

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 46454

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0594/2020/NS
Date	:	24-Aug-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Wang Wen
Address	:	111 Clementi Road #09-01 Singapore 129792
Telephone	:	Office +65 96485908
Type of Claim	:	Own Damage Claims
Policy No.	:	2070044058
Vehicle No	:	SMS 8919 T
Model Code	:	Audi Q2 1.0 TFSI S TRONIC
Model / Year	:	Mar-20
Engine No	:	CHZ C32587
Chassis No	:	WAUZZZGA9KA082224
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	21-Aug-20
Place of Accident	:	Exit Of AYE At Jalan Boon Lay Crossing

Premium Automobiles

55 Ulu Road 1, Singapore 408699
Tel: 6366 2325 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMS 8919 T

S/N	Nature of Jobs	Estimated Charges	Survivor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 280.00	X
2	To remove and transfer lhs headlight control unit and power modules.	S/N \$ 400.00	250 ✓
3	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 3,200.00	1500 ✓
4	To respray front bumper, lhs front fender and bonnet.	\$ 3,400.00	1650 ✓
5	To carry out diagnostic check.	S/N \$ 384.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 7,664.00	

Premium Automobiles

55-06, Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMS 8919 T

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
1	FRONT BUMPER <i>Repair</i>	\$ 1,854.00	*
2	FRONT BUMPER FIXING PARTS	\$ 343.00	*
3	FRONT BUMPER GRILLE - CENTRE	\$ 195.00	*
4	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 167.00	*
5	FRONT BUMPER END CAP - LH	\$ 34.00	*
6	FRONT BUMPER SPOILER	\$ 296.00	*
7	FRONT BUMPER CLOSING ELEMENT	\$ 154.00	*
8	WHEEL SPOILER - LH	\$ 34.00	*
9	FRONT BUMPER ADAPTER - LH	\$ 35.00	*
10	RADIATOR GRILLE <i>at</i>	\$ 1,395.00	1116
11	RADIATOR GRILLE STRIKER PLATE <i>the m</i>	\$ 123.00	*
12	FRONT BUMPER CARRIER <i>not nec</i>	\$ 679.00	+
13	FRONT BUMPER FOAM FILLER PIECE <i>mem</i>	\$ 77.00	+
14	FOAM FILLER PIECE COVER <i>cut</i>	\$ 99.00	79.04
15	FRONT BUMPER GUIDE SECTION - LH	\$ 35.00	*
16	CAUTION SIGN STICKER <i>?</i>	NEC \$ 14.00	10.80
17	AIRCON STICKER <i>?</i>	NEC \$ 8.00	5.68
18	FRONT FENDER - LH <i>Dented</i>	\$ 1,134.00	907.20
19	FRONT FENDER ATTACHMENT PARTS <i>? X mem</i>	\$ 40.00	*
20	FRONT FENDER BRACKET - LH <i>? X mem</i>	\$ 16.00	*
SUB TOTAL SPARE PARTS CHARGES		:	\$ 6,732.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6396 2323 Fax: 6541 1183

Telefax

Material List for Accident Vehicle Regn No. SMS 8919 T

S/N	Parts Description	Damage Parts & Prices		REMARKS
		S/NETT		
21	FRONT FENDER BRACKET - LH ?X	\$	47.00	+
22	FRONT FENDER BRACKET - LH ?X	\$	16.00	+
23	FRONT FENDER BRACE - LH ?X	\$	37.00	+
24	FRONT FENDER BRACKET ?X	\$	23.00	+
25	WHEEL HOUSING LINER - LH Not n	\$	194.00	+
26	WHEEL HOUSING LINER ATTACHMENT PARTS Not n	\$	57.00	+
27	BONNET Dented	\$	2,757.00	✓ 2205.60
28	BONNET ATTACHMENT PARTS ?	\$	163.00	+
29	BONNET STRIKER - LH Not n	\$	109.00	+
30	BONNET IMPACT PROTECTION - CENTRE/ LH / RH Not n 3	\$	90.00	✓ 70.48
31	BONNET LID LOCK Not n	\$	212.00	+
32	HEADLIGHT MOUNTING - LH Not n	\$	117.00	+
33	HEADLIGHT - LH CAMEBACK	\$	4,859.00	✓ 3887.20
34	LED WITH HEAT SINK - LH ?X Not n	\$	725.00	+
35	MAIN LIGHT ELECTRONICS POWER MODULE - LH ?X Not n	\$	749.00	+
36	LIGHT CONTROL SYSTEM CONTROL UNIT ?X Not n	\$	551.00	+
37	HEADLAMP REPAIR KIT Not n	\$	64.00	+
38	HEADLIGHT - HOSE Not n	\$	29.00	+
39	HEADLIGHT COMPENSATING PIECE Not n	\$	45.00	+
40	LIFT SYLINER - LH	\$	141.00	+
41	LIFT SYLINDER HOSE Not n	\$	175.00	+
42	FRONT WHEEL COVER - LH / RH Not n 2	\$	636.00	✓ 508.80
43	FRONT NO PLATE Not n	S/N \$	60.00	✓ 60
44	SUNDRIES Not n	\$	300.00	✓ 15.36
TOTAL SPARE PARTS CHARGES		:	\$ 18,888.00	
TOTAL LABOUR CHARGES		:	\$ 7,664.00	
GRAND TOTAL		:	\$ 26,552.00	

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name : *Adrian L.*
Surveyed Date : *24/08/20*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 28 Days,*
06 Days.
SLP.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant