

Mon 31/08 @ 10am

SDQ3396B

S&R.

Dealer

Performance Motors Limited

Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

21 AUG 2020

Estimate No. : b1 55823
Date Estimated : 21/08/2020
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Woo Wai Chee
6 Jalan Bangket

Singapore 588951

- ACCOUNT - 40000

Cash Sales - Service
Singapore

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|---------|---------|
| SDQ3396B | WBA3A12080J721297 | 25/09/2013 | 316iA/4 | 0 |

DESCRIPTION

To replace front bumper, front right fender, bonnet, front air duct, cross link, right headlight inner support including to knock out dented area caused by the accident

To respray front bumper, front right fender and bonnet

To carry out body cavity preservation (2X)

To replace right headlight.

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

To supply front emboss number plate. 3t

Sundries

Sundries

VALUE

3400 2880 4280.00

2898 3221.00

200 236.00

408 481.00

150 177.00

83.00

80.00

? 150.00

Total Labour 1: 8,678.00

DESCRIPTION

| DESCRIPTION | QTY | PRIC | VALUE |
|---|-----|----------|----------|
| BONNET 5t | 1 | 1,281.20 | 1,281.20 |
| # FRT LH SIDE PANEL repair | 1 | 702.65 | 702.65 |
| EXPANDING RIVET ? x 4 | 10 | 0.50 | 5.00 |
| Flap (Tow Hook) ? x 1 | 1 | 107.95 | 107.95 |
| FRT RH TOP SUPPORT SIDE PANEL ? x 5 | 1 | 20.10 | 20.10 |
| FRONT SHOCK ABSORBER ? cm | 1 | 54.55 | 54.55 |
| FRT BUMPER TOP MOUNT ? x 1 | 1 | 380.00 | 380.00 |
| INSERT AIR INTAKE CENTER ? x 1 | 1 | 125.70 | 125.70 |
| FINISHER ROD CENTER (SPORT) ? x 1 | 1 | 42.90 | 42.90 |
| FRT RH BOTTOM MOUNTING SIDE PANEL ? x 1 | 1 | 20.10 | 20.10 |
| # FRT BUMPER PANEL TRIM (LINES de | 1 | 1,037.05 | 1,037.05 |
| # FINISHER ROD RH (SPORT) ? x 1 | 1 | 23.05 | 23.05 |
| SUPPORT CENTRAL ? x 1 | 1 | 11.40 | 11.40 |

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 5

Estimate No. : b1 55823
Date Estimated : 21/08/2020
Prepared By : Han Kwan Yong

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|---------|---------|
| SDQ3396B | WBA3A12080J721297 | 25/09/2013 | 316iA/4 | 0 |

| DESCRIPTION | QTY | PRIC | VALUE |
|-------------------------------------|-----|----------|----------|
| MOUNT FOR SUPPORT ?kan | 1 | 7.05 | 7.05 |
| # CLOSED GRID RH (LINES SPORT) ?kan | 1 | 90.50 | 90.50 |
| FRT LH GRILLE (SPORT) ca/ | 1 | 128.60 | 128.60 |
| FRT RH GRILLE (SPORT) ca/ | 1 | 128.60 | 128.60 |
| LICENCE PLATE BASE (ECE) de/ | 1 | 69.60 | 69.60 |
| INSCRIPTION SIDE (SPORT LINE) re/ | 1 | 46.55 | 46.55 |
| GROMMET xan | 2 | 0.80 | 1.60 |
| LH LOWER PART OF HOOK LOCK ?xan | 1 | 88.40 | 88.40 |
| RH LOWER PART OF HOOK LOCK ?xan | 1 | 88.40 | 88.40 |
| BONNET CATCH BRACKET ?xan | 2 | 26.40 | 52.80 |
| FRONT PANEL V STRUT ?xan | 1 | 112.75 | 112.75 |
| RH SUPPORT ?bt/ | 1 | 132.15 | 132.15 |
| RH HEADLIGHT BRACKET ?bt/ | 1 | 10.40 | 10.40 |
| FRONT CROSSLINK ?bt/ | 1 | 169.10 | 169.10 |
| # AIR DUCT RADIATOR ?ca/ | 1 | 105.35 | 105.35 |
| FRONT ENGINE HOOD SEALING xan | 1 | 39.05 | 39.05 |
| PLAQUE 82MM re/ | 1 | 71.60 | 71.60 |
| RH HEADLIGHT (XENON) ca/ | 1 | 2,130.35 | 2,130.35 |

Total Parts : 7,284.50

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 31/08/2020 P1520 Excess S\$ _____
Surveyor's Name PASUL Sign _____
Surveyor's Tel 9006068 Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____
Surveyor's E-mail _____
No. of Working Days Recommend 5 & 4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



| | | |
|----------------|---|-----------|
| Labour 1 | : | 8,678.00 |
| Parts | : | 7,284.50 |
| Labour 2 | : | 0.00 |
| Excess | : | 0.00 |
| Total GST @ 7% | : | 1,117.38 |
| Grand Total | : | 17,079.88 |

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 55823**
Date Estimated : **21/08/2020**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -
Woo Wai Chee
6 Jalan Bangket

Singapore 588951

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

| | | | | |
|-----------------|------------------------|-------------------|----------------|----------|
| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
| SDQ3396B | WBA3A12080J7212 | 25/09/2013 | 316iA/4 | 0 |

| DESCRIPTION | ORIGINAL PRICE | DISC. % | NETT |
|-------------|----------------|---------|------|
|-------------|----------------|---------|------|

| DESCRIPTION | UNIT PRICE | QTY | DISC. % | NETT |
|--|------------|------|---------|----------|
| # BLIND RIVET nec | 1.60 | 4.00 | 0.00 | 6.40 |
| # BLIND RIVET FLAT HEADED 6.5X14.3 nec | 4.50 | 4.00 | 0.00 | 18.00 |
| # FRT RH 2 SIDE PANEL BRACKET nec | 35.10 | 1.00 | 0.00 | 35.10 |
| # FRT BUMPER PANEL TRIM (LINES SRA) in estimate x | 1,037.05 | 1.00 | 0.00 | 1,037.05 |
| # AIR DUCT RADIATOR in estimate x | 105.35 | 1.00 | 0.00 | 105.35 |

REP
REP

SUPPLEMENTARY ITEMS

Total Labour :

Total Parts :

1,201.90