

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 46212

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0587/2020/NS
Date : 20-Aug-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Chong Wee Tek
Address : 62 Clover Avenue
Singapore 579345
Telephone : HP +65 93864465
Type of Claim : Own Damage Claim
Policy No. : 1800148014
Vehicle No : **SBB 60 S**
Model Code : Audi RS 4 Avant 2.9 TFSI
Model / Year : Dec-18
Engine No : DEC 011856
Chassis No : WAUZZZF43KA900077
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 20-Aug-20
Place of Accident : Upper Thomson Rd And Ang mo Kio Ave 1 Intersection

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SBB 60 S

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	✓
2	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00 500 ✓	✓
3	To respray front bumper and bonnet. ✓ ✓	\$ 2,000.00 1100 ✓	✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: <u>\$ 3,722.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBB 60 S

S/N Parts Description		Damage Parts & Prices		Remarks
S/N	Parts Description	S/Nett		
1	FRONT BUMPER <i>Repair</i>	\$	5,654.00	X
2	FRONT BUMPER SECURING STRIP <i>new</i>	2 \$	70.00	X
3	FRONT BUMPER AIR GUIDE - LH / RH	2 \$	332.00	X
4	FRONT BUMPER SPOILER - UPPER	\$	606.00	X
5	FRONT BUMPER GRILLE - CENTRE	\$	714.00	X
6	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$	346.00	X
7	FRONT BUMPER SPOILER	\$	701.00	X
8	FRONT BUMPER SPOILER - LOWER	\$	846.00	X
9	FRONT BUMPER SPOILER - LH / RH	2 \$	1,336.00	X
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2 \$	1,454.00	X
11	RADIATOR AIR GUIDE - LH	\$	74.00	X
12	RADIATOR AIR GUIDE - LH / RH	2 \$	446.00	X
13	RADIATOR GRILLE <i>cracked</i>	\$	4,125.00	✓ 3300
14	RS4 INSCRIPTION <i>new</i>	\$	122.00	✓ 97.6
15	RADIATOR COVER CAP	\$ NN	209.00	X NN
16	RADIATOR GRILLE COVER - UPPER	\$	153.00	X NN
17	FRONT BUMPER COVER - LOWER <i>new</i>	deformed \$	211.00	✓ 168.4
18	LICENSE PLATE HOLDER <i>deformed</i>	\$	614.00	✓ 491.2
19	FRONT PARKING AID SENSOR - INNER <i>new</i>	2	TBC	X
20	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	\$	294.00	X
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$ 18,307.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBB 60 S

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	FRONT BUMPER CARRIER <i>New</i>	\$ 795.00	X
22	FRONT BUMPER COVER <i>Defect New</i>	\$ 240.00	X
23	CAUTION SIGN STICKER } <i>New</i>	NEC \$ 14.00	X
24	AIRCON STICKER	NEC \$ 8.00	X
25	LOCK CARRIER BRACKET <i>New</i>	\$ 241.00	X 192.8 CRA
26	FRONT BUMPER SUPPORT - LH / RH <i>New</i>	2 \$ 56.00	X
27	IMPACT PROTECTION - CENTRE } <i>New</i>	\$ 27.00	X
28	IMPACT PROTECTION - LH	\$ 28.00	X
29	IMPACT PROTECTION - RH	\$ 27.00	X
30	FRONT NO PLATE <i>Dented</i>	S/N \$ 80.00	✓ 80
31	SUNDRIES ?	\$ 200.00	? 2.24 NEC
TOTAL SPARE PARTS CHARGES		: \$ 20,023.00	
TOTAL LABOUR CHARGES		: \$ 3,722.00	
GRAND TOTAL		: \$ 23,745.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel 6366 2323 Fax 6841 1183

Telefax

Name : Adam Li
Surveyed Date : 25/08/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 4days ✓

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant