

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 46212

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0587/2020/NS
Date : 20-Aug-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Denise,

4 days - ok - Jy - 30 Nov 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Chong Wee Tek
Address : 62 Clover Avenue
Singapore 579345
Telephone : HP +65 93864465
Type of Claim : Own Damage Claim
Policy No. : 1800148014
Vehicle No : **SBB 60 S**
Model Code : Audi RS 4 Avant 2.9 TFSI
Model / Year : Dec-18
Engine No : DEC 011856
Chassis No : WAUZZZF43KA900077
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 20-Aug-20
Place of Accident : Upper Thomson Rd And Ang mo Kio Ave 1 Intersection

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SBB 60 S

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	\$ 480.00
2	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.	\$	1,050.00	\$ 500.00
3	To respray front bumper and bonnet.	\$	2,000.00	\$ 1,100.00
4	Supplementary	\$	400.00	\$ 250.00
5	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 4,122.00	\$ 2,522.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBB 60 S

S/N Parts Description		<u>Damage Parts & Prices</u>	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 5,654.00	
2	FRONT BUMPER SECURING STRIP	2 \$ 70.00	
3	FRONT BUMPER AIR UIDE - LH / RH	2 \$ 332.00	
4	FRONT BUMPER SPOILER - UPPER	\$ 606.00	
5	FRONT BUMPER GRILLE - CENTRE	\$ 714.00	
6	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 346.00	
7	FRONT BUMPER SPOILER	\$ 701.00	
8	FRONT BUMPER SPOILER - LOWER	\$ 846.00	
9	FROT BUMPER SPOILER - LH / RH	2 \$ 1,336.00	
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 1,454.00	
11	RADIATOR AIR GUIDE - LH	\$ 74.00	
12	RADIATOR AIR GUIDE - LH / RH	2 \$ 446.00	
13	RADIATOR GRILLE	\$ 4,125.00	\$ 3,300.00
14	RS4 INSCRIPTION	\$ 122.00	\$ 97.60
15	RADIATOR COVER CAP	\$ 209.00	
16	RADIATOR GRILLE COVER - UPPER	\$ 153.00	
17	FRONT BUMPER COVER - LOWER	\$ 211.00	\$ 168.40
18	LICENSE PLATE HOLDER	\$ 614.00	\$ 491.20
19	FRONT PARKING AID SENSOR - INNER	2 TBC	
20	FRONT BUMPER FOAM FILLER PIECE	\$ 294.00	
SUB TOTAL SPARE PARTS CHARGES		: \$ 18,307.00	\$ 4,057.20

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBB 60 S

S/N	Parts Description		Damage Parts & Prices		
			S/Nett	Remarks	
		<i>c/f</i>		\$	4,057.20
21	FRONT BUMPER CARRIER		\$ 795.00		
22	FRONT BUMPER COVER		\$ 240.00		
23	CAUTION SIGN STICKER	NEC	\$ 14.00		
24	AIRCON STICKER	NEC	\$ 8.00		
25	LOCK CARRIER BRACKET		\$ 241.00	\$	192.80
26	FRONT BUMPER SUPPORT - LH / RH	2	\$ 56.00		
27	IMPACT PROTECTION - CENTRE		\$ 27.00		
28	IMPACT PROTECTION - LH		\$ 28.00		
29	IMPACT PROTECTION - RH		\$ 27.00		
30	FRONT NO PLATE	S/N	\$ 80.00	\$	80.00
31	SUPPLEMENTARY		\$ 30.00	\$	24.00
32	SUPPLEMENTARY		\$ 7,693.00	\$	6,154.40
33	SUNDRIES		\$ 200.00	\$	2.24
TOTAL SPARE PARTS CHARGES		:	\$ 27,746.00	\$	10,510.64
TOTAL LABOUR CHARGES		:	\$ 4,122.00	\$	2,522.00
GRAND TOTAL		:	\$ 31,868.00	\$	13,032.64

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.