



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0587/2020/NS 5-Oct-20 Glory Tan 1 OF 1 SBB 60 S Audi RS 4 Avant 2.9 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	Headlight LHS CRACKED	\$ 7,693.00	\$ 6,154.40	
<u>Labours</u>				
1	To remove and transfer lhs headlight control unit and power module.	s/n \$ 400.00	\$ 250.00	✓
TOTAL		\$ 8,093.00	\$ 6,404.40	

For Premium Automobiles Pte Ltd

 Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0587/2020/NS 5-Oct-20 Glory Tan 1 OF 1 SBB 60 S Audi RS 4 Avant 2.9 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u> 1	Radiator air guide upper LHS DAMAGED	\$ 30.00	\$ 24.00	
TOTAL		\$ 30.00	\$ 24.00	

For Premium Automobiles Pte Ltd

 Authorised Signature