



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2101521

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 10/03/2021
Reference CC6/CTI20008870/Uea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. YL 9292E
Insured Veh. GBE 1051X
Claim No. SNM20D203041
Policy No. DMCVSN1655931903
Accident Date 22/08/2020
Inspection Date 24/08/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI20008870/Uea3q2	
			Date: 10/03/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 1051X	Veh. Inspected	YL 9292E	
Policy No.	DMCVSN1655931903	Coverage (\$)	0.00	
Claim No.	SNM20D203041	Excess (\$)	0.00	
Assign From		Assign Date	24/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	HINO XZU700R	c.c	4009	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JHHTCS3H20K002917	Colour	WHITE	
Odometer	259285 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	7.00 R16	OHTSU	6 mm	
L/H Front Tyre	7.00 R16	OHTSU	6 mm	
R/H Rear Tyre	7.00 R16 (D)	OHTSU	6/6 mm	
L/H Rear Tyre	7.00 R16 (D)	OHTSU	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/08/2020	Inspection Date	24/08/2020	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			15 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YL 9292E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DISTORTED	1,414.46	1,005.20
1	FRONT BUMPER BRACKET N/S	BENT	457.97	342.90
1	FRONT BUMPER FOG LAMP N/S	CRACKED	450.50	350.90
1	FRONT BUMPER FOG LAMP COVER N/S	CRACKED	78.20	78.20
1	FRONT GRILLE	BROKEN	1,520.00	1,250.00
1	FRONT GRILLE LOGO	MISSING	108.15	108.15
1	FRONT PANEL	BADLY DENTED	2,820.15	1,324.70
1	FRONT PANEL INNER	TO REPAIR SEE LABOUR	1,515.00	-
1	FRONT PANEL 'HINO' STICKER	NECESSARY	66.45	66.45
1	FRONT PANEL '300' STICKER	NECESSARY	80.00	66.45
1	FRONT CORNER PANEL N/S	DISTORTED	799.65	647.80
1	FRONT WINDSCREEN	BROKEN	1,800.15	1,534.20
1	FRONT WINDSCREEN RUBBER	TWISTED	399.00	299.00
1	FRONT WIPER ARM N/S	BENT	345.00	215.00
1	FRONT WIPER BLADE N/S	BENT	108.00	108.00
1	FRONT WIPER LINKAGE	TWISTED / JAMMED	545.90	411.50
1	FRONT WIPER MOTOR	SHORTED	820.15	665.20
2	HEADLAMPS @ \$1280.00	CRACKED / BROKEN	2,560.00	2,301.20
1	HEADLAMP LOWER RUBBER N/S	TORN	35.00	35.00
1	FRONT CABIN CENTRE CROSS MEMBER W/BACKET ASSY	BENT / TWISTED	2,450.00	1,650.00
1	AIR CON CONDENSER	TWISTED	1,880.00	1,550.20
1	AIR CON CONDENSER BRACKET	TO REPAIR SEE LABOUR	650.00	-
1	AIR CON CONDENSER FAN ASSY	CRACKED / JAMMED	885.00	681.00
1	AIR CON LIQUID PIPE	BENT	399.00	235.00
1	AIR CON DISCHARGE HOSE	BENT	618.45	485.00
1	AIR CON SUCTION HOSE	BENT	566.15	499.00
1	FRONT DOOR N/S	BUCKLED	2,200.15	1,980.00
1	FRONT DOOR CHECKER N/S	TWISTED	182.00	166.00

Report Ref No. CC6/CTI20008870/Uea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT DOOR HINGES @ \$165.00	BENT	330.00	290.00
1	FRONT DOOR INNER RUBBER N/S	TWISTED	482.15	322.10
1	FRONT DOOR INNER LOWER RUBBER N/S	TORN	188.30	166.50
1	FRONT DOOR INNER LOCK N/S	DENTED / JAMMED	615.00	450.50
1	FRONT DOOR INNER TRIM BOARD N/S	DISTORTED	922.35	815.00
1	FRONT DOOR GLASS N/S	SHATTERED	850.15	680.00
1	FRONT DOOR GLASS REGULATOR N/S	BENT	480.35	322.50
1	FRONT DOOR GLASS REGULATOR MOTOR N/S	JAMMED	600.15	490.00
1	FRONT DOOR GLASS OUTER MOULDING N/S	DISTORTED	311.00	225.10
1	FRONT DOOR '616' STICKER N/S	NECESSARY	85.00	85.00
1	FRONT DOOR OUTER TOP SIDE GARNISH N/S	MISSING	105.00	105.00
1	FRONT DOOR REAR PILLAR OUTER N/S	BADLY DENTED	990.15	850.15
1	FRONT DOOR VIEW MIRROR N/S	BROKEN	299.00	185.00
1	FRONT DOOR VIEW MIRROR BRACKET N/S	BENT	665.15	420.15
1	FRONT DOOR VIEW MIRROR BRACKET MOTOR N/S	NO SUCH PARTS	850.00	-
1	FRONT DOOR VIEW ROUND MIRROR N/S	BROKEN	125.00	125.00
1	FRONT DOOR OUTER PILLAR N/S	BADLY DENTED	1,665.15	1,215.00
1	FRONT DOOR INNER PILLAR N/S	BADLY DENTED	1,415.15	1,005.00
1	FRONT DOOR INNER PILLAR GARNISH N/S	TWISTED	360.80	185.00
1	FRONT DOOR CHANNEL STRIP N/S	TWISTED	411.20	366.50
1	FRONT STEP GARNISH N/S	BROKEN	405.80	299.00
1	FRONT WHEEL ARCH PANEL N/S	BUCKLED	688.90	485.00
1	FRONT WHEEL ARCH PANEL TOP GARNISH N/S	DISTORTED	299.90	184.50
1	FRONT FLOOR PANEL	TO REPAIR SEE LABOUR	2,015.00	-
1	FRONT WIPER PANEL INNER	BADLY DENTED	825.15	615.10
1	AIR CON BLOWER ASSY	CRACKED	2,800.15	2,150.00
1	AIR CON HEATER ASSY	CRACKED	3,200.15	2,600.00
1	ELECTRIC VEHICLE CONTROL UNIT	DENTED / SHORTED	2,550.00	2,200.00
1	INJECTOR CONTROL UNIT	CRACKED	1,850.00	1,150.00
1	ROOF PANEL	DENTED / BUCKLED	3,800.15	2,205.15
1	ROOF LINING	WARPED	1,900.00	1,445.25

Report Ref No. CC6/CTI20008870/Uea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DASHBOARD UPPER	DISTORTED	1,866.15	1,125.35
1	FRONT DASHBOARD LOWER N/S	CRACKED	880.15	485.30
1	FRONT DASHOARD INNER REINFORCEMENT	BENT	1,100.15	820.00
1	FRONT DASHBOARD CONSOLE BOX N/S	NOT NECESSARY	488.90	-
1	METER ASSY	CRACKED	2,450.00	1,600.00
1	AIR DUCT	DISTORTED	354.00	182.00
1	WIRE HARNESS ASSY	TO REPAIR SEE LABOUR	2,650.00	-
1	CABIN LOCK BRACKET	TO REPAIR SEE LABOUR	485.25	-
1	FRONT DOOR O/S	TO REPAIR SEE LABOUR	2,200.25	-
1	FRONT DOOR OUTER PANEL O/S	TO REPAIR SEE LABOUR	1,665.15	-
1	WASHER TANK	DEFORMED	312.00	245.00
1	ENGINE CONTROL UNIT	CRACKED / SHORTED	2,150.00	1,850.00
	LESS 10% DISCOUNT		-	-4,600.12
			74,442.73	41,401.08
	<u>SPECIAL NETT ITEMS</u>			
1	REAR FREEZER BOX DOOR N/S (SN)	TO REPAIR SEE LABOUR	1,500.00	-
1	REAR FREEZER BOX DOOR O/S (SN)	TO REPAIR SEE LABOUR	1,500.00	-
2	REAR FREEZER BOX LOCK BARS @ \$450.00 (SN)	TO REPAIR SEE LABOUR	900.00	-
1	REAR SAFETY BUMPER (SN)	NOT NECESSARY	1,200.00	-
1	SET FRONT PANEL 'CORPORATE' STICKER (SN)	NECESSARY	380.00	250.00
1	SET FRONT DOOR 'CORPORATE' STICKER N/S (SN)	NECESSARY	380.00	300.00
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	50.00	40.00
1	SET ROOF LINING CLIPS (SN)	NECESSARY	50.00	50.00
1	ERP BRACKET (SN)	NECESSARY	20.00	20.00
			5,980.00	660.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00

Report Ref No. CC6/CTI20008870/Uea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE & REPLACED FRONT WINDSCREEN.	NOT NECESSARY	150.00	100.00
	TO DISMANTLE & REPLACED FRONT DASHBOARD.		380.00	200.00
	TO DISMANTLE & REPLACED ROOF LINING.		300.00	150.00
	TO DISMANTLE & REPLACED FRONT DOOR MECHANISM.		100.00	60.00
	TO REFILL AIR CON GAS.		20.00	20.00
	TO SPRAY RUST PROOFING.		200.00	120.00
	TO STRAIGHTEN & REALIGN CHASSIS MEMBER.		1,000.00	-
	TO RESET & REPROGRAMME SYSTEM.		300.00	100.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT PANEL INNER, AIR CON CONDENSER BRACKET, FRONT FLOOR PANEL, WIRE HARNESS ASSY, CABIN LOCK BRACKET, FRONT DOOR O/S, FRONT DOOR OUTER PANEL O/S, REAR FREEZER BOX DOOR N/S, REAR FREEZER BOX DOOR O/S AND REAR FREEZER BOX LOCK BARS .		4,500.00	2,400.00
	TO PUTTY & SPRAY PAINTING.		2,800.00	1,800.00
			9,830.00	4,980.00
GRAND TOTAL			90,252.73	47,041.08
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				35,000.00

Report Ref No. CC6/CTI20008870/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YL 9292E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YL 9292E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YL 9292E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YL 9292E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

