

ASSIGNMENT

From: Date:
Estimated Cost:
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: YL 9292 E
at Workshop m/s Rf.
of
Insured: GBE 1251 X
Policy No.
Claims No.
Sum Insured: Excess:
(Client's Record)
Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 43k.
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 15 days Res.: Yes or No
Lum Sum: 25 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 3562

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: YL 9292 E Yr Regn: 25/12/15
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or (M) (Refrigerated)
Make: HINO X2U700R c.c 4009
Colour White A/C: Insured / Std / NI / NA
Sp. Reading 25928K T/Radio: Insured / Std / NI / NA
Eng/No:
C/No: JHHTCS3H20K002917
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 7.00 R 16
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or OHTSU

Front	Rear
R/Bal. 6 mm	R/Bal. 6/6 mm
L/Bal. 6 mm	L/Bal. 6/6 mm
D.O.A. 24/8/20	D.O.I. 24/8/20

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/5/14 4.45 AM Rep 8100
net 39438

29/9/20 4/5 @ 35.000 Confirmed with Alu.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

) S + RS. SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I.: (\$)

TOTAL

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6 #01-48
SINGAPORE 417883

date: ASher

not Authorized
nku
24/8/20
2/5 = 35.000/
15 days.

VEHICLE No: YL 9292E

1PC	FRONT BUMPER	1005.20	D/S	\$1,414.46	✓
1PC	FRONT BUMPER BRACKET N/S	342.90	Bent	\$457.97	✓
1PC	FRONT BUMPER FOG LAMP N/S	350.90	CNE	\$450.50	✓
1PC	FRONT BUMPER FOG LAMP COVER N/S		CNE	\$78.20	✓
1PC	FRONT GRILLE	1250.00	SRO	\$1,520.00	✓
1PC	FRONT GRILLE LOGO		M.S	\$108.15	✓
1PC	FRONT PANEL	1324.70	Body	\$2,820.15	✓
1PC	FRONT PANEL INNER		N	\$1,515.00	X
1PC	FRONT PANEL 'HINO' STICKER		NA	\$66.45	✓
1PC	FRONT PANEL '300' STICKER	66.45	NA	\$80.00	✓
1PC	FRONT CORNER PANEL N/S	647.86	D/S	\$799.65	✓
1PC	FRONT WINDSCREEN	1534.20	SRO	\$1,800.15	✓
1PC	FRONT WINDSCREEN RUBBER	299.00	twi	\$399.00	✓
1PC	FRONT WIPER ARM N/S	215.00	Bent	\$345.00	✓
1PC	FRONT WIPER BLADE N/S		Bent	\$108.00	✓
1PC	FRONT WIPER LINKAGE	411.50	twi/Jun	\$545.90	✓
1PC	FRONT WIPER MOTOR	665.20	shubb	\$820.15	✓
2PCS	HEADLAMPS @\$1280.00	1150.60 x 2 = 2301.20	CNE/SRO	\$2,560.00	✓
1PC	HEADLAMP LOWER RUBBER N/S		To in	\$35.00	✓
1PC	FRONT CABIN CENTRE CROSS MEMBER W/BACKET ASSY	1650.00	Bent/twi	\$2,450.00	✓
1PC	AIR CON CONDENSER	1550.20	twi	\$1,880.00	✓
1PC	AIR CON CONDENSER BRACKET		N	\$650.00	X
1PC	AIR CON CONDENSER FAN ASSY	681.00	CNE/Jun	\$885.00	✓
1PC	AIR CON LIQUID PIPE	235.00	Bent	\$399.00	✓
1PC	AIR CON DISCHARGE HOSE	485.00	Bent	\$618.45	✓
1PC	AIR CON SUCTION hose	499.00	Bent	\$566.15	✓
1PC	FRONT DOOR N/S	1980.00	Bent	\$2,200.15	✓
1PC	FRONT DOOR CHECKER N/S	166.00	twi	\$182.00	✓
2PCS	FRONT DOOR HINGES @\$165.00	145 x 2 = 290	Bent	\$330.00	✓
1PC	FRONT DOOR INNER RUBBER N/S	322.10	twi	\$482.15	✓
1PC	FRONT DOOR INNER LOWER RUBBER N/S	166.50	To in	\$188.30	✓
1PC	FRONT DOOR INNER LOCK N/S	450.50	twi/Jun	\$615.00	✓
1PC	FRONT DOOR INNER TRIM BOARD N/S	815.00	D/S	\$922.35	✓
1PC	FRONT DOOR GLASS N/S	680.00	shubb	\$850.15	✓
1PC	FRONT DOOR GLASS REGULATOR N/S	322.50	Bent	\$480.35	✓
1PC	FRONT DOOR GLASS REGULATOR MOTOR N/S	490.00	Jm	\$600.15	✓
1PC	FRONT DOOR GLASS OUTER MOULDING N/S	225.10	D/S	\$311.00	✓
1PC	FRONT DOOR '616' STICKER N/S		NA	\$85.00	✓
1PC	FRONT DOOR OUTER TOP SIDE GARNISH N/S		M.S	\$105.00	✓
1PC	FRONT DOOR REAR PILLAR OUTER N/S	850.15	Body	\$990.15	✓
1PC	FRONT DOOR VIEW MIRROR N/S	185.00	SRO	\$299.00	✓
1PC	FRONT DOOR VIEW MIRROR BRACKET N/S	420.15	Bent	\$665.15	✓
1PC	FRONT DOOR VIEW MIRROR BRACKET MOTOR N/S		N/S	\$850.00	X
1PC	FRONT DOOR VIEW ROUND MIRROR N/S		SRO	\$125.00	✓

104

23588.11

1PC	FRONT DOOR OUTER PILLAR N/S	1215.00
1PC	FRONT DOOR INNER PILLAR N/S	1005.00
1PC	FRONT DOOR INNER PILLAR GARNISH N/S	185.00
1PC	FRONT DOOR CHANNEL STRIP N/S	366.50
1PC	FRONT STEP GARNISH N/S	299.00
1PC	FRONT WHEEL ARCH PANEL N/S	485.00
1PC	FRONT WHEEL ARCH PANEL TOP GARNISH N/S	184.50
1PC	FRONT FLOOR PANEL	
1PC	FRONT WIPER PANEL INNER	615.10
1PC	AIR CON BLOWER ASSY	2150.00
1PC	AIR CON HEATER ASSY	2600.00
1PC	ELECTRIC VEHICLE CONTROL UNIT	2200.00
1PC	INJECTOR CONTROL UNIT	1150.00
1PC	ROOF PANEL	2205.15
1PC	ROOF LINING	1445.25
1PC	FRONT DASHBOARD UPPER	1125.35
1PC	FRONT DASHBOARD LOWER N/S	485.30
1PC	FRONT DASHBOARD INNER REINFORCEMENT	820.00
1PC	FRONT DASHBOARD CONSOLE BOX N/S	
1PC	METER ASSY	1600.00
1PC	AIR DUCT	182.00
1PC	WIRE HARNESS ASSY	
1PC	CABIN LOCK BRACKET	
1PC	FRONT DOOR O/S	
1PC	FRONT DOOR OUTER PILLAR O/S	
1PC	WASHER TANK	245.00
1PC	ENGINE CONTROL UNIT	1850.00

body	\$1,665.15	✓
body	\$1,415.15	✓
tw	\$360.80	✓
tw	\$411.20	✓
SD	\$405.80	✓
Buc	\$688.90	✓
Dis	\$299.90	✓
R	\$2,015.00	X
body	\$825.15	✓
CNA	\$2,800.15	✓
CNE	\$3,200.15	✓
wo/shuttl	\$2,550.00	✓
CNE	\$1,850.00	✓
wo/suc	\$3,800.15	✓
negat	\$1,900.00	✓
D.S	\$1,866.15	✓
CNE	\$880.15	✓
Seaf	\$1,100.15	✓
nn	\$488.90	X
CNE	\$2,450.00	✓
Dis	\$354.00	✓
R	\$2,650.00	X
R	\$485.25	X
R	\$2,200.25	X
R	\$1,665.15	X
De	\$312.00	✓
CNE/shuttl	\$2,150.00	✓
	\$74,442.73	

46001.26

102
44601.36

S.NETT	
1PC	REAR FREEZER BOX DOOR N/S
1PC	REAR FREEZER BOX DOOR O/S
2PCS	REAR FREEZER BOX LOCK BARS @\$450.00
1PC	REAR SAFETY BUMPER
1SET	FRONT PANEL 'CORPORATE' STICKER
1SET	FRONT DOOR 'CORPORATE' STICKER N/S
1SET	FRONT GRILLE CLIPS
1SET	ROOF LINING CLIPS
1PC	ERP BRACKET

R	\$1,500.00	X
R	\$1,500.00	X
R	\$900.00	X
nn	\$1,200.00	X
nn	\$380.00	250
nn	\$380.00	300
nn	\$50.00	40
nn	\$50.00	✓
nn	\$20.00	✓

TO CHECK WIRING	\$80.00	30
TO DISMANTLE & REPLACED FRONT WINDSCREEN	\$150.00	100
TO DISMANTLE & REPLACED FRONT DASHBOARD	\$380.00	200
TO DISMANTLE & REPLACED ROOF LINING	\$300.00	150
TO DISMANTLE & REPLACED FRONT DOOR MECHANISM	\$100.00	60
TO REFILL AIR CON GAS	\$20.00	✓
TO SPRAY RUST PROOFING	\$200.00	120
TO STRAIGHTEN & REALIGN CHASSIS MEMBER	\$1,000.00	X
TO RESET & REPROGRAMME SYSTEM	\$300.00	100
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$4,500.00	2400

TO PUTTY & SPRAY PAINTING

TOTAL \$2,800.00 / 800
\$90,252.73

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

47041-13