

ACR. REC. BY:

Steve

REF:

CS/CTI 20008871/Erfs

ASSIGNMENT

From:

Date:

Estimated Cost:

CP/TP/WS/TP RCS/CD RCS/EVA/INV/IMV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMH 8779M

Yr Regn:

14/2/19

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Atrige

c.c.

1193

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

91620

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MMBSTAT3AJ+1004497

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

11

BS ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

21/8/20

D.O.I.

25/8/20

Survey held at

Ryder

Des. of Damages ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-53K

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Rep. Formed:

Lump Sum / L.E.I. /

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Phone

Others

TOTAL

yder Auto Pte Ltd
2 Kaki Bukit Ave 2, #02-19 Kaki Bukit
Autohub
417921

Insurer Reference: SKN5041U
Repairer Reference: 035376
Date calculated: 24/08/2020 4:34 PM

Full Report
Registration: SMH8779M
Printed: 24/08/2020 4:34 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	San Choon	Currency:	SGD
Claim Reference:	SKN5041U	Date of Incident:	
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle
Manufacturer: MITSUBISHI
Model: ATTRAGE (A13A)
Sub Model: BASE MODEL
Model Sheet Number: 32 AT 01
Registration: SMH8779M
VIN number: MMBSTA13AJH004497
Odometer:
Model Specs
EXHAUST W/CATALYST 1.2 LTR 59KW

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐


Steve (LKK)

with P/L

25/8/20, 11.00 am

P/P, 14 dys

Ry Bel spy



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer
Signature:
Date:

PRINT DATE 24/08/2020

.about

Code	Description	Time Base 10 WU/h		Price = 80.00 SGD/h	
				WU	Price SGD
NO NUMBER	PREPARATION TIME PER JOB			2.0	16.00
514110 00)	RENEW FRONT BUMPER			7.0	56.00
	INCLUDES: R + R NECESSARY ATTACHED PARTS				
514121 10)	R + R FRONT BUMPER ATTACHED PARTS			5.0	40.00
425111 10)	RENEW BONNET			3.0	24.00
	INCLUDES: BONNET AND ATTACHED PARTS R+R,				
	ADJUST BONNET				
NO NUMBER	R + R COWL SEAL			2.0	16.00
425113 00)	R + R L/BONNET HINGE			3.0	24.00
425113 00)	R + R R/BONNET HINGE			3.0	24.00
422022 00)	R + R L/F WING			8.0	64.00
	INCLUDES: R + R HEADLAMP AND WHEELARCH				
	TRIM				
422022 10)	RENEW R/FR WING			8.0	64.00
	INCLUDES: R/HEADLAMP ASSY, WHEELARCH-				
	TRIM RIGHT R + R				
NO NUMBER	ADJUST HEADLAMPS			2.0	16.00
421020 YE)	RENEW FRONT PANEL CPL			17.0	136.00
NO NUMBER	RENEW BOTH REAR OUT SIDE PNL/ END PANEL			244.0	1,952.00
	INCLUDES: REAR END PANEL REINFORCEMENT				
	RENEW				
	BUMPER, TAILGATE,				
	TAILLAMPS, ALL ATTACHED PARTS AND				
	TRIMS IN REPAIR AREA				
	REMOVE AND REFIT				
514221 10	REAR BUMPER (REMOVED) RENEW			5.0	40.00
	INCLUDES: REQUIRED ATTACHED PARTS				
	REMOVE AND REFIT				
NO NUMBER	RENEW L/UPPER SIDE PANEL EXTENSION			10.0	80.00
NO NUMBER	RENEW R/UPPER SIDE PANEL EXTENSION			10.0	80.00
424311 10)	RENEW TAILGATE			5.0	40.00
421030 ZA	RENEW L/R SIDEMEMBER EXTENSION			11.0	88.00
421030 ZA	RENEW R/R SIDEMEMBER EXTENSION			11.0	88.00
NO NUMBER	RENEW BOOT FLOOR PANEL			41.0	328.00
NO NUMBER	REMOVE AND REFIT FUEL TANK CPL			11.0	88.00
145010 00)	R + R RADIATOR CPL			7.0	56.00
NO NUMBER	R + R REAR SILENCER			8.0	64.00
NO NUMBER	R + R EXHAUST PIPE RUBBER/S			4.0	32.00
NN	support panel upper R&R / NEW PARTS			4.0*	X 32.00
NN	bodykit R&R / NEW PARTS			20.0*	10/ 160.00
NN	body kit L & R R&R / NEW PARTS			2.0*	1.0/ 16.00
NN	ventilator cover R&R / NEW PARTS			2.0*	1.0/ 16.00
NN	buzzer R&R / NEW PARTS			2.0*	1.0/ 16.00
NN	antenna R&R / NEW PARTS			2.0*	1.0/ 16.00
NN	spare wheel panel R&R / NEW PARTS			1.0*	/ 8.00
NN	spare wheel board R&R / NEW PARTS			1.0*	/ 8.00
NN	reverse sensor R&R / NEW PARTS			15.0*	4.0/ 120.00
NN	body kit R&R / NEW PARTS			20.0*	10/ 160.00
NN	extension R&R / NEW PARTS			20.0*	15/ 160.00

**Labour Cost
Panel / Mechanical Labour**

Hrs WU
51.60 516.0 4,128.00

Total of Labour

4,128.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description		WU	Price SGD
	BONNET NEW PART PAINTING		17.0	
	R/F WING NEW PART PAINTING		10.0	
	FRONT PANEL CPL SURFACE PAINT		5.0	
	REAR PANEL CPL NEW PART PAINTING		19.0	
	BOOTLID NEW PART PAINTING		13.0	
	L/R OUT QTR PANEL NEW PART PAINTING		19.0	
	R/R OUT QTR PANEL NEW PART PAINTING		19.0	
	L/UPP SIDE PANEL EXT NEW PART PAINTING		9.0	
	R/UPP SIDE PANEL EXT NEW PART PAINTING		9.0	
	REAR FLOOR PANEL SURFACE PAINT		7.0	
	L/SIDE MEMBER EXT SURFACE PAINT		4.0	
	R/SIDE MEMBER EXT SURFACE PAINT		4.0	
	FRONT BUMPER NEW PART PAINT K1R		12.0	
	FRT BUMPER TRIM CAP NEW PART PAINT K1R		3.0	
	REAR BUMPER NEW PART PAINT K1R		10.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	41.51
0742	R/F WING NEW PART PAINTING	15.31
1009	FRONT PANEL CPL SURFACE PAINT	8.10
2711	REAR PANEL CPL NEW PART PAINTING	20.10
2931	BOOTLID NEW PART PAINTING	28.61
3481	L/R OUT QTR PANEL NEW PART PAINTING	19.23
3482	R/R OUT QTR PANEL NEW PART PAINTING	19.23
3577	L/UPP SIDE PANEL EXT NEW PART PAINTING	2.19
3578	R/UPP SIDE PANEL EXT NEW PART PAINTING	2.19
3901	REAR FLOOR PANEL SURFACE PAINT	16.19
4027	L/SIDE MEMBER EXT SURFACE PAINT	0.70
4028	R/SIDE MEMBER EXT SURFACE PAINT	0.70
0283	FRONT BUMPER NEW PART PAINT K1R	49.56
0349	FRT BUMPER TRIM CAP NEW PART PAINT K1R	0.35
2583	REAR BUMPER NEW PART PAINT K1R	42.23

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	80.00 SGD/h		
Time Paint		160.0	
Preparation Main Work Metal	1.70	17.0	136.00
Preparation Comp. Work Plastic	0.30	3.0	24.00
Total	10 WU/h	18.00 180.0	1,440.00

Material Cost - Paint

New Part Painting	148.37
New Part Painting - Plastic K1R	92.14
Surface-/Blend Paint	25.69
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	293.30

Price SGD

148.37

92.14

25.69

18.10

9.00

293.30

Spare Parts

prices as at 2015-06-01

Price SGD

Code	Description	Part Number	Part Source	Price SGD
1011	antenna / BR	Rear	Original	160.20
3021	BADGE MODEL / MC	7415A646	Original	93.80
1004	bodykit	Rear bumper	Original	0.00
1019	body kit	Front	Original	0.00
1006	body kit L & R	Rear bum chrome	Original	0.00
0471	BONNET / DD	5900A623	Original	891.20
0493	BONNET LOCK X	5908A186	Original	280.80
2977	BOOT/TAILGATE LOCK	5927A041 ?	Original	325.60
2944	BOOT/TAILGATE SEAL	5921A017 ?	Original	286.60
2635	BOOT/T-GATE	8341A199 ?	Original	201.50
	MOULDING			
2931	BOOTLID / DD	5920A238	Original	1,076.40
1010	buzzer / BR	Rear	Original	106.60
0494	CLIP FASTENING ? X	MU001908	Original	85.50
4985	END PANEL TRIM ?	7240A172XA	Original	84.50
1020	extension (LH) / DD	Rear chassis	Original	296.40
0283	FRONT BUMPER / BR	6400F244	Original	865.80
0257	FRONT NUMBER PLATE	KNPL3 / BT	Original	45.00
1009	FRONT PANEL CPL X	5256B865	Original	1,298.70
0349	FRT BUMPER TRIM CAP	6400F205BA / CMT	Original	68.60
0258	FRT NO PLATE REINF	KNPL0 / BR	Original	29.00
0415	GRILLE / BR	6402A301	Original	625.00
0413	GRILLE BACKING ?	6400F190	Original	159.00
2953	L/BOOTLID HINGE ?	5923A037	Original	58.00
2955	L/FASTENING CLIP X	5925A022	Original	10.00
3283	L/FASTENING CLIP X	MR482761	Original	10.00
4205	L/FASTENING CLIP X	MU001623	Original	20.00
0561	L/F HEADLAMP / BR	8301C543	Original	737.20
0317	L/F UPP BUMPER BRKT	6400F221 / BR	Original	35.10
4983	L/INN W-HOUSE COVER	7230A169 ?	Original	489.00
3281	L/R LAMP / BR	8330A851	Original	431.60
4203	L/R MUFLAP / TN	5370B565	Original	125.20
2629	L/R OUT BUMPER BRKT	6410C433 / BR	Original	87.50
3481	L/R OUT QTR PANEL	5301F967 / DD	Original	972.40
0361	L/SCREW M8X20	MF247251 / MC	Original	10.00
4027	L/SIDE MEMBER EXT	5253AM39 ? ?	Original	933.40
3577	L/UPP SIDE PANEL EXT	5301F977 ?	Original	265.00
0475	LEFT BONNET HINGE	5905A157 ?	Original	82.50
4978	LUGG COMP CARPET	7646A264 ?	Original	250.90
0411	LWR RADIATOR GRILLE	6402A281 / BR	Original	216.50
0431	MANUFACTURER BADGE	7415A603 / MC	Original	82.60
2954	R/BOOTLID HINGE	5923A038 ?	Original	58.00
2956	R/FASTENING CLIP	5925A022 X	Original	10.00
3284	R/FASTENING CLIP	MR482761 X	Original	10.00
4206	R/FASTENING CLIP	MU001623 X	Original	20.00

		Part Number	Part Source	Price SGD
Je	Description			737.20
62	R/F HEADLAMP	8301C544 ✓ <i>BR</i>	Original	35.10
318	R/F UPP BUMPER BRKT	6400F222 ✓ <i>BR</i>	Original	569.40
0742	R/F WING	5220H942 ✓ <i>DD</i>	Original	489.00
4984	R/INN W-HOUSE COVER	7240A170 ?	Original	431.60
3282	R/R LAMP	8330A852 ✓ <i>BR</i>	Original	125.20
4204	R/R MUFLAP	5370B566 ✓ <i>MIS</i>	Original	87.50
2630	R/R OUT BUMPER BRKT	6410C434 ✓ <i>BR</i>	Original	972.40
3482	R/R OUT QTR PANEL	5301F968 ✓ <i>DD</i>	Original	10.00
0362	R/SCREW M8X20	MF247251 X	Original	933.40
4028	R/SIDE MEMBER EXT	5253M348 ?	Original	265.00
3578	R/UPP SIDE PANEL EXT	5301F978 ?	Original	58.50
3015	REAR BADGE	7415A389 ✓ <i>MIS</i>	Original	962.00
2583	REAR BUMPER	6410C750 ✓ <i>MIS</i>	Original	130.20
8831	REAR EXHAUST RUBBER	1577A566 X	Original	1,398.00
3901	REAR FLOOR PANEL	5251C804 ✓ <i>DD</i>	Original	47.30
3020	REAR MANUFACT BADGE	MR108148T ✓ <i>MIS</i>	Original	260.00
2711	REAR PANEL CPL	5281A631 ✓ <i>DD</i>	Original	0.00
1017	reverse sensor	Rear ✓ <i>MIS</i>	Original	82.50
0476	RIGHT BONNET HINGE	5905A158 X	Original	65.50
1790	RR EXHAUST SEAL RING	MR529052 X	Original	771.00
8833	RR EXHAUST SILENCER	1570C567 ?	Original	153.00
1014	spare wheel board	Rear ?	Original	150.00
1013	spare wheel panel	Rear insulator ✓ <i>MIS</i>	Original	160.00
1001	support panel upper	Front X	Original	120.20
2973	T-GATE LOCK STRIKER	5927A044 X	Original	125.00
1009	ventilator cover	Rear ✓ <i>CRU</i>	Original	

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings
Subtotal
Subtotal Discount(+10.00%)

0.00
21,034.10
-2,103.41

Total

18,930.69

Extras

Code	Description	Price SGD
1000	C&C REAR BADGE ✓ <i>MIS</i>	58.30*
1002	bumper clips Rear ✓ <i>MIS</i>	30 80.00*
1003	body kit Rear bumper ✓ <i>MIS</i>	812.00*
1005	body kit L & R Rear bum chrome ✓ <i>MIS</i>	398.00*
1007	screw Rear bumper ✓ <i>MIS</i>	10 20.00*
1008	molding clips Rear boot lid ✓ <i>MIS</i>	19 32.00*
1012	trim clips Rear end panel ✓ <i>MIS</i>	10 48.00*
1015	windscreen sealant Rear ✓ <i>MIS</i>	60 80.00*
1016	reverse sensor Rear ✓ <i>MIS</i>	200 280.00*
1018	body kit Front ✓ <i>BR</i>	835.00*
Total Extras		2,643.30

Final Calculation

	SGD	SGD
Parts	21,034.10	
Total Discount(+10.00%)	-2,103.41	
Total Parts		18,930.69
Labour Time Base 10 WU/h		
Total 516.0 WU X 80.00 SGD/h	4,128.00	
Total of Labour		4,128.00
Total Of Extras		2,643.30
Paint Work Time Base 10 WU/h		
Labour Cost 180.0 WU X 80.00 SGD/h	1,440.00	
Material Cost	293.30	
Total Paint Including Material		1,733.30
Repair Cost		27,435.29

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/08/2020 12:10
Date Of Accident	21/08/2020 18:40
Exact Location Of Accident	PIE TWDS CHANGI B4 THOMSON FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH8779M
Insured/Policyholder	
Name Of Registered Owner	FOONG MENG PENG (FENG WENBIN)
NRIC No	SXXXX521J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84995940
Alternative Phone No	OTHERS-84995940
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	ATTRAAGE
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5116199800
Cover Note Number	
Driver	
Name of Driver	FOONG MENG PENG (FENG WENBIN)
NRIC No	SXXXX521J
Date Of Birth	10/05/1981
Occupation	OUTDOOR
Date Of Driving Pass	25/06/2015
Driving Experience	5 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-84995940
Fax Number	
Contact Number	OTHERS-84995940
Email Address	NOEMAIL

Address BL K 441C BUKIT BTOK WEST AVENUE
#10-933
Postcode 653441
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 5
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3
Passenger 1

NAME: : SAMUEL
GENDER: : MALE

Passenger 2

NAME: : WEI REN
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1:

Vehicle Registration Number SKN5041U
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2:

Vehicle Registration Number SHA2062H
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3:

Vehicle Registration Number SLH75A
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4:

Vehicle Registration Number SFL8373L
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1:

Name FOONG MENG PENG (FENG WENBIN)
Approximate Age
Injuries Sustain SLIGHT
Injured person in which vehicle? SMH8779M
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

DETAILS OF INJURED PERSON 2

Name SAMUEL
Approximate Age
Injuries Sustain SLIGHT
Injured person in which vehicle? SMH8779M
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

DETAILS OF INJURED PERSON 3


Name WEI REN
Approximate Age
Injuries Sustain SLIGHT
Injured person in which vehicle? SMH8779M
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Individual Statement

SKETCH PLAN:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ALONG PIE TOWARDS CHANGI BEFORE THOMSON FLYOVER. VEHICLE AHEAD SLOWED DOWN AND STOPPED. I FOLLOWED SUIT. MOMENT LATER WHILE MY VEHICLE WAS STILL STATIONARY, VEH B REAR-ENDED MY VEHICLE. THE IMPACT FORCED MY VEHICLE FORWARD TO HIT VEHICLE C. WHEN I ALIGHT I REALISE I WAS INVOLVE IN A CHAIN COLLISION.

DECLARATION

I/ We declare the foregoing particulars are true in every respect.

JK
Policyholder's Signature
Date & Time:

JK
Driver's Signature
(If driver is not the policyholder)
Date & Time:

ofun 22/08/20
Reporting Centre Personnel's Signature
Name:
NRIC / FIN No.: