

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20008873/UPA3Q2

Date: 30/10/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJK1125R	Insured Vehicle No :	SHA3745P
Date of Loss: 16/08/2020	Nature of Claim: TP	Claim No: MCT20080246

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK1125R		
Make & Model:	MERCEDES-BENZ GLC 250, 2.0 4MATIC (A)	Engine No:	27492031597415
Reg. Date:	19/03/2020 (Man. Year: 2018)	Chassis No:	WDC2533462F498885
Colour:	Black	Odometer:	3919 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,511.00	3,190.50	3,320.50	51.00
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,690.00	1,322.08	367.92	21.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,212.00	4,523.58	3,688.42	44.92
Approved Total (Overridden) (\$\$)		4,512.58		
(\$\$)	8,212.00	4,512.58	3,699.42	45.05
+ GST 7.00/7.00% (\$\$)	574.84	315.88	258.96	45.05
Nett Amount (\$\$)	8,786.84	4,828.46	3,958.38	45.05
+ Car Rental (4.0 x S\$180.00/day) (\$\$)		720.00		
+ Doc/Search Fee (\$\$)		36.45		
+ Other Costs (\$\$)		42.00		
Nett Liability (\$\$)		5,626.91		

INSPECTION

Date of Assignment:	21/08/2020 Present Location:	SME Motor Pte Ltd (Kaki Bukit)
Date Inspected:	25/08/2020 Inspected At:	SME Motor Pte Ltd (Kaki Bukit)
		1 Kaki Bukit Ave 6 #02-15, AutoBay @
		Kaki Bukit
		Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Sep 2020)
Parts:	M1-SUV	MERCEDES-BENZ GLC 250 2.0 4MATIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK1125R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Badly Dented	2,350.00 F	*2,350.00 FL
2	1		*REAR LH DOOR	Repair	2,550.00 F	*- FL
3	1		*FRT LH DOOR INNER RUBBER	Necessary	290.00 F	*290.00 FL
4	1		*REAR LH DOOR INNER RUBBER	Not Necessary	290.00 F	*- FL
5	1		*SIDE SKIRTS LH	Grazed	390.00 F	*390.00 FL
6	15		*SIDE SKIRTS CLIPS	Necessary	165.00 F	*165.00 FL
7	1		*REAR LH FENDER PROTECTOR	Grazed	210.00 F	*210.00 FL
8	8		*PROTECTOR CLIPS	Not Necessary	56.00 F	*- FL
9	20		*DOOR RIVERTS	Necessary	140.00 F	*140.00 FL
10	10		*DOOR RIVERTS	Not Necessary	70.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	6,511.00	3,545.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	354.50
Total Parts (\$)	6,511.00	3,190.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	40.00	-
2	TRANSFER 2 DOORS COMPONENT	New	200.00	-
3	RESET DOOR SETTINGS	New	250.00	250.00
4	LABOUR CHARGE	New	600.00	560.00
5	SPRAY PAINTING	New	600.00	512.08
Gross Labour Cost (\$\$)			1,690.00	1,322.08

Report was unsubmitted during this print-out.

< END OF ESTIMATES >