

**TTS EUROCARS PTE LTD**

383 Sin Ming drive Singapore 575717

Date : 23.09.2019

**RE: VEHICLE REPAIR QUOTATION**

Insurance Company : **AIG Asia Pacific**  
 Vehicle Reg No : **SMA7463S**  
 Name of Insured :  
 Policy Number :  
 Date of Accident : **22.08.2020**  
 Tyre of Claim : **Third Party Claim**  
 Model : **Hyundai i30**  
 Chassis No : **TMAH3513VJJ065190**

*Not Authorized*  
*Recovery Bepaint*  
*8 days*  
~~8 7854.20~~

We are please to submit our estimate of repairs to the above mention vehicle.

		Parts	Labour
1	REAR BUMPER	<i>R</i> \$ 801.90	<i>X</i>
2	REAR LH FENDER	<i>R</i> \$ 1,891.10	<i>✓</i>
3	REAR LH DOOR	<i>R</i> \$ 1,830.00	<i>✓</i>
4	FRONT LH DOOR	<i>R</i> \$ 1,734.00	<i>✓</i>
5	FRONT LH FENDER	<i>R</i> \$ 789.00	<i>X</i>
6	REAR BUMPER SIDE RETAINER	<i>Sn</i> \$ 53.76	<i>X</i>
7	BUMPER CLIPS	<i>na</i> \$ 59.00	<i>X</i>
8	FRONT DOOR WEATHERSTRIP	<i>Sn</i> \$ 201.00	<i>X</i>
9	REAR DOOR WEATHERSTRIP	<i>Sn</i> \$ 292.00	<i>X</i>
10	LH ROCKER PANEL	<i>R</i> \$ 2,449.00	<i>X</i>
11	REAR LH WHEEL BEARING	<i>Sn</i> \$ 454.00	<i>X</i>
12	REAR LH WHEEL HUB		
13	REAR LH SHOCK ABSORBER	<i>Sn</i> \$ 498.10	<i>X</i>
14	REAR LH SPORTS RIM	<i>Sn</i> \$ 1,338.00	<i>✓</i>
15	FENDER TAPE	<i>na</i> \$ 24.10	<i>✓</i>

**SUPP:**

MOULDING ASSY REAR DOOR FRAME	\$82.50	<i>✓</i>	<i>ne</i>	Sub Total Parts	\$12,414.96
FRT DOOR TOP MOULDING LH	\$95.60	<i>✓</i>	<i>nec</i>	Less 20%	\$ 2,482.99
TAPE FRT BLACK REAR LH	\$36.50	<i>✓</i>	<i>nec</i>	Total Parts	\$ 9,931.97
BLACK TAPE REAR DOOR FRT LH	\$36.50	<i>✓</i>	<i>nec</i>		
BLACK TAPE REAR FOOR FRAME REAR LH	\$31.50	<i>✓</i>	<i>nec</i>		

1	Sundries	\$	<del>150.00</del>	150.00	<i>X</i>	20
2	Wiring connection and check.	\$	150.00		<i>201</i>	
3	Tuff kote and spray anti rust proofing	\$	150.00		<i>901</i>	
4	Sealant for door panel, fender, end panel	\$	250.00		<i>901</i>	
6	Transfer front door components, trims, scuff plates	\$	250.00		<i>801</i>	
7	Transfer rear door components, trims, scuff plates	\$	250.00		<i>801</i>	
8	To remove and refix rear lh door quarter glass, conduct water leak test	\$	150.00		<i>301</i>	

**KKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

9	sealant for lh door quarter glass	\$	60.00	✓
10	Inner seal for LH door quarter glass	\$	<i>na</i> 50.00	<i>305n</i>
11	To remove and refix rear seats, carpets, rear lh fender inner trims, spare tyre compartment boards and scuff plates, seat belts to facilitate repair	\$	250.00	<i>100l</i>
12	To remove and refix petrol tank, to facilitate repairs	\$	500.00	<i>60l</i>
13	To replace rear lh sports rim, conduct wheel balancing	\$	30.00	<i>20l</i>
14	To conduct 4 wheel alignment, check steering angle and geometry	\$	150.00	<i>80l</i>
15	To remove and replace rear lh shock absorber wheel hub, wheel bearing, lower arm	\$	<i>na</i> 250.00	<i>X</i>
16	Labour charges to dismantle & refix front bumper front lh fender, front lh door, rear lh door, lh rocker panel, lh rear fender, rear bumper To repair and adjust affected portion to specific dimension.	\$	2,800.00	<i>1000l</i>
17	To spray paint front bumper, front lh fender front lh door, front lh "B" pillar, LH rocker panel rear lh door, rear lh fender, rear bumper rear end panel and all other accident affected portion	\$	2,800.00	<i>900l</i>
18	Remove and refix rear bumper sensor	\$	<i>na</i> 150.00	<i>X</i>
19	To conduct ECU programming, check and clear fault codes, restore programme modules	\$	<i>na</i> 350.00	<i>X</i>
Total (Labour)		\$	<b>8,740.00</b>	
Sub Total :		\$	18,671.97	
GST 7%		\$	1,307.04	
<b>Grand Total :</b>		\$	<b>19,979.01</b>	

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.