

TTS EUROCARS PTE LTD

383 Sin Ming drive Singapore 575717

Date : 23.09.2019

RE: VEHICLE REPAIR QUOTATION

Insurance Company : **AIG Asia Pacific**
 Vehicle Reg No : **SMA7463S**
 Name of Insured :
 Policy Number :
 Date of Accident : **22.08.2020**
 Tyre of Claim : **Third Party Claim**
 Model : **Hyundai i30**
 Chassis No : **TMAH3513VJJ065190**

We are please to submit our estimate of repairs to the above mention vehicle.

		Parts	Labour
1	REAR BUMPER	R \$ 801.90	X
2	REAR LH FENDER	R \$ 1,891.10	✓
3	REAR LH DOOR	R \$ 1,830.00	✓
4	FRONT LH DOOR	R \$ 1,734.00	✓
5	FRONT LH FENDER	R \$ 789.00	X
6	REAR BUMPER SIDE RETAINER	SL \$ 53.76	X
7	BUMPER CLIPS	na \$ 59.00	X
8	FRONT DOOR WEATHERSTRIP	\$ 201.00	?
9	REAR DOOR WEATHERSTRIP	\$ 292.00	?
10	LH ROCKER PANEL	R \$ 2,449.00	X
11	REAR LH WHEEL BEARING	\$ 454.00	?
12	REAR LH WHEEL HUB		
13	REAR LH SHOCK ABSORBER	\$ 498.10	?
14	REAR LH SPORTS RIM	nd \$ 1,338.00	✓
15	FENDER TAPE	na \$ 24.10	✓

Sub Total Parts \$12,414.96**Less 20% \$ 2,482.99****Total Parts \$ 9,931.97**

1	Sundries	\$	150.00	?
2	Wiring connection and check.	\$	150.00	2ol
3	Tuff kote and spray anti rust proofing	\$	150.00	9ol
4	Sealant for door panel, fender, end panel	\$	250.00	9ol
6	Transfer front door components, trims, scuff plates	\$	250.00	8ol
7	Transfer rear door components, trims, scuff plates	\$	250.00	8ol
8	To remove and refix rear lh door quarter glass, conduct water leak test	\$	150.00	3ol

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

9	sealant for lh door quarter glass	\$	60.00	✓
10	Inner seal for LH door quarter glass	\$	na 50.00	3000
11	To remove and refix rear seats, carpets, rear lh fender inner trims, spare tyre compartment boards and scuff plates, seat belts to facilitate repair	\$	250.00	1000
12	To remove and refix petrol tank, to facilitate repairs	\$	500.00	600
13	To replace rear lh sports rim, conduct wheel balancing	\$	30.00	200
14	To conduct 4 wheel alignment, check steering angle and geometry	\$	150.00	800
15	To remove and replace rear lh shock absorber wheel hub, wheel bearing, lower arm	\$	250.00	?
16	Labour charges to dismantle & refix front bumper front lh fender, front lh door, rear lh door, lh rocker panel, lh rear fender, rear bumper To repair and adjust affected portion to specific dimension.	\$	2,800.00	1000
17	To spray paint front bumper, front lh fender front lh door, front lh "B" pillar, LH rocker panel rear lh door, rear lh fender, rear bumper rear end panel and all other accident affected portion	\$	2,800.00	9000
18	Remove and refix rear bumper sensor	\$	na 150.00	X
19	To conduct ECU programming, check and clear fault codes, restore programme modules	\$	350.00	?
Total (Labour)		\$	8,740.00	
Sub Total :		\$	18,671.97	
GST 7%		\$	1,307.04	
Grand Total :		\$	19,979.01	

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.