

F1 Garage Pte Ltd

8 KAKI BUKIT AVE 4, #03-33

PREMIER @ KAKI BUKIT, SINGAPORE 415875

H/P: 96311088 / 91188490

Email: sales@F1garageSG.com

VEHICLE NUMBER SMR3923T

MAKE AND MODE: TOYOTA VIOS

DATE OF ACCIDENT:

MR2B23F3201189758

TP III Cecilia.

REPAIR ESTIMATE

NO.	DESCRIPTION OF SPARE PARTS	AMOUNT	REMARKS
1	REAR BUMPER <i>Carbide</i>	\$ 440.10	✓
1	REAR BUMPER LH SIDE RETAINER <i>new</i>	\$ 66.10	✓
1	REAR BUMPER LH BRACKET <i>new</i>	\$ 155.10	✓
1	REAR BUMPER LH REFLECTOR ASSY <i>at</i>	\$ 107.10	✓
1	REAR BUMPER LH REVERSE SENSOR <i>new</i>	\$ 321.40	✓
1	REAR BUMPER REINFORCEMENT <i>Beut</i>	\$ 459.10	316
1	REAR BUMPER LH SPLASH SHIELD <i>new</i>	\$ 78.30	✓
1	LH TAILLAMP ASSY <i>Carbide</i>	\$ 422.50	✓
1	END PANEL <i>new</i>	\$ 821.70	616.
1	BOOTLID <i>new</i>	\$ 733.36	✓
1	BOOTLID CENTRE EMBLEM <i>new</i>	\$ 59.10	✓
1	BOOTLID "VIOS" EMBLEM <i>new</i>	\$ 72.10	✓
1	BOOTLID "G" EMBLEM	\$ 42.40	✓
1	BOOTLID LOCK <i>new</i>	\$ 184.20	✓
		\$ 3,962.56	
		-25% \$ 990.64	
		\$ 2,971.92	

1967.80
1475.85

NO.	DESCRIPTION OF SPARE PARTS	AMOUNT	REMARKS
10	REAR BUMPER CLIPS <i>new</i>	\$ 50.00	30
	LABOUR CHARGES ON AFFECTED AREAS	\$ 900.00	600.
	RE-SPRAY ON AFFECTED AREAS	\$ 1,000.00	600.
	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS	\$ 70.00	50 1420.
	REMOVE AND REINSTALL REAR INNER TRIMS AND GARNISH	\$ 180.00	60
	APPLY ANTI RUST ON AFFECTED AREAS	\$ 50.00	✓
	CHECK WIRING AND LIGHTING SYSTEM	\$ 50.00	30
		\$ 5,271.92	

TOTAL: \$ 5,271.92

total: 289585 05 days.

h/s: 2.3K.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to information
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: