



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

## EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



### ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 TEL:62962706	Cust No/Name	KCV09189/Mr Winston Tang Liat Meng
Contact No	Reg No/Reg Date	SMD7173M / 31/08/2018
	Date In/Mileage	21/08/2020/ 38661
	Chassis No	GF7W0402224
	Engine No	4J11YT1342
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE
	Colour/Trim	X04 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000040	Credit	21/08/2020/ 18:08	DS	303 / Renemer	51307

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 DIAGNOSTIC/SCANNING				250.00
S MIPNT88088 TO CHECK ALL LIGHTING/WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AEAS				80 100.00
S MIPNT88088 TO REPLACE FRONT BUMPER, EXTENSION BUMPER, BRACKETS, CLIPS. STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS				600 1200.00
S MIPNT98088 SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS				420 840.00
S MIPNT88088 TO APPLY ZERTONA PAINT PROTECTION				550.00
S MIPNT88088 LICENSE PLATE WITH CASING				50.00
M JJ6400K114 FACE, FR BUMPER	1.00	851.00	0.00	851.00
M JJMR200300 CLIP, BUMPER	10.00	4.00	0.00	40.00
M JJ6400H313 LH BRACKET, FR BUMPER	1.00	18.00	0.00	18.00
M JJ6400H314 RH BRACKET, FR BUMPER	1.00	18.00	0.00	18.00
M JJ6405A197 EXTENSION, FR BUMPER	1.00	426.00	0.00	426.00
Z NOTES ACCIDENT ON 21/08/2020 ALONG ANG MO KIO AVENUE 4 OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP#: SLF6300X TP INS: LONPAC				

# Estimate

(Certificate) ↑

Steve (LKK) ML Angel  
3 days  
25/8/20, 3:00pm  
PIP

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm &amp; accepted by

Ry Bel-My

## Acknowledged by Repairer Parts

Signature: Labour  
Date: Standard Menu  
Specialist Job  
Others (Lub, etc)  
Sundry  
Total (w/o GST)

1,353.00  
0.00  
0.00  
2,990.00  
0.00  
0.00  
4,343.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.