

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 TEL:62962706	Cust No/Name KCV09189/Mr Winston Tang Liat Meng Reg No/Reg Date SMD7173M / 31/08/2018 Date In/Mileage 21/08/2020/ 38661 Chassis No GF7W0402224 Engine No 4J11YT1342 Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE Colour/Trim X04 / BK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000040	Credit	21/08/2020/ 18:08	DS	303 / Renemer	51307			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S	MIPNT88088	DIAGNOSTIC/SCANNING						250.00
S	MIPNT88088	TO CHECK ALL LIGHTING/WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AEAS						80 100.00
S	MIPNT88088	TO REPLACE FRONT BUMPER,EXTENSION BUMPER,BRACKETS,CLIPS. 670						600 1200.00
S	MIPNT88088	STRAIGHTEN,REFORM,ALIGN ON FRONT ACCIDENT AFFECTED AREAS						420 840.00
S	MIPNT98088	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS 470						550.00
S	MIPNT88088	TO APPLY ZERTONA PAINT PROTECTION						50.00
S	MIPNT88088	LICENSE PLATE WITH CASING						851.00
M	JJ6400K114	FACE,FR BUMPER	X R		1.00	851.00	0.00	851.00
M	JJMR200300	CLIP, BUMPER	—	me	10.00	4.00	0.00	40.00
M	JJ6400H313	LH BRACKET,FR BUMPER	—	BR	1.00	18.00	0.00	18.00
M	JJ6400H314	RH BRACKET,FR BUMPER	X	NM	1.00	18.00	0.00	18.00
M	JJ6405A197	EXTENSION, FR BUMPER	X	NM	1.00	426.00	0.00	426.00
Z	NOTES	ACCIDENT ON 21/08/2020 ALONG ANG MO KIO AVENUE 4 OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP#: SLF6300X TP INS: LONPAC						
Steve (LKK) HK Angel 3 days 25/8/20, 3:00pm PIP					LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
Confirm & accepted by Ry Ref- my					Acknowledged by Repairer Parts Signature: Labour Date: Standard Menu Specialist Job Others(Lub,etc) Sundry Total(w/o GST)			
Authorized signatory and company stamp					1,353.00 0.00 0.00 2,990.00 0.00 0.00 4,343.00			

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 TEL:62962706 Contact No	Cust No/Name	KCV09189/Mr Winston Tang Liat Meng
	Reg No/Reg Date	SMD7173M / 31/08/2018
	Date In/Mileage	21/08/2020/ 38661
	Chassis No	GF7W0402224
	Engine No	4J11YT1342
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE
	Colour/Trim	X04 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000040	Credit	25/08/2020/ 15:12	DS	303 / Renemer	51307			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	JJ7407A315	LH MOULDING, FR BUMP			1.00	116.00	0.00	CUT 116.00 v
Z	NOTES							
	SUPPLEMENTARY ITEM							
Estimate								

Confirm & accepted by

Parts	116.00
Labour	0.00
Standard Menu	0.00
Specialist Job	0.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	116.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.