

LEANG AUTOMOTIVE
BLK 1 KAKI BUKIT AVE 6
#01-68 AUTO BAY@ KAKI BUKIT
S'PORE 417883 HP 90286516

Lee Ahn

*Not Approved
1/5 4900
2 418/20
Hays*

VEHICLE No: SLD 8943M

1PC	REAR DOOR N/S
1PC	REAR DOOR INNER LOCK N/S
1PC	REAR DOOR INNER RUBBER N/S
1PC	REAR FENDER N/S
1PC	REAR BUMPER
1PC	REAR BUMPER PDC SENSOR N/S
1SET	REAR BUMPER CLIPS
1PC	REAR SHOCK ABSORBER N/S
1PC	REAR KNUCKLE N/S
1PC	REAR KNUCKLE ARM BEARING N/S
1PC	REAR SPORT RIM 18 INCH N/S

<i>DD/Bar</i>	\$1,645.45	✓
<i>11</i>	\$321.12	X
<i>11</i>	\$288.40	X
<i>Body</i>	\$1,632.85	✓
<i>Deep cut</i>	\$1,056.55	✓
<i>shocked</i>	\$182.35	✓
<i>lee</i>	\$45.00	✓
<i>11</i>	\$282.30	X
<i>11</i>	\$711.23	X
<i>11</i>	\$282.50	X
<i>cut/OD</i>	\$1,000.00	680 s-n
	\$7,447.75	

107

TO CHECK WIRING
TO DISMANTLE & REPLACED PDC SENSOR
TO TRANSFER REAR DOOR COMPONENTS
TO DISMANTLE & REFIX CUSHION UPHOLSTERY
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

	\$80.00	20
	\$80.00	40
	\$100.00	50
	\$120.00	80
	\$80.00	60
	\$800.00	550
	\$1,000.00	600
TOTAL	\$9,707.75	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*P-4862.2
102
P-4102.98
S-W 68000
H-1000
6181.98
4948*