

S THREE AUTOMOTIVE RECOVERY PTE LTD
 Blk 8 Sin Ming Industrial Estate
 #01-64/66 Singapore 575643
 Tel : 6284 1542 / 6284 1575
 Fax : 6487 5315
 sthreeautomotive@gmail.com

Not Authorized

11 Rmp 833000

Accident After Repair

ATT: MOTOR CLAIM DEPT.

T/P VEH. NO.: GBG2731A

ESTIMATE REPORT 1st QUOTATION

OWNER'S PARTICULAR

NAME: NG AH SOON

ADDRESS:

LICENSE NO. SMN2753U TRANS.:

MAKE / MODEL: TOYOTA NOAH

OWNER'S INSURER: FWD INSURANCE

JOB-CODE: TP S/A: MICHELLE

JOB NO:

CONTACT:

CHASSIS NO:

ENGINE NO:

ACCIDENT DATE: 21-Aug-20

CLAIM DETAIL

MATERIALS

		QTY	QUO-PRICE	DISC %	DISC- PRICE	SUR. DISP	REV. PRICE
1	REAR BUMPER 1455.80	CM 1.00	1677.10	25.00	1257.83	Y	✓
2	REAR BUMPER INNER SHIELD LH	1.00	105.00	25.00	78.75	Y	X
3	REAR BUMPER RETAINER LH	DI 1.00	45.00	25.00	33.75	Y	✓
4	REAR BUMPER RETAINER RH	1.00	45.00	25.00	33.75	Y	X
5	REAR BUMPER BRACKET LH	1.00	58.50	25.00	43.88	Y	X
6	REAR BUMPER BRACKET RH	1.00	58.50	25.00	43.88	Y	X
7	REAR BUMPER SPONGE	1.00	210.00	25.00	157.50	Y	X
8	REAR BUMPER REFLECTOR LH	1.00	105.00	25.00	78.75	Y	X
9	REAR FENDER LH 1339.20	1.00	1380.00	25.00	1035.00	Y	✓
10	REAR FENDER 1/4 GLASS W/MOULDING LH 40896 nec	1.00	550.00	25.00	412.50	Y	X ✓
11	REAR FENDER TOP RUN COVER LH	1.00	439.00	25.00	329.25	Y	X
12	TAILLAMP LH	1.00	898.60	25.00	673.95	Y	X
13	TAILAMP LOWER COVER LH	CM 1.00	259.00	25.00	194.25	Y	✓
14	TAILAMP LOWER RETAINER LH	CM 1.00	58.40	25.00	43.80	Y	X
15	REAR REVERSE SENSOR 1SET	1.00	1120.00	25.00	840.00	Y	X
TOTAL (PARTS):			7009.10		4416.83		

SPECIAL NETT ITEM

1	REAR FENDER INNER TRIMBOARD CLIPS 1SET	1.00	nn 80.00	0.00	80.00	Y	X
2	REAR BUMPER CLIPS	1.00	nn 50.00	0.00	50.00	Y	✓
3	REAR FENDER INNER GARNISH CLIPS 1SET	1.00	nn 120.00	0.00	120.00	Y	X
4	REAR FENDER 1/4 GLASS SEALANT	nn 1.00	180.00	0.00	180.00	Y	X
5	REAR FENDER 1/4 GLASS PRIMER AND CLEANER	nn 1.00	80.00	0.00	80.00	Y	X
6	TAILGATE 1/4 GLASS SEALANT	nn 1.00	80.00	0.00	80.00	Y	X
7	TAILGATE 1/4 GLASS INNER SEAL	nn 1.00	80.00	0.00	80.00	Y	X
8	TAILGATE 1/4 GLASS PRIMER AND CLEANER	nn 1.00	50.00	0.00	50.00	Y	X
TOTAL (PARTS):			720.00		720.00		

ABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA	1.00	1400.00	0.00	1400.00	Y	700
2	SPRAY PAINTING ON AFFECTED AREA	1.00	1200.00	0.00	1200.00	Y	550
3	R&R TAILGATE 1/4 GLASS TO ASSIST REPAIR	1.00	nn 200.00	0.00	200.00	Y	X

1	CARPET & INNER TRIM TO ASSIST REPAIR	1.00	120.00	0.00	120.00	Y	100
2	SEAT AND GARNISH TO ASSIST REPAIR	1.00	120.00	0.00	120.00	Y	30
3	SPRAY TUFF KOTE ON ACCIDENT AREA	1.00	180.00	0.00	180.00	Y	20
4	CHECK WIRING SYSTEM	1.00	80.00	0.00	80.00	Y	50
5	R&R REVERSE SENSOR	1.00	120.00	0.00	120.00	Y	X
6	COMPUTERISED WHEEL ALIGNMENT	1.00	120.00	0.00	120.00	Y	

TOTAL (LABOUR) : 3540.00 3540.00

TOTAL PARTS & LABOUR 9,516.83

EXCESS : : \$

NO. OF DAY : 05 days

RE-SURVEY : BEFORE / AFTER PAINTING

PART BY-PART OR LUMP-SUM : \$

DATE OF SURVEY : 25/08/20

SURVEY BY : Kunnorh

CONTACT NO: 98910883

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FAX NO :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.