

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2000167
Date: 19 Aug 2020
Veh Reg No: SLV6355D
Make/Model: TOYOTA WISH 1.8
AUTO
Chasis No: JTDER12W103002485
Reg. Date: 10/03/2009
Your Ref No: SMF399P

Claim Type: Third Party
Accident Date: 31/07/2020
TP Veh Reg No: SMF399P

Xiao Tong

Estimate Repair Cost to Vehicle No :SLV6355D

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
30	2 PCS RADIATOR TOP BRACKETS	117.60	+
31	2 PCS RADIATOR TOP BUSH	16.00	+
32	2 PCS RADIATOR BOTOM BUSH	16.00	+
33	1 PC FRT DOOR LH	1,253.80	+
34	2 PCS FRT DOOR HINGE LH	162.40	+
35	1 PC FRT QUARTER GLASS LH	246.60	✓
36	1 PC AIR CLEANER BOX	945.90	✓
37	1 PC AIR CLEANER JOINT HOSE	78.60	+
38	1 PC AIR CLEANER OUTLET HOSE	89.40	✓
39	1 PC FRT FUSE BOX	723.70	✓
40	1 PC BATTERY TRAY	183.20	✓
41	1 PC FRT WIPER PANEL GARNISH	583.30	✓
42	1 PC FRT WIPER PANEL SIDE GARNISH	46.20	✓
43	1 PC FRT SHOCK ABSORBER LH	394.30	✓
44	1 PC FRT SHOCK ABSORBER MOUNTING LH	185.40	✓
45	1 PC FRT COIL SPRING LH	323.10	+
46	1 PC FRT LOWER ARM LH	472.90	✓
47	1 PC FRT KNUCKLE ARM LH	408.90	✓
48	1 PC FRT BEARING LH	179.30	✓
49	1 PC FRT WHEEL HUB LH	288.40	✓
50	1 PC FRT DRIVE SHAFT LH	1,253.40	✓
51	1 PC ANTI ROLL BAR	340.80	✓
52	1 PC ANTI ROLL BAR LINKAGE LH	178.70	✓
53	1 PC FRT BALL JOINT LH	179.90	✓
54	1 PC STEERING RACK & PINION	1,243.60	✓
55	1 PC FRT BRAKE ROTOR LH	366.20	+
56	1 PC FRT BRAKE ROTOR PANEL LH	96.40	+
57	1 PC FRT BRAKE PAD LH	198.70	+
58	1 PC FRT BRAKE HOSE LH	43.60	+
59	1 PC FRT BRAKE PIPE LH	128.80	+
60	1 PC FRT BRAKE CALIPER LH	898.30	+

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2000167
Date: 19 Aug 2020
Veh Reg No: SLV6355D
Make/Model: TOYOTA WISH 1.8
AUTO
Chasis No: JTDER12W103002485
Reg. Date: 10/03/2009
Your Ref No: SMF399P

Claim Type: Third Party
Accident Date: 31/07/2020
TP Veh Reg No: SMF399P

Estimate Repair Cost to Vehicle No :SLV6355D

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	List Price		
1	1 PC BONNET <i>Dented</i>	698.80	✓
2	2 PCS BONNET HINGES <i>Key Bent</i>	95.40	✓
3	1 PC BONNET LOCK <i>new</i>	58.80	+
4	1 PC BONNET TRIM <i>new</i>	312.80	+
5	1 PC BONNET RUBBER <i>new</i>	65.50	+
6	1 PC BONNET CHROME MOULDING <i>new</i>	188.80	+
7	1 PC FRT WHEEL HOUSING LH <i>Distorted</i>	668.10	✓
8	1 PC FRT FENDER LH <i>Distorted</i>	723.40	✓
9	1 PC FRT FENDER COWLING LH <i>torn</i>	180.10	✓
10	1 PC FRT FENDER SIGNAL LAMP LH <i>cracked</i>	58.10	✓
11	1 PC FRT CHASSIS FRAME LH <i>Repair</i>	847.80	+
12	1 PC ENGINE UNDER COVER LH <i>torn</i>	168.10	✓
13	1 PC HEADLAMP LH <i>smashed</i>	953.60	✓
14	1 PC HEADLAMP PANEL LH <i>Distorted</i>	98.10	✓
15	1 PC FRT GRILLE <i>cracked</i>	199.20	✓
16	1 PC FRT DOOR PILLAR LH <i>Dented</i>	947.20	✓ 796
17	1 PC FRT BUMPER <i>Distorted</i>	572.80	✓
18	1 PC FRT BUMPER REINFORCEMENT <i>Bent</i>	275.30	✓
19	1 PC FRT BUMPER SPONGE <i>cracked</i>	95.90	✓
20	2 PCS FRT BUMPER BRACKETS <i>new</i>	199.40	+
21	2 PCS FRT BUMPER SIDE RETAINERS <i>new</i>	86.80	✓
22	1 PC FRT FOG LAMP COVER LH <i>missing</i>	38.20	✓
23	1 PC FRT SUPPORT PANEL <i>Repair</i>	848.90	+
24	1 PC FRT SUPPORT PANEL TRIM <i>new Dented</i>	115.80	✓
25	1 PC AIRCON CONDENSER <i>new</i>	1,357.80	+
26	1 PC RADIATOR <i>Distorted</i>	1,543.10	✓
27	1 PC RADIATOR FAN AND MOTOR ASSY <i>new</i>	533.80	+
28	1 PC RADIATOR FAN COWLING <i>new new</i>	185.10	+
29	1 PC RADIATOR TOP HOSE <i>new</i>	65.50	+

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2000167
Date: 19 Aug 2020
Veh Reg No: SLV6355D
Make/Model: TOYOTA WISH 1.8
AUTO
Chasis No: JTDER12W103002485
Reg. Date: 10/03/2009
Your Ref No: SMF399P

Claim Type: Third Party
Accident Date: 31/07/2020
TP Veh Reg No: SMF399P

Estimate Repair Cost to Vehicle No :SLV6355D

Quantity	Description	List Price	Amount
		SS	SS
61	1 PC FRT CROSSMEMBER <i>Best</i>	1,758.20	<i>1658</i>
62	1 PC FRT ENGINE CENTRE CROSSMEMBER <i>new</i>	365.80	<i>X</i>
	<i>1 set wire hardness snapped</i>	25,949.60	
	<i>1 pc air bag sensor cable</i>	6,487.40	19,462.32
	<i>Special Net</i>		
63	1 SET BONNET TRIM CLIPS <i>new</i>	40.00	<i>X</i>
64	1 SET FRT FENDER COWLING CLIPS LH <i>new</i>	40.00	<i>30</i>
65	1 SET ENGINE UNDER COVER CLIPS LH <i>new</i>	40.00	
66	1 SET FRT GRILLE CLIPS <i>new</i>	30.00	<i>10</i>
67	1 SET FRT BUMPER CLIPS <i>new</i>	40.00	<i>30</i>
68	1 PC FRT NUMBER PLATE <i>new</i>	50.00	<i>X</i>
69	1 SET FRT SUPPORT PANEL TRIM CLIPS <i>new</i>	30.00	<i>✓</i>
70	1 TUBE FRT QUARTER GLASS SEALANT LH <i>new</i>	60.00	<i>20</i>
71	1 PC FRT QUARTER GLASS SEAL LH <i>new</i>	60.00	<i>20</i>
72	1 PC BATTERY <i>Replaced</i>	250.00	<i>200</i>
73	1 TUBE FRT WINDSCREEN GLASS SEALANT <i>new</i>	60.00	<i>40</i>
74	1 PC FRT WINDSCREEN SEAL <i>new</i>	60.00	<i>40</i>
75	1 PC FRT SPORTS RIM LH <i>lit</i>	800.00	<i>400</i>
76	1 PC FRT TYRE LH <i>Punctured</i>	380.00	<i>200</i>
		1,940.00	1,940.00
	Labour		
77	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,800.00	<i>1600</i>
78	1 TO REMOVE AND REFIT FRONT LH DOOR GLASS	100.00	<i>X</i>
79	1 TO REMOVE AND REFIT SEAT CUSHION	200.00	<i>X</i>
80	1 TO REMOVE AND REPLACE QUARTER GLASS	100.00	<i>50</i>
81	1 TO REMOVE AND REFIT ENGINE	600.00	<i>X</i>
82	1 TO REMOVE AND REFIT FRONT UNDERCARRIAGE	600.00	<i>380</i>
83	1 TO REMOVE AND REFIT FRONT WINDSCREEN GLASS	120.00	<i>✓</i>

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2000167
Date: 19 Aug 2020
Veh Reg No: SLV6355D
Make/Model: TOYOTA WISH 1.8
AUTO
Chasis No: JTDER12W103002485
Reg. Date: 10/03/2009
Your Ref No: SMF399P

Claim Type: Third Party
Accident Date: 31/07/2020
TP Veh Reg No: SMF399P

Estimate Repair Cost to Vehicle No :SLV6355D

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
84	1 TO REMOVE AND REFIT DASHBOARD	400.00 <i>x</i>	
85	1 TO REMOVE AND REFIT ^{FUSE} FUEL BOX	250.00 <i>200</i>	
86	1 TO PROGRAMME AND DIAGNOSE	450.00 <i>x</i>	
87	1 TO CHECK WHEEL ALIGNMENT	120.00 <i>80</i>	
88	1 TO CHECK WIRING	100.00 <i>30</i>	
89	1 TO REFILL AIRCON GAS	120.00 <i>4220</i> ✓	
90	1 TO SPRAY PAINTING	1,800.00 <i>1500</i>	
91	1 TO SPRAY UNDERSEAL	180.00 <i>80</i>	
92	1 TOWING	60.00 ✓	
		8,000.00	8,000.00
	Total		S\$ 29,402.32
	Add GST @ 7%		2,058.16
	Total Amount Payable		<u>S\$ 31,460.48</u>

TOTAL: SINGAPORE DOLLAR THIRTY ONE THOUSAND FOUR HUNDRED SIXTY AND CENTS FORTY EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

Adrian Lj
L/S 20/08/20
14 Dgs

For Kang Car Repairers Pte Ltd

Chia
AUTHORISED SIGNATURE

Supplement: 1088.17
total: 19054.84
L/S: 15.2k

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2000167
Date: 29 Sep 2020
Veh Reg No: SLV6355D
Make/Model: TOYOTA WISH 1.8
AUTO
Chasis No: JTDER12W103002485
Reg. Date: 10/03/2009
Your Ref No: SMF399P

Claim Type: Third Party
Accident Date: 31/07/2020
TP Veh Reg No: SMF399P

Estimate Repair Cost to Vehicle No :SLV6355D

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair			
	List Price		
1	1 PC AIR BAG SENSOR <i>could snapped.</i>	177.20	✓
2	1 PC WIRE HARNESS	867.90	✓
3	1 PC BRAKE SENSOR <i>Dangt.</i>	165.80	✓
		1,210.90	
	Less 25%	302.73	908.18
Special Net			
4	1 PC AUTO OIL - 4 LITRES <i>New</i>	150.00	100. ✓
5	1 PC BRAKE OIL <i>New</i>	80.00	40. ✓
6	1 PC RADIATOR COOLANT <i>New</i>	100.00	40. ✓
		330.00	330.00
Total			S\$ 1,238.18
GST Amount			S\$ 86.67
Total Amount Payable			<u><u>S\$ 1,324.85</u></u>

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

Supplementary: 1088.17.