



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLU5350D*RA

United Overseas Insurance Ltd

Motor Claims Department
3 Anson Rd #28-01 Springleaf Tow
Singapore 079909

*Mobile: +6593394828

Vehicle & Document Information

WIP No **44516**
Reg No/Reg Date **SLU5350D*RA / 25/09/2012**
Date In/Mileage **26/08/2020/ 81015**
Chassis No **WDD2120482A626502**
Engine No **27186030476676**
Make/Model **MB/E 200 CGI SEDAN (W212)**
Colour/Trim **027 755 Tenorite Gr/ 042 208 Leather Gr**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00003	Cash	31/08/2020/ 10:25	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

Z REQUEST

Customer Request

M BPNSUN

POLICY NO/ACC DATE : DHOM120040851901 // 23/08/2020

DRIVE IN/EXCESS : 24/08/2020 // \$750

DATE IN/DATE SURVEY: 25/08/2020 1345 // LKK - RASUL

BY/AUTHORIZED ON : 26/8/2020 1704 // LKK - DENISE

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESpray REAR BUMPER

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

X REAR BUMPER

1.00 1816.23 00.00

1816.23

X PARKTRONIC SENSOR SPACER RING

2.00 9.77 00.00

19.54

X BPNEXC

INSURANCE EXCESS

-750.00

X LH/ REAR BUMPER BOTTOM BRACKET

1.00 22.71 00.00

22.71

Finalize.

Confirmed & accepted by

7% GST on **Nett 3,168.48**
221.79

Authorized signatory and company stamp

Total Payable 3,390.27

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLU5350D*RA

United Overseas Insurance Ltd

Motor Claims Department
3 Anson Rd #28-01 Springleaf Tow
Singapore 079909

*Mobile: +6593394828

Vehicle & Document Information

WIP No **44516**
Reg No/Reg Date **SLU5350D*RA / 25/09/2012**
Date In/Mileage **26/08/2020/ 81015**
Chassis No **WDD2120482A626502**
Engine No **27186030476676**
Make/Model **MB/E 200 CGI SEDAN (W212)**
Colour/Trim **027 755 Tenorite Gr/ 042 208 Leather Gr**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00003	Cash	31/08/2020/ 10:19	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X LH/ REAR BUMPER BOTTOM BRACKET	1.00	22.71	00.00	22.71

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Supplementary

Confirmed & accepted by

	Nett	22.71
7% GST on	22.71	1.59
Total Payable		24.30

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany