

Not Authorized
Reservy B&Paint

AAD2008-082

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO/GST Reg. No. 201019626G

SHB 7724T

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

21 AUG 2020

SHB 7724T

JTDKB3FU303081296

TOYOTA

PRIUS

20.8.2020

FCIL

18/6/2019

	PART		LIST	
1	FRONT BUMPER	\$	CM 516.00	✓
1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	Sm 103.40	X
1	REINFORCEMENT, FRONT BUMPER	\$	Ry 716.60	✓
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	Ry 246.10	✓
1	COVER, FRONT BUMPER HOLE, RH	\$	any 29.30	✓
1	COVER, FRONT BUMPER HOLE, LH	\$	Sm 29.30	X
1	ABSORBER, FRONT BUMPER, LOWER	\$	CM 132.70	✓
1	ABSORBER, FRONT BUMPER ENERGY	\$	CM 79.60	✓
1	FRONT BUMPER SIDE RETAINER RH	\$	DIT 80.10	✓
1	FRONT BUMPER SIDE RETAINER LH	\$	Sm 82.30	X
1	COVER, ENGINE UNDER, NO.1	\$	Sm 472.40	X
1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	Sm 241.90	X
1	EXTENSION, FRONT BUMPER, RH	\$	X 120.10	X
1	EXTENSION, FRONT BUMPER, LH	\$	X 120.10	X
1	FRONT LED LAMP (LOWER) RH	\$	Sm 951.40	X
1	FRONT LED LAMP (LOWER) LH	\$	Sm 951.40	X
1	FRONT HEADLAMP RH	\$	any CM 2,637.60	✓
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	Sm 960.50	X
1	MOTOR, HEADLAMP LEVELING, RH	\$	Sm 487.50	X
1	FRONT HEADLAMP LH	\$	SVC 2,637.60	X
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	Sm 960.50	X
1	FRONT FENDER RH	\$	Bu 977.80	✓
1	LINER, FRONT FENDER, RH	\$	Sm 206.70	X
1	EMBLEM, SIDE PANEL	\$	Ry 54.60	✓
1	GRILLE SUB-ASSY, RADIATOR	\$	CM 346.00	✓
1	GRILLE, RADIATOR, LOWER NO.1	\$	CM 170.10	✓

AAD2008-082

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7724T

1 EMBLEM ASSY, RADIATOR GRILLE	\$	mit	90.80	✓
1 FRONT BONNET	\$	R	983.10	✓
1 HINGE ASSY, HOOD, RH	\$	N	58.90	}
1 HINGE ASSY, HOOD, LH	\$	N	58.90	
1 INSULATOR, HOOD	\$	Sn	410.90	
1 FRONT FENDER LH	\$	N	977.80	
1 LINER, FRONT FENDER, LH	\$	Sn	202.50	
1 EMBLEM, SIDE PANEL	\$	N	54.60	
1 COVER, RADIATOR SUPPORT OPENING	\$	Sn	235.30	
1 WIRE, ENGINE ROOM MAIN	\$	Sn	7,323.90	
1 SUPPORT SUB-ASSY, RADIATOR, RH	\$	Sn	245.10	
1 SUPPORT SUB ASSY, RADIATOR, UPPER	\$	Sn	377.10	
1 SUPPORT SUB ASSY, RADIATOR, LOWER	\$	Sn	409.90	
1 SUPPORT SUB-ASSY, RADIATOR, LH	\$	Sn	245.10	
1 SUPPORT, RADIATOR, UPPER RH	\$	N	78.90	
1 SUPPORT, RADIATOR, UPPER LH	\$	N	78.90	
1 JAR ASSY, WINDSHIELD WASHER	\$	Sn	219.10	
1 INLET SUB ASSY, WASHER	\$	Sn	67.00	}
1 MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$	Sn	292.40	
1 GUIDE, RADIATOR AIR, NO.3	\$	Sn	112.70	
1 GUIDE, RADIATOR AIR, NO.1 RH	\$	Sn	65.30	
1 SEAL, RADIATOR TO SUPPORT, NO.2	\$	Sn	29.60	
1 GUIDE, RADIATOR AIR, NO.1 LH	\$	Sn	69.90	
1 SEAL, RADIATOR TO SUPPORT, NO.3	\$	Sn	29.60	
1 HORN ASSY, HIGH PITCHED	\$	N	134.80	
1 PANEL SUB ASSY, FRONT DOOR, RH	\$	N	1,300.70	
1 TAPE, BLACK OUT, NO.1 FRT RH	\$	N	13.30	
1 TAPE, BLACK OUT, NO.2 FRT RH	\$	N	43.50	
1 TAPE, BLACK OUT, NO.3 FRT RH	\$	N	26.30	
1 INLET, AIR CLEANER, NO.3	\$	N	42.10	
1 INLET, AIR CLEANER, NO.2	\$	Sn	112.70	}
1 INLET, AIR CLEANER, NO.1	\$	Sn	155.60	
1 SEAL, HOOD TO FRONT END PANEL	\$	N	51.60	
1 BATTERY	\$	Sn	1,584.90	

Trans-cab Auto Services Pte Ltd

AAD2008-082

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7724T

- 1 CLAMP SUB-ASSY, BATTERY

	\$	<i>115.50</i>	<i>X</i>
TOTAL	\$	30,609.90	
25%	\$	7,652.48	
	\$	22,957.43	

Special Nett

- 1 FRONT WHEEL RIM
1 FRONT WHEEL RIM COVER
1 FRONT TYRE 195/65/15
1SET CLIP, FRONT LH FENDER LINER
1SET CLIP, FRONT RH FENDER LINER
1 FRONT NUMBER PLATE WITH MOULDING
1SET BUMPER CLIP FRT
1SET FRT LH BUMPER RETAINER CLIP
1SET FRT RH BUMPER RETAINER CLIP
1 FRONT DOOR STICKER "Trans-Cab"
1 ENGINE UNDER COVER CLIP
1 HOOD INSULATOR CLIP
1 RADIATOR GRILLE SCREW

\$	<i>1,879.40</i>	<i>X</i>
\$	<i>211.50</i>	<i>X</i>
\$	<i>350.00</i>	<i>X</i>
\$	<i>65.00</i>	<i>X</i>
\$	<i>65.00</i>	<i>X</i>
\$	<i>200.00</i>	<i>450</i>
\$	<i>80.00</i>	
\$	<i>60.00</i>	
\$	<i>60.00</i>	
\$	<i>100.00</i>	
\$	<i>65.00</i>	
\$	<i>50.00</i>	
\$	<i>50.00</i>	
TOTAL	\$	3,235.90

TOTAL PARTS \$ 26,193.33**LABOUR**

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts, Adjust
And Realign The Same

\$ 2,000.00 *500*

To remove and refit interior fittings, trimings, garnish,
fittings and other, to enable repair.

\$ *380.00* *X*

To Rust-Proofing and apply undercoat Of The Affected
Areas.

\$ 250.00 *300*

Putty And Spray Painting Of The Affected Portion.

\$ 2,000.00 *600*

Trans-cab Auto Services Pte Ltd

AAD2008-082

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7724T

To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn	350.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To transfer of Bonnet fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	201
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To transfer of door fittings, attachments and perform water seepage test.	\$	nn	170.00	X
Towing Fees	\$		170.00	501
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas to facilitate bodywork repair.	\$	nn	380.00	X
To remove and refit battery, battery cover, electrical wiring, fuse box, relay and other necessary items to facilitate bodywork repair.	\$	nn	480.00	X

TOTAL \$ 7,080.00**Over All Total** \$ 33,273.33

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(PART-BY-PART) Repair Days

20 days

3 days