

WinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

SHIN-HAN MOTORS PTE LTD
43 SPRINGSIDE WALK
SINGAPORE 786628

Contact : 98515910, 87662500

4 Days
Impress repair
25/8/2020
Gino Qid
After repair photos.

ESTIMATE

Repair Code : CLM14999

Date in : 24/08/2020

Vehicle Num. : SIN3588J

Model : HONDA FREED 1.5G A

Chassis/Eng# : GB31030569/L15A2330939

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER ✓ Cut	1	562.10	✓ 562.10
FRONT BUMPER REINFORCEMENT Repair. x	1	233.70	× 233.70
FRONT BUMPER RH SIDE RETAINER / De	1	22.00	✓ 22.00
FRONT GRILLE ✓ CMA	1	237.50	✓ 237.50
FRONT RH FENDER ✓ CMA	1	532.60	✓ 532.60
FRONT RH FENDER INNER SHIELD COVER x NN	1	115.00	× 115.00
FRONT RH HEADLAMP / Cut	1	650.00	✓ 650.00
FRONT RH KNUCKLE ARM X	1	250.00	× 250.00
FRONT RH KNUCKLE ARM BEARING X } NN	1	130.00	× 130.00
FRONT RH LOWER ARM X	1	259.00	× 259.00
FRONT RH SHOCK ABSORBER X	1	361.60	× 361.60
FRONT RH TIE ROD END X	1	30.00	× 30.00
FRONT WASHER TANK ✓ De	1	89.50	✓ 89.50
FRONT WASHER TANK MOTOR x NN	1	48.50	× 48.50
FRONT WASHER TANK NECK x NN	1	19.50	× 19.50
FRONT RH HEADLAMP LOWER BRACKET ✓ BA	1	47.00	✓ 47.00

*** This is a computer-generated document which requires no signature. ***

page 1

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Car AUTOMOTIVE PTE LTD

Autofab
 17-18 Heavy Vehicle #01-08 Spray Painting #02-27
 Singapore 417921 Tel No : +65 6842 0051 Fax No : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

SHIN-HAN MOTORS PTE LTD
 43 SPRINGSIDE WALK
 SINGAPORE 786628

Contact : 98515910, 87662500

ESTIMATE

Repair Code : CLM14999

Date in : 24/08/2020

Vehicle Num : SJN3588J

Model : HONDA FREED 1.5G A

Chassis/Eng# : GB31030569/L15A2330939

	Subtotal before discount	2140.7	3,588.00
Percentage discount 20%		1712.56	717.60
	Sub-total 1		2,870.40
FRONT BUMPER CLIPS - SET ✓ <i>SMC</i>	1	50.00	30 50.00
FRONT GRILLE CLIPS - SET ✓ <i>SMC</i>	1	30.00	20 30.00
FRONT RH 185/70R14 TYRE X <i>NN</i>	1	280.00	X 280.00
FRONT RH FENDER INNER SHIELD COVER CLIPS - SET ✓ <i>SMC</i>	1	30.00	20 30.00
FRONT RH HEADLAMP TRANSPARENT STICKER ✓ <i>SMC</i>	1	120.00	60 120.00
FRONT RH SPORT RIM ✓ <i>Cut</i>	1	650.00	350 650.00
	Subtotal before discount	480	1,160.00
Percentage discount 0%			0.00
	Sub-total 2		1,160.00
	Parts-total		4,030.40

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

	30	80.00
NN X <i>So</i>	200	200.00
	60	120.00
	600	800.00
450	400	700.00
	40	100.00
Labour Total	1180	2,000.00
Parts & Labour Total		6,030.40

3372.56

-20%: 2700

*** This is a computer-generated document which requires no signature ***