



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS3/FWD19001929/Gsf3e2-1

C/O: SEAH ONG & PARTNERS LLP  
36 ROBINSON ROAD  
#12-03 CITY HOUSESINGAPORE 068877

Date : 15-09-2020



Code : FWD

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLP 4121G	<b>Veh. Inspected</b>	SKA 7103E
<b>Policy No.</b>	20.28070 FWD	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	1201900003642	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	XIN YI	<b>Assign Date</b>	24/08/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA WISH	<b>c.c</b>	1797
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2011
<b>Chassis No.</b>	ZGE200008634	<b>Colour</b>	BLACK
<b>Odometer</b>	157153	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/65 R15	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	195/65 R15	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	195/65 R15	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	195/65 R15	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	25/01/2019	<b>Inspection Date</b>	30/01/2019
<b>Survey held at</b>	BLACK EAGLE AUTO PTE. LTD. 25 KAKI BUKIT ROAD 4 #05-80 SYNERGY @ KB SINGAPORE 417800		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>2 Working Days</b>
--	-----------------------