

ASS. REC. BY:

REF:

AIG/20008912/ke

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

1. B. 1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMC 9462X

Yr Regn:

07/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW

216i

c.c

1499

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

44127

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBA 2D 920505KB 81128

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

205/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

29/6/20

D.O.I.

24/8/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/8

1090h

Confirm

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKV5188M
Accident Date : 29-Jun-2020

No. : 06189

Date : 06-Jul-2020

Our Ref : 020069 (AIG) / CHAN

PAGE : 1

LIN JYH FANG KELVIN
32 BUKIT BATOK STREET 21
#07-09
Singapore 659637

*Not Authorised
Putty After Rain
81090k 3days*

ESTIMATED COST OF REPAIR FOR BMW 216I GT LED NAV SMC9462X
=====

To repair and service rear rh rim	200.00	<i>150k</i>
To panel beating rear rh door, rh fender, repair rear bumper, align & refix rh rocker garnish	350.00	<i>280k</i>
To putty and spray rear rh door, rh fender, rear bumper & rocker garnish	900.00	<i>660k</i>
Total :	S\$ 1,450.00	

Singapore Dollars One Thousand Four Hundred and Fifty Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Vehicle Registration Details

Vehicle No. SMC9462X	Make/Model B.M.W./216I GT LED NAV	Vehicle Scheme -
Current Propellant Petrol	Chassis No. WBA2D920505K81128	Vehicle Type Passenger Motor Car

Owner's Details

Owner Name:

LIN JYH FANG, KELVIN

Owner ID Type:

Singapore NRIC

NRIC/Passport/Company Cert No.:

S1785421F

Registered Address

**32 BUKIT BATOK STREET 21 #07-09
SINGAPORE 659637**

Mailing Address:

-

Birth Date

08 Jul 1967

Registration Details

Previous Vehicle No.:

-

Effective Date of Ownership:

30 Jul 2018

Original Registration Date:

30 Jul 2018

Registration Date:

30 Jul 2018

No. of Transfers:

0

IU Label No.:

1128589207

Vehicle Specifications

Engine No.:

31765253B38A15A

Chassis No.:

WBA2D920505K81128

Year of Manufacture:

2018

Primary Colour:

White

Secondary Colour:

-

Passenger Capacity:

6