

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKV5188M
Accident Date : 29-Jun-2020

No. : 06189

Date : 06-Jul-2020

Our Ref : 020069 (AIG) / CHAN

PAGE : 1

LIN JYH FANG KELVIN
32 BUKIT BATOK STREET 21
#07-09
Singapore 659637

*Not Authorised
Resurvey After Paint
81090k 3days*

ESTIMATED COST OF REPAIR FOR BMW 216I GT LED NAV SMC9462X
=====

To repair and service rear rh rim

200.00 *150k*

To panel beating rear rh door, rh
fender, repair rear bumper, align &
refix rh rocker garnish

350.00 *280k*

To putty and spray rear rh door, rh
fender, rear bumper & rocker garnish

900.00 *660k*

Total : S\$ 1,450.00
=====

Singapore Dollars One Thousand Four Hundred and
Fifty Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: