

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9787 5558

Email: Samuel.auburnauto@gmail.com

Vehicle No: SMG5902Z

Model: Toyota Altis

QTY		Description	Repairer's Estimate	
Spare Parts - List Items				
1		Front bumper inner sponge X NN	\$	135.90
1		Front bumper side retainers / BR	\$	145.20
1		Front fender inner shield X SVC	\$	426.50
1		Front headlamp lower bracket X NN	\$	186.00
2		L/H and R/H Headlight Front Bumper / BR	\$	1,220.00
1		Bonnet Headlamp RH ?	\$	950.00
1		Front Left Passenger Rim X SVC	\$	420.00
1		Front R/H Fender X R SVC	\$	660.00
			\$	4,143.60

c/f: \$

9,616.90

S/N. Labour Charges

1	To establish mirror motor & reset wiring focussing	\$	210.00	X ^{NN}
2	To check wiring and reset headlamps focussing.	\$	30 320.00	
3	To apply tuff kote.	\$	30 330.00	
4	Panel beating.	\$	300 1,000.00	
5	To sand-down, patch-work, re-spray paint.	\$	400 1,000.00	
		\$	<u>2,860.00</u>	

Total Repair Cost: \$

7,003.60

Survey:

1st / 2nd / 3rd

(delete accordingly)

Surveyor Details:

(Name) Steve (LKK)

(Contact) _____

(Email) _____

(Signature) _____

(Date/Time) 25/8/20, 5.00pm

WIL Fijl

3 days

L/S

My AL Sky

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: