

# COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

DATE: 24.08.2020

3P INSURANCE: AIG ASIA (P/P)

MODEL: HYUNDAI IONIQ

SURVEYOR: NA

VEH NO.: SHB3311C

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Rear Wheel Cap (LH)	1		\$346.40
	SPARE PARTS SUB TOTAL			\$346.40
	LESS 20%			\$69.28
	DISCOUNTED SPARE PARTS TOTAL			\$277.12
	Rear Door APPS Sticker (LH)	1		\$80.00
	Supp → Fuel Lid (petrol only)	1		\$30
	NETT TOTAL			\$80.00
	SPARE PARTS & NETT TOTAL			\$357.12
	Panel Beating – Rear Door LH etc			\$300.00
	Spray Painting Charge – Rear Bumper, Rocker			\$1,000.00
	Panel Garnish LH & Rear Fender LH etc			\$60.00
	Tuff Kote			
	LABOUR TOTAL			\$1,360.00
	ESTIMATE TOTAL			\$1,717.12

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanjin @ 97495949  
 in p' 24/8/2020  
 v/p Resurvey after repair  
 2 days  
 Resurvey after w  
 Tanjin @ 97495949

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: