

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008928/EES3Q2
Date: 28/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993949
Claimant Vehicle No :	SMQ7983Z	Insured Vehicle No :	GBK1034P
Date of Loss:	23/08/2020	Nature of Claim:	TP
		Claim No:	4903950373SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ7983Z	Engine No:	L13A2288462
Make & Model:	HONDA FIT, 1.3 (A)	Chassis No:	GD12369246
Reg. Date:	05/02/2007 (Man. Year: 2006)	Odometer:	93476 km
Colour:	Black		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		3,608.00		
Nett Amount (S\$)	0.00	3,608.00	-3,608.00	
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	25/08/2020		
Date Inspected:	25/08/2020	Inspected At:	My Car Consultant Pte Ltd - Ubi (HQ) 53 Ubi Ave 1, #01-33 Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	0.0 days		

Adjuster: CHEN TSUE YEE

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$11,000.00

LTA REIMBURSEMENT VALUE (RV) : \$7,392.00

NETT VALUE : \$3,608.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >