

KIM CHWEE AUTO PTE LTD

Page 1 / 5

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

Estimate : 21934

Date : 20.08.2020

Vehicle Num : PD 108M

Make/Model : TOYOTA HIACE

Chassis/Engine no :

Accident Date : 07.08.2020

Claim No :

Reference : 0820-21934

Policy No :

not Authorized
LHR
Excess \$ 1500?
25/8/20

20 days 1/59
Chephel Attache

Qty	Particular	Amount S\$
-----	------------	------------

List Item :

1 pc Brake booster	11	\$ 633.00	X
1 pc Brake master pump	11	\$ 391.00	X
2 pc Front door @ 667.00	NLSBUC 015R	\$ 1,334.00	10c
2 pc Front door hinge @ 52.00	twilred	\$ 104.00	✓
1 pc Front door check LH	twi	\$ 69.00	✓
2 pc Front door rubber @ 104.00	NLS To.1	\$ 208.00	12c
1 pc Front door glass regulator LH	sent	\$ 113.00	✓
1 pc Front door glass regulator motor	Jun	\$ 242.00	✓
1 pc Front door glass run channel		\$ 104.00	?
1 pc Front door glass outer mldg	sent	\$ 67.00	✓
2 pc Front dooe step panel garnish @ 69.00	NLS D.S	\$ 138.00	12c
2 pc Front door lock @ 334.00	NLS Jun	\$ 668.00	12c
1 pc Front door side mirror assy	320	\$ 403.00	—
1 pc Front door board LH	D.S	\$ 552.00	—
2 pc Front door pillar (inner) @ 161.00	NLS D.S 015R	\$ 322.00	12c
1 pc Front door glass	shottard	\$ 207.00	✓
1 pc Front door frame lining strip LH	D.S	\$ 98.00	✓
1 pc Front door pillar inner garnish LH	D.S	\$ 69.00	✓
1 pc Front step panel LH	D.S	\$ 52.00	✓
1 pc Front wing mirror (small)	320	\$ 161.00	✓
1 pc Wire cover LH	one	\$ 98.00	✓
1 pc Front door speaker		\$ 322.00	?
1 pc Front door top panel	Andison	\$ 207.00	✓
1 pc Front door rear pillar	Andison	\$ 363.00	✓
1 pc Wire harness assy		\$ 1,288.00	—
1 pc Aircond cooling coil with heater unit		\$ 782.00	—
1 pc Aircond blower assy		\$ 460.00	—
1 pc Aircond blower by pass duct		\$ 121.00	—
1 pc Dashboard assy		\$ 633.00	—
2 pc Front wiper grille corner garnish @ 37.00		\$ 74.00	?
1 pc Dashboard reinforcement		\$ 437.00	—
1 pc Dashboard centre HI-FI cover		\$ 265.00	—
1 pc Dashboard compartment grove box (lower)		\$ 288.00	—
1 pc Dashboard compartment grove box cover (lower)		\$ 253.00	—
1 pc Dashboard centre lower cover		\$ 253.00	—
		\$ 11,779.00	

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

Page 2 / 5

Estimate : 21934

Date : 20.08.2020

Vehicle Num : PD 108M

Make/Model : TOYOTA HIACE

Chassis/Engine no :

Accident Date : 07.08.2020

Claim No :

Reference : 0820-21934

Policy No :

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Dashboard compartment grove box (top)	\$ 161.00
1 pc	Meter assy	\$ 1,426.00
1 pc	Aircond ventinator	\$ 75.00
1 pc	Abs pump	\$ 552.00
1 pc	Pump bracket	\$ 121.00
1 pc	Meter outer rim	\$ 248.00
1 pc	Abs brake pipe valve	\$ 205.00
1 pc	Steering column shaft	\$ 1,472.00
1 pc	Steering column shaft lower cover	\$ 161.00
6 pc	Abs pipe @ 144.00	\$ 864.00
1 pc	Sun visor LH	\$ 180.00
1 pc	Roof top lining	\$ 2,625.00
1 pc	Roof top panel	\$ 3,997.00
1 pc	Front fire wall panel support beam	\$ 207.00
1 pc	Front floor board panel	\$ 1,996.00
1 pc	Front fire wall panel	\$ 1,472.00
1 pc	Front fire wall panel sponge	\$ 213.00
1 pc	Front bonnet	\$ 288.00
1 pc	Front bonnet emblem	\$ 35.00
2 pc	Front bonnet hinge @ 41.00	\$ 82.00
1 pc	Front bonnet lock	\$ 64.00
1 pc	Front grille garnish (top)	\$ 110.00
1 pc	Front grille garnish (bottom)	\$ 207.00
1 pc	Front grille	\$ 219.00
1 pc	Front top panel	\$ 219.00
2 pc	Front head lamp @ 2128.00 LED	\$ 4,256.00
1 pc	Front bumper air grille	\$ 98.00
1 pc	Front support panel	\$ 276.00
1 pc	Front bumper centre inner plastic support	\$ 56.00
1 pc	Front bumper	\$ 225.00
2 pc	Front bumper fog lamp cover @ 41.00	\$ 82.00
2 pc	Front bumper reinforcement bracket @ 52.00	\$ 104.00
1 pc	Front bumper reinforcement	\$ 161.00
2 pc	Front bumper side retainer @ 60.00	\$ 120.00
1 pc	Front bumper top beam	\$ 110.00
		\$ 22,687.00

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

Page 3 / 5

Estimate : 21934

Date : 20.08.2020

Vehicle Num : PD 108M

Make/Model : TOYOTA HIACE

Chassis/Engine no :

Accident Date : 07.08.2020

Claim No :

Reference : 0820-21934

Policy No :

Qty	Particular	Amount S\$
<u>List Item : plastic</u>		
1 pc	Plastic clean exhaust chemical tank pump	\$ 1,093.00
1 pc	Plastic clean exhaust chemical tank	\$ 1,160.00
2 pc	Radiator side garnish (cowling) @ 57.00	\$ 114.00
1 pc	Radiator fan motor	\$ 184.00
1 pc	Radiator fan blade	\$ 64.00
1 pc	Radiator fan cowling	\$ 161.00
1 pc	Front wiper panel	\$ 368.00
1 pc	Air cleaner box assy	\$ 368.00
1 pc	Aircond condenser	\$ 598.00
1 pc	Radiator	\$ 863.00
1 pc	Aircond fan motor	\$ 184.00
1 pc	Aircond liquid pipe	\$ 294.00
1 pc	Aircond discharge hose	\$ 317.00
1 pc	Radiator spare tank	\$ 179.00
1 pc	Radiator top hose	\$ 65.00
2 pc	Radiator bottom hose @ 80.00	\$ 160.00
1 pc	Washer tank	\$ 64.00
1 pc	Washer tank motor	\$ 90.00
1 pc	Front windscreen	\$ 529.00
1 pc	Front windscreen mldg	\$ 64.00
1 pc	Front wiper motor	\$ 478.00
2 pc	Front corner panel @ 81.00	\$ 162.00
1 pc	Front wiper grille	\$ 276.00
2 pc	Front wiper arm @ 58.00	\$ 116.00
2 pc	Front wiper blade @ 42.00	\$ 84.00
1 pc	Front wiper linkage	\$ 190.00
1 pc	Front top arm LH	\$ 368.00
1 pc	Front knuckle arm LH	\$ 276.00
1 pc	Front wheel bearing LH	\$ 127.00
1 pc	Front wheel bearing hub LH	\$ 328.00
1 pc	Front lower arm	\$ 167.00
1 pc	Front stay arm LH	\$ 90.00
1 pc	Front passenger seat (lower) LH	\$ 903.00
1 pc	Front passenger seat rest LH	\$ 1,282.00
		\$ 11,766.00

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

Page 4 / 5

Estimate : 21934

Date : 20.08.2020

Vehicle Num : PD 108M

Make/Model : TOYOTA HIACE

Chassis/Engine no :

Accident Date : 07.08.2020

Claim No :

Reference : 0820-21934

Policy No :

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Safty belt LH <i>11</i>	\$ 830.00 <i>X</i>
1 pc	Safty belt RH <i>11</i>	\$ 830.00 <i>X</i>
1 pc	Airbag ECU <i>11</i>	\$ 1,323.00 <i>X</i>
1 pc	Console box	\$ 650.00 <i>?</i>
1 pc	Fuse box assy (main)	\$ 455.00 <i>?</i>
1 pc	Relay box assy (head lamp)	\$ 299.00 <i>?</i>
1 pc	Front door relay box holder (side) LH	\$ 56.00 <i>?</i>
1 pc	Sliding door (LH) <i>11</i>	\$ 748.00 <i>X</i>
1 pc	Turbo cooling cowl	\$ 88.00 <i>?</i>
1 pc	Turbo cooler	\$ 748.00 <i>?</i>
1 pc	Front cabin carpet	\$ 978.00 <i>?</i>
2 pc	Engine mounding @ 87.00	\$ 174.00 <i>?</i>
1 pc	Gear box mounting	\$ 75.00 <i>?</i>
2 pc	Head lamp balast @ 253.00 <i>11/13/10</i>	\$ 506.00 <i>12C</i>
List Item Total :		\$ 53,992.00
Cost Plus 10% :		\$ 5,399.20
		\$ 59,391.20

Special Nett Item :

1 pc	Front tyre LH	\$ 500.00 <i>?</i>
1 pc	Front wheel rim (LH) <i>11</i>	\$ 260.00 <i>X</i>
1 pc	ERP unit <i>11</i>	\$ 150.00 <i>X</i>
1 pc	ERP unit bracket <i>11</i>	\$ 30.00 <i>15</i>
1 pc	Front windscreen sealant <i>11</i>	\$ 100.00 <i>40</i>
20pc	Front bumper air grille clips @ 7.00 <i>11</i>	\$ 140.00 <i>30</i>
1 pc	Front number plate <i>11</i>	\$ 50.00 <i>X</i>
12pc	Front door inner board clips @ 7.00 <i>11</i>	\$ 84.00 <i>30</i>
1 pc	Front door company sticker lettering <i>11</i>	\$ 50.00 <i>X</i>
1 pc	Driver seat back board <i>11</i>	\$ 280.00 <i>X</i>
1 pc	Driver seat back safty bar <i>11</i>	\$ 400.00 <i>X</i>
Special Nett Total :		\$ 2,044.00

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

Page 5 / 5

Estimate : 21934

Date : 20.08.2020

Vehicle Num : PD 108M

Make/Model : TOYOTA HIACE

Chassis/Engine no :

Accident Date : 07.08.2020

Claim No :

Reference : 0820-21934

Policy No :

Qty	Particular	Amount S\$
<u>Labour Charge :</u>		
	To check wiring & reset fault core	\$ 450.00 200
	Towing	\$ 100.00 ✓
	Remove and replace radiator	\$ 11 100.00 X
	Remove and replace Aircond cendenser & refill gas	\$ 160.00 100
	Remove and replace front windscreen	\$ 160.00 120
	Remove and refix cushion seat, roof top lining etc	\$ 450.00 200
	To remove and replace spare part and panel beating	\$ 4,500.00 3000
	To spray painting and etc	\$ 2,800.00 1500
	To lift up engine & install parts	\$ 11 550.00 X
	Remove & refix under carriage suspension etc	\$ 550.00 ?
	Check wheel alignment	\$ 120.00 60
	Remove & refix petrol hose tank etc	\$ 11 120.00 X
	Remove & refix meter, dashboard & renew parts & wiring	\$ 650.00 250
	Labour Charge Total :	\$ 10,710.00

72,145.20

E & O. E

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Total Amount \$
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

KIM CHWEE AUTO PTE LTD