

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S :

Not Authorized
1/5 3200
26/8/20
3 days

Estimate No: ES1700704
 Date: 18 Aug 2020
 Policy No: DMCVSN1826771901
 Veh Reg No: XD2962E
 Make/Model: ISUZU CYZ52L
 Chassis No: JALCYZ52L87000066
 Engine No: 6WG1408610
 Reg. Date: 01/09/2008

ATTN: Motor Claim Department \ MEITING
 Your Ref No: LEI ENGINEERING P L
 Claim Type: Third Party
 Accident Date: 18/08/2020
 TP Veh Reg No: SMS9192R

Estimate Repair Cost to Vehicle No :XD2962E

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 Front Corner Panel - LH	566.80	1 PC	566.80	X
2 Front Corner Panel Rubber Seal - LH	88.40	1 PC	88.40	X
3 Front Bumper	1,597.70	1 PC	1,597.70	✓
4 Front Bumper Bracket - LH	221.00	1 PC	221.00	X
5 Front Bumper Top Step Garnish - LH	110.50	1 PC	110.50	✓
6 Front Bumper Top Center Step Garnish - LH	201.50	1 PC	201.50	X
7 Headlamp Assy - LH	434.20	1 PC	434.20	✓
8 Headlamp Bracket - LH	354.90	1 PC	354.90	X
9 Headlamp Rim - LH	127.40	1 PC	127.40	✓
10 Front Bumper Signal Lamp - LH/RH	208.00	2 PC	416.00	1 PC
11 Front Bumper Fog Lamp - LH/RH	551.20	2 PC	1,102.40	1 PC
12 Front Bumper Side Bracket - LH	227.50	1 PC	227.50	X
13 Front Bumper Lamp Bracket - LH	175.50	1 PC	175.50	X
14 Stand Panel - LH	694.00	1 PC	694.00	X
15 Stand Panel Alloy Mat - LH	286.00	1 PC	286.00	X
16 Step Garnish - LH	494.00	1 PC	494.00	✓
17 Step Garnish Cover - LH	494.00	1 PC	494.00	X
18 Step Garnish Alloy Mat - LH	386.00	1 PC	386.00	X
19 Step Alloy Bracket - LH	839.00	1 PC	839.00	X
20 Front Fender Signal Lamp - LH	134.00	1 PC	134.00	✓
21 Front Fender Panel - LH	563.00	1 PC	563.00	X
			9,513.80	
		Less 10% 157	951.38	8,562.42
Labour				
22 Labour to refocus & connect all lamp & wiring .	380.00	1 JOB	380.00	20
23 Labour charge to cut & weld & dismantle & remove & refit all parts	1,500.00	1 JOB	1,500.00	480
24 To spray & painting at accident affected area .	1,200.00	1 JOB	1,200.00	400
25 Torust proofing at affected area .	580.00	1 JOB	580.00	X
			3,660.00	3,660.00

P-3657
142
3108.45
4008.42

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S :

ATTN: Motor Claim Department \ MEITING
 Your Ref No: LEI ENGINEERING P L
 Claim Type: Third Party
 Accident Date: 18/08/2020
 TP Veh Reg No: SMS9192R

Estimate No: ES1700704
Date: 18 Aug 2020
Policy No: DMCVSN1826771901
Veh Reg No: XD2962E
Make/Model: ISUZU CYZ52L
Chassis No: JALCYZ52L87000066
Engine No: 6WG1408610
Reg. Date: 01/09/2008

Estimate Repair Cost to Vehicle No :XD2962E

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
			Total	S\$ 12,222.42
			Add GST @ 7%	855.57
			Total Amount Payable	S\$ 13,077.99

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND SEVENTY SEVEN AND CENTS NINETY NINE ONLY

**For MAH LIAN MOTOR VEHICLE
REPAIRER**

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: