

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Aug 2020 Edit Reg		25 Aug 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LOW JING HUI , ID: S7419457E									
Main Claimant: AM SWOMYNATHARR , ID: S2686134I									
Vehicle Reg. No.: SJB6241C		Date of Loss: 24/08/2020 00:00 - :59 [151 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 5398372128SG		Policy/Cover Note No.: 2100196309 (Comprehensive)							
Vehicle Reg. No. (Insured): SVJ6455Y		Policy No. (Claimant):							
		Excess:							
Repairer: Jementah Motor Works (HQ) 14 Defu Lane 10, #01-406, 539195 Defu Lane - Tel: 92996636									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chew, Mavis] Chew.Mavis@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/09/2020]									
Claimant's Solicitor: C YOGARAJAH LLC - Tel: 62925838									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (27/08/2020): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJB6241C (5398372128SG)**
[SJV6455Y]

TP

AM SWOMYNATHARR

Aug 24 2020 12:00AM

[LOW JING HUI]

Jementah Motor Works

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/08/20 10:24	General View	 Load JPG	☒
2	26/08/20 10:24	General View	 Load JPG	☒
3	26/08/20 10:24	General View	 Load JPG	☒
4	26/08/20 10:24	General View	 Load JPG	☒
5	26/08/20 10:24	General View	 Load JPG	☒
6	26/08/20 10:24	General View	 Load JPG	☒
7	26/08/20 10:24	General View	 Load JPG	☒
8	26/08/20 10:24	General View	 Load JPG	☒
9	26/08/20 10:24	General View	 Load JPG	☒
10	26/08/20 10:24	General View	 Load JPG	☒
11	26/08/20 10:24	General View	 Load JPG	☒
12	26/08/20 10:24	General View	 Load JPG	☒
13	26/08/20 10:24	General View	 Load JPG	☒
14	26/08/20 10:24	General View	 Load JPG	☒
15	26/08/20 10:24	General View	 Load JPG	☒
16	26/08/20 10:24	General View	 Load JPG	☒
17	26/08/20 10:24	General View	 Load JPG	☒
18	26/08/20 10:24	General View	 Load JPG	☒
19	26/08/20 10:24	General View	 Load JPG	☒
20	26/08/20 10:24	General View	 Load JPG	☒
21	26/08/20 10:24	General View	 Load JPG	☒
22	26/08/20 10:24	General View	 Load JPG	☒
23	26/08/20 10:24	General View	 Load JPG	☒
24	26/08/20 10:24	General View	 Load JPG	☒
25	26/08/20 10:24	General View	 Load JPG	☒
26	26/08/20 10:24	General View	 Load JPG	☒
27	26/08/20 10:24	General View	 Load JPG	☒
28	26/08/20 10:24	General View	 Load JPG	☒
29	26/08/20 10:24	General View	 Load JPG	☒
30	26/08/20 10:24	General View	 Load JPG	☒
31	26/08/20 10:24	General View	 Load JPG	☒
32	26/08/20 10:24	General View	 Load JPG	☒
33	26/08/20 10:24	General View	 Load JPG	☒
34	26/08/20 10:24	General View	 Load JPG	☒
35	26/08/20 10:24	General View	 Load JPG	☒
36	26/08/20 10:24	General View	 Load JPG	☒
37	26/08/20 10:24	General View	 Load JPG	☒
38	26/08/20 10:24	General View	 Load JPG	☒
39	26/08/20 10:24	General View	 Load JPG	☒
40	26/08/20 10:24	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
41	26/08/20 10:24	General View		Load JPG ☒
42	26/08/20 10:24	General View		Load JPG ☒
43	26/08/20 10:24	General View		Load JPG ☒
44	26/08/20 10:24	General View		Load JPG ☒
45	26/08/20 10:24	General View		Load JPG ☒
46	26/08/20 10:24	General View		Load JPG ☒
47	26/08/20 10:24	General View		Load JPG ☒
48	26/08/20 10:24	General View		Load JPG ☒
49	26/08/20 10:24	General View		Load JPG ☒
50	26/08/20 10:24	General View		Load JPG ☒
51	26/08/20 10:24	Odometer Reading		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	27/08/20 10:07	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20008949/GTF3S2**Date:** 31/08/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100196309
Claimant Vehicle No :	SJB6241C	Insured Vehicle No :	SJV6455Y
Date of Loss:	24/08/2020	Nature of Claim:	TP
		Claim No:	5398372128SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJB6241C	Engine No:	QG16425838
Make & Model:	NISSAN SUNNY, 1.6 EX (A)	Chassis No:	JN1CFAN16Z0109746
Reg. Date:	18/01/2008 (Man. Year: 2007)	Odometer:	178931 km
Colour:	Beige		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	25/08/2020		
Date Inspected:	25/08/2020	Inspected At:	Jementah Motor Works (HQ) 14 Defu Lane 10, #01-406 Singapore 539195
Estimated Period of Repair:	5.0 days		

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
4	1		*REAR BUMPER SPONGE	Deformed	0.00 F	*- F
5	1		*REAR BUMPER MOULDING	Cut	0.00 F	*- F
6	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
7	1		*REAR END PANEL	Buckled	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
10	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
11	1		*BOOTLID	Bent	0.00 F	*- F
12	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
13	1		*BOOTLID LOCK	Bent	0.00 F	*- F
14	1		*BOOTLID HINGE	Twisted	0.00 F	*- F
15	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
16	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)					0.00	0.00
-------------------	--	--	--	--	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >