

## REPAIR ESTIMATE

Tyre Brand: DunlopDATE: 24.08.20203P INSURANCE: TOK MAR (P/P)MODEL: HYUNDAI I40SURVEYOR: LKK-TAUFIKHVEH NO.: SHA9969XMVA: LIM T S

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Front Bumper Cover	1	841.76	\$1,052.20 <i>ok</i>
	Front Bumper Bracket Top (RH)	1		\$22.40 <i>ok</i>
	Front Bumper Side Bracket (RH)	1		\$24.60 <i>ok</i>
	Headlamp (RH)	1	1110.40	\$1,388.00 <i>ok</i>
	Front Fender (RH)	1	530.40	\$663.00 <i>ok</i>
	Radiator Grille H Emblem	1	31.60	\$39.50 <i>ok</i>
	Radiator Grille	1	1184.	\$1,480.00 <i>ok</i>
	SPARE PARTS SUB TOTAL			\$4,669.70
	LESS 20%		3648.16	\$933.94
	DISCOUNTED SPARE PARTS TOTAL			\$3,735.76
	Panel Beating – Bonnet ETC			\$600.00 <i>420.</i>
	Spray Painting Charge			\$750.00 <i>400</i>
	Wiring Charge			\$40.00 <i>30.</i>
	Tuff Kote			\$60.00 <i>30</i>
	TP MERIMEN		891	\$11.00 <i>ok</i>
	LABOUR TOTAL			\$1,461.00 <i>891</i>
	ESTIMATE TOTAL		4589.16 3 days #	\$5,196.76

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the

Taufik 97495749  
 'ok' 24/8/20 e 5pm  
 03 days  
 P/P Resurvey before paint.  
 Taufik e/ikhanawm

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: