



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

SOMPO INSURANCE SINGAPORE PL

Ref: CS3/SMO20008954/Ktf3e2

50 RAFFLES PLACE #05-01/06 SINGAPORE LAND
TOWER SINGAPORE 048623

Date: 11-11-2020



Code: SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKN 4188L	Veh. Inspected	SLR 6091K
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2002486/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	25/08/2020

2. Vehicle Particulars & Condition


Make & Model	TOYOTA WISH (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDGG20W30J007822	Colour	METALLIC PEARL WHITE
Odometer	112315 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	CONTINENTAL	8 mm
L/H Front Tyre	205/55 R16	CONTINENTAL	8 mm
R/H Rear Tyre	205/55 R16	CONTINENTAL	8 mm
L/H Rear Tyre	205/55 R16	CONTINENTAL	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.



5. General Information

Accident Date	14/08/2020	Inspect Date / Time	25/08/2020 (02:23 PM)
Survey held at	KUM CHEW MOTOR WORKSHOP 160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
 THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
 D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**

Report Ref No. CS3/SMO20008954/Ktf3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.