




## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20008957/T1vf3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 18-09-2020	
Code: INC4				
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SMN 5878Z	<b>Veh. Inspected</b>	SHA 5789A
	<b>Policy No.</b>	5112624286	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	MT/1101115-003	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>		<b>Assign Date</b>	24/08/2020
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	HYUNDAI I40	<b>c.c</b>	1685
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2014
	<b>Chassis No.</b>	KMHLB41UMEU053751	<b>Colour</b>	BLUE
	<b>Odometer</b>	735531	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	205/60 R16	WEST LAKE	6 mm
	<b>L/H Front Tyre</b>	205/60 R16	WEST LAKE	6 mm
	<b>R/H Rear Tyre</b>	205/60 R16	WEST LAKE	6 mm
	<b>L/H Rear Tyre</b>	205/60 R16	WEST LAKE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S, REAR O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	21/08/2020	<b>Inspection Date</b>	24/08/2020
	<b>Survey held at</b>	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>10 Working Days</b>	