

**\*AIR ESTIMATE\***

VEHICLE NO: SHA2902J *94 B21804*

DATE 11/08/20 12:00 AM

MAKE :

MODEL : HYUNDAI IONIQ G3

NTUC/CHIANG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$418.30 <i>Ry</i>
1	FRONT RADIATOR GRILLE			\$1,409.10 <i>Ry</i>
1	FRONT BUMPER MOULDING			<del>188 \$108.50</del> <i>int-</i>
	<b>SUB TOTAL</b>			<b>\$1,935.90</b>
	20.00%			\$387.18
	<b>DISCOUNTED TOTAL</b>			<b>\$1,548.72</b>
	<b>Labour Charge</b>			
	Panel Beating			\$480.00 <i>320</i>
	Spray Paint			\$250.00 <i>200</i>
	Check lighting			\$60.00 <i>X n n</i>
	<b>TOTAL LABOUR</b>		<i>520</i>	<b>\$790.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$2,338.72</b>
	<i>Tariffin 97495745</i>			
	<i>with 24/24/8/2005pc</i>			
	<i>2 days</i>			
	<i>1/2p Resurvey before paint</i>			
	<i>feather like work.</i>			
			<i>188</i>	
			<i>20% - 150.40</i>	
			<i>670.40</i>	
			<i>2 days</i>	
			<i>#</i>	
				2,402.32#

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: