



# CAS GARAGE PTE LTD

(Reg No: 201828067/M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

## VEHICLE REPAIR ESTIMATE

Insurance Company: INDIA INTERNATIONAL INSURANCE

(MOTOR CLAIMS DEPARTMENT)

Address: NO 64, CECIL STREET, #04-05  
IOB BUILDING, S(049711)

*Xiao Tong*

Telephone: 63476100 Fax: 62244174

Email: [motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)

Make/ Model : HYUNDAI AVANTE

Date: 24.08.2019

Chassis No : KMHD841CMLU965195

Vehicle No: SMU390J

Date/Time of Accide 20.08.2020/ 1030

Reg date : 17.10.2019

### Materials Cost/ Spare Parts Cost

#### TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	FRONT BUMPER <i>Repld.</i>	1	\$ 785.80	<i>528</i>	\$ ✓ 785.80
2	FRONT BUMPER TOP BRACKET RH <i>new</i>	1	\$ 98.60		\$ + 98.60
3	FRONT BUMPER SIGNAL LAMP RH <i>exchd</i>	1	\$ 165.80		\$ ✓ 165.80
4	FRONT BUMPER RETAINER RH <i>new</i>	1	\$ 86.90		\$ ✓ 86.90
5	FRONT BUMPER AIR GUIDE RH <i>exchd</i>	1	\$ 125.80		\$ ✓ 125.80
6	FRONT BUMPER SIDE STRIP RH <i>new</i>	1	\$ 92.60		\$ + 92.60
7	FRONT BUMPER SIDE COVER RH <i>exchd</i>	1	\$ 98.60		\$ ✓ 98.60
8	FRONT BUMPER LOWER LIP <i>new</i>	1	\$ 295.60		\$ + 295.60
9	FRONT BUMPER LOWER COVER <i>exchd</i>	1	\$ 202.30		\$ + 202.30
10	FRONT ENGINE UNDER COVER <i>exchd</i>	1	\$ 356.80		\$ + 356.80
11	FRONT BUMPER SPONGE <i>new</i>	1	\$ 225.60		\$ + 225.60
12	FRONT BUMPER LOWER STIFFENER <i>new</i>	1	\$ 175.20		\$ + 175.20
13	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 589.50		\$ + 589.50
14	FRONT BUMPER RADIATOR GRILLE <i>new</i>	1	\$ 1,123.70		\$ + 1,123.70
15	FRONT SUPPORT PANEL <i>new</i>	1	\$ 950.80		\$ + 950.80
16	FRONT SUPPORT PANEL TOP GARNISH <i>new</i>	1	\$ 202.50		\$ + 202.50
17	FRONT HEADLAMP RH <i>lt</i>	1	\$ 1,756.40		\$ ✓ 1,756.40
18	FRONT HEADLAMP BRACKET RH <i>new</i>	1	\$ 98.60		\$ + 98.60
19	FRONT BONNET <i>new</i>	1	\$ 1,498.50		\$ + 1,498.50
20	FRONT FENDER RH <i>Repis</i>	1	\$ 985.60		\$ + 985.60
21	FRONT FENDER INNER COWLING RH <i>new</i>	1	\$ 189.50		\$ + 189.50
<b>Total List Price Cost</b>					<b>\$ 10,104.70</b>

PARTS DISCOUNT 20% \$ 8,083.76

*2761.5*

*2209.20*

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT FENDER INNER COWLING CLIPS <i>new</i>	1 SET	\$ 30.00	\$ <del>30.00</del> + 30.00
2	FRONT BUMPER CLIPS <i>new</i>	1SET	\$ 30.00	\$ <del>30.00</del> + 30.00
3	FRONT NUMBER PLATE WITH CASING <i>new</i>	1SET	\$ 50.00	\$ <del>50.00</del> + 50.00
4	FRONT ENGINE UNDERCOVER CLIPS <i>new</i>	1SET	\$ 30.00	\$ <del>30.00</del> + 30.00
5	FRONT BUMPER LOWER LIP <i>new</i>	1SET	\$ 450.00	\$ <del>450.00</del> + 450.00
6	FRONT ENGINE UNDERCOVER <i>new</i>	1SET	\$ 30.00	\$ <del>30.00</del> + 30.00
<b>Total Special Nett Items</b>				<b>\$ 620.00</b>

30

Labour Works/ Panel Beating Related Works		Quotation
<b>Job Scope</b>		
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN, STRAIGHTENED MEMBER		\$ <del>1,600.00</del>
		300
<b>Spray Painting</b>		
<b>Job Scope</b>		
TO RESPRAY AFFECTED AREAS		\$ <del>1,200.00</del>
		400
<b>Others Cost (Accident Repair Related Expenses)</b>		
<b>Job Scope</b>		
TO TUFFCOAT AFFECTED AREA		\$ <del>150.00</del>
TO REMOVE / REFIT CONDENSER AND TOP UP GASTO REPLACE FRONT SUPPORT		\$ <del>120.00</del>
TO REMOVE/ REFIT WIRING CHECKS FOR HEADLAMP		\$ <del>150.00</del>
<b>Total Others Cost</b>		\$ 420.00
<b>GRAND TOTAL</b>		<b>\$ 11,923.76</b>

730

**CAS GARAGE PTE LTD**  
 UEN 201828067M  
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,  
 SINGAPORE 417883

Adrian G  
 L/S 25/08/20  
 04 Pags.

CAS GARAGE PTE LTD

Person Incharge: Allan  
 Direct Contact: +65 8782 7171  
 Email: allangoh.cas@gmail.com  
 Fax : 6509 9501

Total: 2969.20  
 L/S: 2350 ✓

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: