

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 22.08.2020

3P INSURANCE: NTUC

MODEL: HYUNDAI IONIQ

SURVEYOR: LKK

VEH NO.: SHC3361C

MVA: JUMANI

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Front Bumper Cover			\$418.30
	Front Wheel Hub Cap (RH)			\$346.40
	SPARE PARTS SUB TOTAL			\$764.70
	LESS 20%			\$152.94
	DISCOUNTED SPARE PARTS TOTAL			\$611.76
	Panel Beating			\$400.00
	Spray Painting			\$500.00
	CHECK WIRING			\$50.00
	LABOUR TOTAL			\$950.00
	ESTIMATE TOTAL			\$1,561.76

346.40
 277.12
 750
 \$1027.12
 2 days #

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Partly work.

Tanghi 77495749

'wp' 24/8/2020

2 days

P/p team after repair
Tanghi (Kantoon)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: