



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI18007761/Gsf3s2-1

C/O: COMLAW LLC

64 CECIL ST #06-01 IOB BLDG SINGAPORE  
049711

Date : 19-10-2020



Code : CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SKP 2016C	<b>Veh. Inspected</b>	SJQ 5323C
<b>Policy No.</b>	DMPCSN3047111802	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	SNM18D02144C02	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	BIJIAO	<b>Assign Date</b>	18/08/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MAZDA 3 1.6 L	<b>c.c</b>	1598
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	JM6BL10Z1A0105478	<b>Colour</b>	GREY
<b>Odometer</b>	178193	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	205/55 R16	BRIDGESTONE	8 mm
<b>L/H Front Tyre</b>	205/55 R16	BRIDGESTONE	8 mm
<b>R/H Rear Tyre</b>	205/55 R16	BRIDGESTONE	8 mm
<b>L/H Rear Tyre</b>	205/55 R16	BRIDGESTONE	8 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.
--

### 5. General Information

<b>Accident Date</b>	26/04/2018	<b>Inspection Date</b>	27/04/2018
<b>Survey held at</b>	NEO AUTOMOTIVE PTE LTD 53 UBI AVE 1 #05-44 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>14 Working Days</b>
-------------------------------------	------------------------