

**MODERN AUTOMOTIVE PTE LTD**  
**BLK 3023A UBI ROAD 1 # 01-61**  
**SINGAPORE 408717**

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

**EQ Insurance Co. Ltd**

22 Gemmill Lane  
Singapore 069257  
Tel : 6223 - 9433  
Fax : 6224 - 3903

**Quotation**

DATE : 01.09.2020  
VEH NO : GBJ1594U  
MODEL : Mit L200 D/Cab  
D O A : 24.08.2020  
YR REF : GBG8835U

*Geilic*

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

**RE : ESTIMATE FOR ACCIDENT REPAIR GBJ1594U (MITSUBISHI L200)**

| <u>Item</u>        | <u>Description</u>                             | <u>Qty</u> | <u>Amt</u>          |
|--------------------|------------------------------------------------|------------|---------------------|
| <b>NO</b>          | <b>LIST ITEMS</b>                              |            |                     |
| 1                  | Rear Number Plate Lamp - LH & RH <i>HL New</i> | 2          | 116.00 <i>X</i>     |
| 2                  | Stopper - LH & RH <i>LH ut</i>                 | 2          | 84.00 <i>42</i>     |
| 3                  | Tailgate <i>Distorted</i>                      | 1          | 1,465.00 <i>✓</i>   |
| 4                  | Tailgate Lamp <i>new</i>                       | 1          | 89.00 <i>X</i>      |
| 5                  | Tailgate Outer Handle <i>new</i>               | 1          | 121.00 <i>X</i>     |
| 6                  | Tailgate Lock <i>Tamed</i>                     | 1          | 155.00 <i>✓</i>     |
| 7                  | L200 emblem <i>new</i>                         | 1          | 68.00 <i>✓</i>      |
| 8                  | Sportoro emblme <i>new</i>                     | 1          | 85.00 <i>✓</i>      |
| 9                  | Mitsubishi Logo <i>new</i>                     | 1          | 62.00 <i>✓</i>      |
| 10                 | DID Emblem <i>new</i>                          | 1          | 42.00 <i>✓</i>      |
| 11                 | cycle and carriage logo <i>new</i>             | 1          | 38.00 <i>✓</i>      |
| 12                 | Tailgate Lower Panel <i>Repair</i>             | 1          | 665.00 <i>X</i>     |
| 13                 | Tail Lamp - LH & RH <i>LH cracked</i>          | 2          | 790.00 <i>395</i>   |
| 14                 | Rear Body Panel - LH <i>Distorted</i>          | 1          | 2,880.00 <i>✓</i>   |
|                    |                                                |            | <hr/>               |
|                    |                                                |            | \$ 6,660.00         |
| Less 10%           |                                                |            | <del>(666.00)</del> |
|                    |                                                |            | <hr/>               |
|                    |                                                |            | \$ 5,994.00         |
| <br>               |                                                |            |                     |
| <b>S/NET ITEMS</b> |                                                |            |                     |
| 1                  | Rear Number Plate <i>Best</i>                  | 1          | 30.00 <i>✓</i>      |
| 2                  | Rear Number Plate Holder <i>del</i>            | 1          | 30.00 <i>✓</i>      |
| 3                  | Reverse Sensor <i>Day 2</i>                    | 1          | 280.00 <i>200</i>   |
| 4                  | 70km/h sticker <i>new</i>                      | 1          | 15.00 <i>✓</i>      |
|                    |                                                |            | <hr/>               |
|                    |                                                |            | \$ 355.00           |
| <br>               |                                                |            |                     |
| <b>Total Parts</b> |                                                |            | <hr/>               |
|                    |                                                |            | \$ 6349.00          |

*5232*  
*4708-80*

*275*

**RE : ESTIMATE FOR ACCIDENT REPAIR GBJ1594U (MITSUBISHI L200)**

**LABOUR CHARGE**

|              |                                                         |                 |                    |
|--------------|---------------------------------------------------------|-----------------|--------------------|
| 1            | To knocking & pull out rear portion & renew above parts | <del>1800</del> | <del>1000</del>    |
| 2            | To putty & spray up paint works                         | <del>1400</del> | <del>1100</del>    |
| 3            | To check wiring                                         | <del>50</del>   | <del>30</del>      |
| 4            | To under seal                                           | <del>150</del>  | <del>100</del>     |
| 5            | To remove body panel top railing                        | 2740            | <del>150</del> 60  |
| 6            | To remove reverse sensor                                |                 | <del>100</del> 50  |
| 7            | To remove rear deck to facilitate repairs.              |                 | <del>600</del> 400 |
| Total Labour |                                                         | \$              | 3650.00 -          |
| Grand Total  |                                                         | \$              | 9999.00            |

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Total: 7723.80 (P/P)  
07 Days.