



# SMA8353U

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)  
60 Jalan Lam Huat #03 - 35/36, Singapore (737869)  
Tel : 6358 3031 | Fax No : 6694 4929

## ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING  
OWN INSURER : AXA  
CLAIM TYPE : TP  
Date of Accident : 24/8/2020

Vehicle Reg. No. : SMA8353U  
Vehicle Reg. Date: 21-Jun-2018  
Make / Model : HYUNDAI ELANTRA AD 1.  
Engine No. : G4FGJU205884  
Chassis No. : KMHD841CMJU705121

## COST OF CLAIMS

Parts Cost / List Items : \$ 15,189.11  
Plus/Less 20% \$ -  
Total Cost / List : \$ 12,151.29  
Special Nett Items : \$ 50.00  
Total Parts Amount : \$ 50.00  
Total Labour Amount : \$ 4,500.00  
Gross Total : \$ ~~4,550.00~~ 16,701.29  
GST % : 7% \$ 318.50  
Nett Amount : \$ 4,868.50

## Surveyor Name and Company :

\_\_\_\_\_

Date of survey : \_\_\_\_\_

Part by Part / Lump Sum : \_\_\_\_\_ days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : \_\_\_\_\_

Fax No : \_\_\_\_\_

HP No : \_\_\_\_\_

This claim is handled by : PAULO

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

60 Jalan Lam Huat #03 - 35/36, Singapore (737869)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SMA8353U  
 Vehicle Reg. Date: 21/6/2018  
 Make / Model : HYUNDAI ELANTRA AD 1.6 GLS AT (AMS)  
 Engine No. : G4FGJU205884  
 Chassis No. : KMHD841CMJU705121

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	BONNET	XR	\$1,910.30		
2	2	BONNET HINGES LH/RH	XSVC	\$ 98.20		
3	1	BONNET HEAT INSULATOR	XSVC	\$ 221.10		
4	1set	BONNET HEAT INSULATOR CLIPS	XSVC	\$ 20.00		
5	1	BONNET LOCK	XSVC	\$ 129.90		
6	1	FRONT BUMPER	/CR4	\$ 474.40		\$ 474.40 ✓
7	1set	FRONT BUMPER CLIPS	/NPC	\$ 25.00		\$ 25.00 ✓
8	2	FRONT BUMPER RETAINER LH/RH	/NPC	\$ 56.00		\$ 56.00 ✓
9	1	FRONT BUMPER CENTER RUBBER	XSVC	\$ 29.40		
10	1	FRONT BUMPER GRILL LOGO	/NPC	\$ 25.00		\$ 25.00 ✓
11	1	FRONT BUMPER GRILL	/CRA	\$ 495.80		\$ 495.80 ✓
12	1	FRONT BUMPER LOWER GARNISH	XSVC	\$ 127.00		
13	1	FRONT BUMPER STIFFENER	/CR4	\$ 63.70		\$ 63.70 ✓
14	1	FRONT BUMPER SPONGE	/CR4	\$ 110.70		\$ 110.70 ✓
15	1	FRONT BUMPER REINFORCEMENT	XR	\$ 695.80		
16	1	FRONT SUPPORT PANEL	XSVC	\$ 949.30		
17	1	FRONT SUPPORT TOP COVER	/CR4	\$ 77.10		\$ 77.10 ✓
18	1set	FRONT SUPPORT TOP COVER CLIPS	/NPC	\$ 25.00		\$ 25.00 ✓
19	2	FOG LAMP LH/RH	XSVC	\$ 530.20		
20	2	FOG LAMP CHROME RING LH/RH	XSVC	\$ 230.80		
21	2	FOG LAMP GARNISH LH/RH	XSVC	\$ 130.00		
22	1	TOW HOOK COVER	/SCR	\$ 25.00		\$ 25.00 ✓
23	1	FRONT UNDERNEAT COVER	XSVC	\$ 173.29		
24	1set	FRONT UNDERNEAT COVER CLIPS	XSVC	\$ 25.00		
25	2	HEAD LAMP LH/RH	/CRA	\$2,397.60		\$1,198.80 ✓
26	2	HEAD LAMP RUBBER LH/RH	XSVC	\$ 127.00		
27	2	HEAD LAMP LOWER BRACKET LH/RH	/CRA	\$ 75.40		\$ 37.70 ✓
28	2	FRONT FENDER LH/RH	XSVC	\$2,455.40		
29	2	FRONT FENDER INNER SHIELD LH/RH	XSVC	\$ 205.68		
30	2set	FRONT FENDER INNER SHIELD CLIPS	XSVC	\$ 40.00		
31	1	WASHER TANK	XSVC	\$ 70.80		
32	1	CONDENSER	XSVC	\$ 745.10		
33	1	RADIATOR	XSVC	\$ 510.50		
34	1	AIRCON PIPE	XSVC	\$ 257.00		
35	1	AIRCON SUCTION PIPE	XSVC	\$ 630.30		
36	1	AIRCON DISCHARGE PIPE	XSVC	\$ 200.20		
37	1	FAN COWLING	XSVC	\$ 567.50		
38	1	FAN MOTOR	XSVC	\$ 235.00		
39	1	FRONT NUMBER PLATE BASE	/CR4	\$ 23.64		\$ 23.64 ✓
40	1	FRONT NUMBER PLATE	/BD		\$ 50.00	\$ 23.64 ✓
				\$ 50.00	\$ 2,637.84	35



**Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)**

60 Jalan Lam Huat #03 - 35/36, Singapore (737869)

Tel : 6358 3031 | Fax No : 6694 4929

**FINALIZATION FORM**

**ATTN TO:** LKK - SUN PIN  
Surveyor Name and Company

Date of Accident : **24/8/2020**

**BILL TO:** CHINA TAIPING  
TP Insurer

**VEHICLE REG. NO.**

**TYPE OF CLAIM:** TP

**SMA8353U**

**Make / Model :** HYUNDAI ELANTRA AD 1.6 GLS AT (AMS)

**COST OF CLAIMS**

**Parts Cost / List :** \$ 2,637.84

**Supp. Parts :** \$ -

**Special Nett :** \$ 50.00

**Total Parts :** \$ 2,160.27

**Total Labour :** \$ 1,060.00

**TOTAL REPAIR COST :** \$ 3,220.27

Total Parts Cost/List :	\$	2,637.84
Plus / Less : 20%	\$	527.57
<b>Total :</b>	<b>\$</b>	<b>2,110.27</b>

Lump Sum Discount : 20%	\$	644.05
<b>Lump Sum Amount:</b>	<b>\$</b>	<b>2,576.22</b>

**Final Lump Sum Amount :** \$ 2,550.00

**No. of Repair Days:** 4

Submitted by / Date : PAULO

Confirmed by / Date : \_\_\_\_\_