



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4051K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	TO REPAIR SEE LABOUR	418.30	-
1	FRT FENDER LH	BENT	490.70	490.70
1	FRT BUMPER MOULDING LH	NOT NECESSARY	93.60	-
1	HEADLAMP LH	NOT NECESSARY	1,993.65	-
1	FRT WHEEL CAP LH	CUT	346.40	346.40
1	FRT FENDER BLUE DRIVER LH	NECESSARY	26.60	26.60
	LESS 20% DISCOUNT		-673.85	-172.74
			2,695.40	690.96
	<u>NETT ITEMS</u>			
1	FRT DOOR COMFORTDEGRO LH (N)	NECESSARY	75.00	75.00
	LESS 10% DISCOUNT		-7.50	-7.50
			67.50	67.50
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT BUMPER.		700.00	480.00
	SPRAY PAINT CHARGE.		750.00	600.00
1	CHECK ALL LIGHTING.		40.00	30.00
	TUFF COAT ON AFFECTED PARTS.		60.00	30.00
	WHEEL ALIGNMENT.		120.00	80.00
			1,670.00	1,220.00
GRAND TOTAL			4,432.90	1,978.46
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,978.46

Report Ref No. NS/INC20009014/T1tf3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.