



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:PETER			Ref: CC4/ASM20009024/Db3q2 Date: 08/03/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKE 6934J	Veh. Inspected	FBD 8818K
	Policy No.	VPA/P1503877	Coverage (\$)	0.00
	Claim No.	S0M02QLH	Excess (\$)	0.00
	Assign From		Assign Date	26/08/2020
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA T135	c.c	135
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	5YP011204	Colour	RED / BLACK
	Odometer	-	Steering	AFFECTED
	Brakes	AFFECTED	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	80/90 R17	PIRELLI	2 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	90/80 R17	PIRELLI	2 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION,N/S AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	10/07/2020	Inspection Date	27/08/2020
	Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	