

ASSIGNMENT

COE Sept 2020

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBD 8818K Yr Regn: Sept 2009

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha T135 C.C. 135

Colour Red / Black A/C: Insured / Std / NI / NA

Sp. Reading N.A. T/Radio: Insured / Std / NI / NA

Eng/No: 5YP011204

C/No: 5YP011204

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / SRim STD A/Rim or

Tyre Size: F: 80/90 717

R: 90/80 717

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 2 mm R/Bal. 2 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 10/07/2020 D.O.A. 27/08/2020

Survey held at SG 98 AMK

Des. of Damages: Fri / Rear / O/S / N/S / U/C / Rooftop or

Rent 7 4/8 Pann 9 o/s Pann.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>AxA. SKE 69345</u>
	<u>MV 7K</u>
	<u>LTA 2.8K</u>
	<u>HL 4.2K</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Photos

Others

TOTAL

Report Format: _____

Lump Sum / L.B.I. (\$) _____

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 27 August 2020

To : LKK

Attn : Bryan

By Fax: 6256-4315

Tel: 97237799

VEHICLE NO : FBD 8818K

Yamaha LC 135

ACCIDENT DATE: 10 July 2020

Description	Qty	Quotation \$	
1 Front Mudguard <i>broken</i>	1	185.00	✓
2 Front Rim <i>broken</i>	1	250.00	✓
3 Brake Disc <i>1st</i>	1	200.00	✓
4 Brake Pump <i>HH</i>	1	250.00	X
5 Fork Tube <i>1st</i>	1 set	350.00	✓
6 Fork Underbracket <i>1st</i>	1	190.00	✓
7 Fork Oil Seal <i>Hel</i>	1	125.00	✓
8 Radiator <i>1st</i>	1	490.00	✓
9 Handle Bar <i>1st</i>	1	125.00	✓
10 Handle Bar Bracket <i>1st</i>	1	155.00	✓
11 Head Lamp <i>broken</i>	1	320.00	✓
12 Head Lamp Cover <i>broken</i>	1	190.00	✓
13 Front Signal Lamp <i>broken</i>	2	150.00	✓
14 Meter Cover <i>broken</i>	1	120.00	✓
15 Front Panel Centre <i>broken</i>	1	190.00	✓
16 Front Side Panel L/RH <i>broken</i>	2	290.00	✓
17 Inner Leg Shield <i>broken</i>	1	135.00	✓
18 Side Panel Inner Holder <i>broken</i>	2	200.00	✓
19 Ignition Switch <i>HH</i>	1	180.00	X
20 Mirror <i>broken</i>	1 set	120.00	✓
21 Centre Garnish Cover <i>broken</i>	1	165.00	✓
22 Centre - V Panel <i>broken</i>	2	160.00	✓
23 Rear Tail Panel LH/RH <i>Cnt</i>	2	270.00	✓
24 Exhaust Pipe <i>1st</i>	1	250.00	✓
25 Exhaust Guard <i>HH</i>	1	190.00	X
26 Engine Cover RH <i>HH</i>	1	220.00	X
27 Footrest <i>SVL</i>	1	65.00	X
28 Rear Tail Lamp <i>HH</i>	1	165.00	X
29 Rear Mudguard <i>HH</i>	1	185.00	X

Sub-Total	5,885.00
Less 10%	588.50
Sub-Total	5,296.50

VEHICLE NO : FBD 8818K

Yamaha LC 135

Nett Items

1	Rear number plate broken ^{Runt}	15.00	✓
2	Rear box Out	180.00	✓
3	Towing fee NH	50.00	X
4	Remove & replace parts, align & etc	350.00	200/-
5	Remove & replace fork assy, rim, brake pump & disc, supply brake oil, etc	200.00	150/-
6	Re-connect harness wiring	120.00	20/-
7	Supply body set decal sticker	120.00	80/-
8	Align body frame	280.00	150/-

Special Nett Items

- 1 Meter Assy ~~broken~~

650.00 ✓
~~280.00~~

Sub-Total 1,595.00
Nett Total 6,891.50

NB: This estimate was made from a visual inspection only. any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion.
Thank you

S9 MOTOR TRADING PTE LTD

:LG

Repair Limit: 3,500.00

27/08/2020 @ 1000hrs

Not Available

Assume 5 days.

LKK Auto

2/12/2020.
Re-inspected
done by LKK-Bryane
LH-Q

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--