

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gerald Poh

Date: 27 Aug 2020

Preliminary Advice

Vehicle No	: GX892H	Accident Date	: 09/08/2020
Make	: NISSAN CABSTAR	Policy No.	: Z/20/VC00/107557
Assignment Date	: 26/08/2020	Excess	: S\$1,200.00
Date of Inspection	: 27/08/2020	Est. Duration of Repair	: 14
Inspection At	: K KIM HIN AUTO PTE LTD (HQ) 160 SIN MING DRIVE #02-20, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,107.45
Revised Amount	:S\$	14,842.95
Check Items (Estimated)	:S\$	13,353.25
Total	:S\$	28,196.20

Lump Sum Repair	:S\$	15,800.00
-----------------	------	-----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	36,000.00
COE / PARF Rebate	:S\$	19,782.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,218.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER AGREED TO REPAIR THE VEHICLE NOT MORE THAN \$15,800.00 ON LUMP SUM BASIS.