

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 31 August 2020 9:44 AM
To: simon@kkimhin.com.sg; service@kkimhin.com.sg
Cc: SUR
Subject: RE: GX 892H - LONPAC

Dear Simon,

As spoken with you.

Please proceed to repair the insured vehicle **GX 892H** at repair cost not more than \$15,800.00 on Lump Sum basis (Excess \$1,200/-).

Kindly arrange re-survey for check items.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Friday, 28 August 2020 2:36 PM
To: simon@kkimhin.com.sg; service@kkimhin.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: GX 892H - LONPAC

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **GX 892H** (Excess \$1,200/-). **LUMP SUM REPAIR**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)