	2000 9027/Kg
Kenneth	ASSIGNMENT
From: Date:	
Estimated Cost	Veh No: GX 89211 Yr Regn: 07,
SO 170 1WS 1 TP RES 1 OD RES 1 EVA / INV 1 MV	Taxl / Prime Mover /
To Inspect Vehicle No:	Truck / Trailer or
at Workshop m/s /C/c 14m	Make: NS Cobsta c.c 295
ol / C//	TO THE MISSIEGISTOINITY
Insured:	Sp.Reading 158254 T/Radio: Insured / Std / NI / N.
Policy No Z/20/VC00/107557	Eng/No:
Claims No. 20/20/20/VC00/023571	C/No: JNISC 21= 24 7-08 58 93
Sum Insured: Excess: 1200	Och. Cond. Good / Fair / Poor / Burnt
(Client's Record)	Commed / Leaked / Burnt or
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: MI SIRIM / STD A/RIM or
(Policy Condition)	Tyre Size: WNYX 185 R15 X8
Pemark: The veh had commenced to	Green Max 165R 15x8(D)
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Bal. or Market Value: 8 36K	1 1040140KO ot
IDAC Accident Rport: Consistent? : Yes or No	Fron! Rear
GIA / PR Seen: Consistent?: Yes or No	R/Bal. 0 mm R/Bal. 6 6 mm
Est Repairs: 19 days Res.: Yes or No	L/Bal. 0 mm L/Bal. 0 mm
Lum Sum: 20 % 3 Val.: Yes or No	D.O.A. 4/8/20 D.O.I. 27/8/20
	Survey held at
Vehicle: IN COUR	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Person Contacted:	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
VEHICLE NOT MORE THAN \$15,800.00 C 28/08/20@2.29pm Chew Beng Kee informe	N LUMP SUM BASIS.
VEHICLE NOT MORE THAN \$15,800.00 C 28/08/20@2.29pm Chew Beng Kee informe 28/0820@2.36pm Informed Simon C/A not	on LUMP SUM BASIS. ed C/A at \$15800 via Merimen. more than LS \$15800 & ex:\$1200 by email. ays Of Repair:
VEHICLE NOT MORE THAN \$15,800.00 C 28/08/20@2.29pm Chew Beng Kee informe 28/0820@2.36pm Informed Simon C/A not	on LUMP SUM BASIS. ed C/A at \$15800 via Merimen. more than LS \$15800 & ex:\$1200 by email.
VEHICLE NOT MORE THAN \$15,800.00 C 28/08/20@2.29pm Chew Beng Kee informed 28/0820@2.36pm Informed Simon C/A not interfire, File Pass to? : Prell. Report District Plant Report Restart Restart Report Restart Report Restart Res	more than LS \$15800 & ex:\$1200 by email. ays Of Repair: Survey No. of Trip: Survey Fee:
VEHICLE NOT MORE THAN \$15,800.00 C 28/08/20@2.29pm Chew Beng Kee informe 28/0820@2.36pm Informed Simon C/A not	ays Of Repair: Survey No. of Trip: Survey Fee: Transportation: Site Insp (\$) S. FS. SI
VEHICLE NOT MORE THAN \$15,800.00 C 28/08/20@2.29pm Chew Beng Kee informe 28/0820@2.36pm Informed Simon C/A not Display Time, File Pass to? : Prell. Report : Final Report Add Fee:	ays Of Repair: Survey No. of Trip: Survey Fee: Interview (\$) Survey Fee: Surv
VEHICLE NOT MORE THAN \$15,800.00 C 28/08/20@2.29pm Chew Beng Kee informe 28/0820@2.36pm Informed Simon C/A not Prell. Report Discontinuo Prell. Report Repor	ays Of Repair: Site Insp (\$) Interview (\$) Tech Invs (\$) Survey BASIS. Merimen. Survey Merimen. Survey Fee: Transportation: Survey Fee: Transportation: Survey Fee: Transportation: Tech Invs (\$)
VEHICLE NOT MORE THAN \$15,800.00 C 28/08/20@2.29pm Chew Beng Kee informe 28/0820@2.36pm Informed Simon C/A not Control of the Pass to? Prell. Report December	ays Of Repair: Survey No. of Trip: Survey Fee: Interview (\$) Tech Invs (\$
VEHICLE NOT MORE THAN \$15,800.00 C 28/08/20@2.29pm Chew Beng Kee informe 28/0820@2.36pm Informed Simon C/A not Prell. Report Discourse Discours	ays Of Repair: Site Insp (\$) S-RS_SI Interview (\$) Ofters



CO. REG. NO: 199402370D GST NO: M2-0123250-3

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722 Tel: 6452 7018 Fax: 6458 3895 Email: service@kkimhin.com.sg

INSURER:

Lonpac Insurance Bhd (HQ)

PARTICULARS OF CLAIM

Claim Type:

OD (OWN DAMAGE)

Policy No: Vehicle Reg. No.:

Z/20/VC00/107557

Driver Age/Info:

GX892H 47 / MALE

TP Injury Involved?

NO

Insured/Claimant-

DONG CONSTRUCTION & ENGINEERING PTE LTD

Driver:

TAN SIM HUA

Make/Model:

NISSAN CABSTAR, 3.0 5M/T ABS 2DR Vehicle Reg. Date:

Vehicle Colour:

WHITE

Engine No: Odometer:

ZD30013934N

0 KM

Paint Type:

Total Loss?

Remarks:

NO

Est. Duration of Repair (day) 18 /4 day

RT NIT

Ref. No:

Date of Loss:

Party At Fault:

Third Party Involved? YES

Driveable?

ZD30013934N

Amount 23,827.45

0.00

0.00

0.00

28/07/2016

09/08/2020

UNKNOWN

Description of Accident/Loss

PLEASE REFER TO SKETCH PLAN

VEHICLE IS IN THE WORKSHOP. PLS ARRANGE FOR SURVEY. THANK YOU -SANDRA

Present Location:

K KIM HIN AUTO PTE LTD (HQ)

COST OF CLAIMS

Parts Miscellaneous Items

Labour

Paintwork Labour

Towing

6.280.00 Gross Total (S\$)

30.107.45 + GST 7.00% (S\$) 2,107.52 Nett Amount (S\$) 32,214,97

This claim is handled by: SANDRA KHONG YEE TENG

Generaled using Merimen e-Claims internet Estimation & Adjusting System

(Last Synchronised 26 Aug 2020) -, 13. NIA Labour: Repairer's

NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database) Print Code: (Unsubmitted, no print-code for GX892H)

Validity:

These estimates are valid only if they contain the print code (above) on all estimates Further Info: Items

Ēs	timates on	values not in reference catalogue are prefixed with an asterisk.	mate pages, running pa	age number	's with the
0.	Qty Part No.	Particulars			
	2	*FRONT BUMPER C/W REINFORCEMENT *FRONT BUMPER BRACKET LUC-			
	1	*FRONT BUMPER BRACKET LH/RH	%Disc	%Depr	
	1	. IVON I COM ILL LARD		- opi	Amount
	1	FRONT GPILE	A 0.00	0.00	*520.00
	10		Ber 0.00	0.00	*520.001
	1	FRONT GRILLE CLIPS	1 0.00	0.00	*120.00 F
	1	FRONT GRILLE BUILD	217 0.00	0.00	*255.00 F
	1	*FRONT GRILLE INNER CROSS MEMBER *N/S HEADLAMP ASSY	B 0.00	0.00	*40.00 F
1	•	*N/S HEAD! AND	ng 0.00	0.00	*60.00 8
	•	*N/S HEADLAMP LOWER APRON GARNISH	0.00	0.00	*30.00 F
	1	*FRONT PANEL	cm 0.00	0.00	*250.00 F
		*FRONT PANEL CABSTAR EMBLEM *FRONT WIPER PANEL	bi 1 0.00	0.00	*65.00 F
		*FRONT WIDER	R 0.00	0.00	*640.00 F
	1	*FRONT WIPER PANEL LOWER MOULDING *N/S FRONT CORNER PANEL	May 0.00	0.00	*35.00 F
	1	*N/S FRONT CORNER PANEL	, 0.00	0.00	*340.00 F
,	1	*N/S FRONT CORNER PANEL *N/S WINGMIRPOR STATE	3 0.00	0.00	*35.00 F

*N/S FRONT CORNER PANEL BRACKET *N/S WINGMIRROR STAY 17 0.00 1 0.00 *N/S WINGMIRROR OUTER GARNISH *200.00 F 0.00 18 0.00 *125.00 F L *N/S WINGMIRROR STAY CAP COVER 0.00 19 0.00 1 414 145.00F 4 *N/S WINGMIRROR STAY INNER COVER 0.00 20 0.00 1 cm *95.00 F • *FRONT WINDSCREEN GLASS 0.00 0.00 21 1 *24.00 F & *FRONT WINDSCREEN GLASS LOWER MOULDING 0.00 0.00 22 2 *24.00 F *FRONT WINDSCREEN GLASS SIDE MOULDING LH/RH 0.00 0.00 *680.00F 23 2 *FRONT WIPER ARM LH/RH 0.00 0.00 *35.00 F 24 2 0.00 *FRONT WIPER BLADE LH/RH 0.00 *130.00 F Act 0.00 25 1 *FRONT WIPER LINKAGE 0.00 190.00F + ar 0.00 26 *FRONT WIPER MOTOR 0.00 *70.00 F 27 0.00 0.00 *N/S DOOR A PILLAR - OUTER *95.00F -0.00 28 *N/S DOOR INNER STEP PANEL 0.00 R 0.00 '350.00F ? 29 *N/S DOOR INNER UPPER PILLAR 0.00 *940.00F -0.00 0.00 30 '165.00F ? *N/S FRONT DOOR 0.00 0.00 31 Bu 0.00 *285.00 F 7 *N/S FRONT DOOR SIGNAL LAMP 0.00 *680.00F -32 2 *N/S FRONT DOOR HINGES (TOP/LOWER) MIY 0.00 0.00 *35.00 F L 33 RT 0.00 *N/S FRONT DOOR CHECKER 0.00 *100.00 F . 34 D.1 0.00 *N/S FRONT DOOR STEP GARNISH 0.00 *45.00 F -35 CM 0.00 *N/S FRONT DOOR STEP GARNISH BRACKET 0.00 120.00 F L 36 *N/S FRONT DOOR LOCK 0.00 0.00 *135.00 F Ta 0.00 37 *N/S FRONT DOOR LOCK CATCH 0.00 *130.00F L 38 *N/S FRONT DOOR WEATHERSTRIP 0.00 0.00 '30 00 F DULLA 39 0.00 *N/S FRONT DOOR FRAME WEATHERSTRIP 0.00 100.00 F 0.00 40 0.00 *N/S FRONT DOOR OUTER MOULDING *95.00 F Buc 0.00 0.00 41 *N/S FRONT DOOR INNER MOULDING *90 00 F 0.00 0.00 42 '55.00 F *N/S FRONT DOOR REGULATOR 0.00 0.00 *95.00 = 43 'N/S FRONT DOOR REGULATOR MOTOR 74 000 0.00 *340 00 F 44 *N/S FRONT DOOR LOWER SEAL D11 0.00 0.00 *30 00 F 'N/S FRONT DOOR INNER TRIMBOARD 45 Bur 000 0.00 1420.00 F *N/S FRONT DOOR INNER ARCH PANEL GARNISH 46 0.00 0 00 *80.00 = 7 *DASHBOARD TOP - LH 17 0 00 000 *300 JO = *DASHBOARD TOP - CENTRE 13 0.00 0.00 .300 00 =

Report was unsubmitted during this print-out Generated using Merimen a-Claims IEAS

		After -		¥.			
		Particulars			%Disc	%Depr	Amount
-	1	DASHBOARD TOP - RH			0.00	0.00	*300.00 F *
51		DASHBOARD TOP TOP INNER			0.00	0.00	*350.00 F 7
52		'NIS DASHBOARD TOP SIDE COVER			0.00	0.00	*60.00 F 7
53		*N/S DASHBOARD LOWER COVER			0.00	0.00	*120.00 F ?
54	1	'N'S DASHBOARD LOWER LID GLOVE BOX			0.00	0.00	145.00 F ?
55	,	MIS DASHBUARD CUP HOLDER FINISHED			0.00	0.00	*70.00 F 7
56	1	UASHBOARD CENTRE LOWER CARNIEL			0.00	0.00	*220.00 F 7
57	,	DASHBOARD CENTRE LOWER GLOVE BOY			0.00	0.00	*150.00 F 7
58	2	DASHBOARD REINFORCEMENT			0.00	0.00	*480.00 F 7
59	2	*FRONT CABIN MOUNTING BUSH			0.00	0.00	*110.00 F 7
60	1	"REAR CABIN MOUNTING			0.00	0.00	*100.00F 7
61		*FRONT CABIN TILT SHAFT		12,	0.00	0.00	*450.00 F
62		FRONT CABIN TILT INNER SHAFT		7	0.00	0.00	
63	1	FRONT CABIN TILT STAY			0.00	0.00	*295.00 F 7
64	,	*CABIN TILT OUTER PULL LEVER			0.00	0.00	120.00 F 7
65	2	"CABIN TILT OUTER PULL LEVER LINKAGE			0.00	0.00	*145.00 F 7
66	1	FRONT CABIN MOUNTING BRACKET I HIPH		710	0.00	0.00	*90.00 F 7
67		AIR CON CONDENSER			0.00	0.00	*390.00F
68	1	*AIR CON FAN ASSY			0.00		*550.00F 7
The state of	1	*AIR CON LIQUID PIPE			0.00	0.00	*380.00 F 7
69 70	1	*AIR CON DISCHARGE PIPE		R	0.00		*210.00 F
71	1	*AIR CON DRYER RECEIVER		3	0.00	0.00	*230.00F
72	1	*AIR CON SUCTION PIPE		n	0.00	0.00	*135.00 F
	1	*AIR CON BLOWER			0.00	0.00	125.00 F
73 74	1	*AIR CON COOLING COIL			0.00	0.00	'480.00F 7
	1	*AIR CON COOLING COIL INLET HOSE			0.00	0.00	1,150.00F 7
75	1	*AIR CON COOLING COIL OUTLET HOSE			0.00	0.00	'70.00 F 7
76	1	*AIR CON HEATER UNIT			0.00	0.00	*70.00 F 7
77	1	*TURBO COOLER			0.00	0.00	*820.00 F 7
78	1	*RADIATOR ASSY			0.00	0.00	*1,450.00 F 7 *580.00 F 7
79	1	*RADIATOR FAN BLADE			0.00	0.00	
80	1	*RADIATOR FAN CLUTCH			0.00	0.00	'125.00 F 7
81	1	*RADIATOR FAN COWLING - TOP			0.00	0.00	*55.00 F 7
82	1	*RADIATOR FAN COWLING - LOWER			0.00	0.00	*55.00 F 7
83	2	*RADIATOR MOUNTING			0.00	0.00	170.00 F ?
84	2	*GEARBOX MOUNTING			0.00	0.00	180.00F 7
85	1	*REAR VIEW MIRROR		Lin	0.00	0.00	
	1	*FRONT NUMBER PLATE		J	م ٥	0.00	195.00 F
87	1	*FRONT PANEL HEAT INSULATION			0	0.00	
88	1	*FRONT WINDSCREEN GLASS SEALANT	Men	405	~ 0	0.00	150.00FS 7
89	1	FRONT WINDSCREEN GLASS DAMPING SEAL	na		0	0.00	*20.00FS -
90		*ERP BRACKET		1	er o	0.00	26.00FS
91		'N/S FRONT DOOR INNER SPEAKER			0	0.00	120.00FS 7
92	1	*N/S FRONT DOOR ROC STICKER		~	ec o	0.00	*25.00 FS

'48.00 FS 7 Sub Total (S\$) 20,782.00 + Margin on L,N Items 15.00% (S\$) 3.045.45 Total Parts (S\$) 23,827.45

0.00

*25.00 FS .

Report was unsubmitted during this print-out, Generated using Merimen e-Claims IEAS

93

F=Franchise part. S=SpcNett.

*RADIATOR COOLANT



Estimates on Labour

No	Particulars	Lab.Type	Amount
Labe	our Items		16001
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS	New	2,000.00
	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAV TEST	New	100.00
	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUM AND RECHARGE GAS TO REMOVE DOORS FITTINGS	New	60/ 80.00
	TO CHECK AND REALIGNMENT ON CHASSIS MEMBER	New	- 00.00
	TO REMOVE AND RENEW FRONT INSTRUMENT PANEL ASSY, TO REWIRING AND TRANSFER INSTRUMENT FITTINGS	New New	7 9 0 1,600.00 2501 280.00
	TO REMOVE FRONT BRAKE BOOSTER, BRAKE MASTER PUMP AND STEERING COLUMN TO CONDUCT FRONT WHEEL ALIGNMENT TEST	New	GOL 120.00
	TO REMOVE AND REFIT FRONT SEAT ASSY TRIMBOARD AND CARPET TO FACILITATE REPARING WORKS	New New	80.00 801 120.00
)	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	12001 1,800.00
	Gross Labou	r Cost (S\$)	6,280.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >

Owner ID: Company 270E Owner ID: GX892H Vehicle Details No Vehicle No.: 24 Aug 2020 Vehicle to be Exported: CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 Intended Deregistration Date: Vehicle Make: White Vehicle Model: 2016 Primary Colour: ZD30013934N Manufacturing Year: JN15C2F24Z0858936 Engine No.: Chassis No.: \$24,942.00 Maximum Power Output: 28 Jul 2016 Open Market Value: 28 Jul 2016 Original Registration Date: First Registration Date: \$1,248.00 Transfer Count: Actual ARF Paid: No Intended PARF Rebate Details PARF Eligibility: \$0.00 PARF Eligibility Expiry Date: PARF Rebate Amount: 27 Jul 2026 Intended COE Rebate Details C - Goods Vehicle & Bus COE Expiry Date: 10 COE Category: \$33,389.00 COE Period(Years): \$19,782.00 PQP Paid: \$19,782.00 COE Rebate Amount: The information contained herein is correct as at 24 Aug 2020

ОК

MV 36800