

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 26/08/2020

To : ALLIED WORLD ASSURANCE COMPANY, LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LIM FUI FONG

: AXA INSURANCE PTE LTD

Certificate No : P2044701

Accident Date : 22/08/2020

Vehicle No : SLU-6453-J

Make & Model : HYUNDAI ELANTRA AD 1.6 GLS AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	REAR BUMPER <i>fora</i> ✓	498.10	✓
1	REAR BUMPER REINFORCEMENT <i>bt</i> ✓	394.80	✓
2	REAR BUMPER REFLECTOR <i>scr</i> ✓	135.80	✓
2	REAR BUMPER RETAINER <i>rec</i> ✓	124.20	✓
10	REAR BUMPER CLIPS <i>rec</i> ✓	50.00	✓
1	END PANEL <i>bt</i> ✓	579.60	✓
1	END PANEL TOP GARNISH <i>de</i> ✓	141.60	✓
1	SPARE TYRE BOARD <i>X Svc</i>	296.40	X
2	TAILLAMP RH/LH <i>con</i> ✓	785.20	✓

Date : 26/08/2020

To : ALLIED WORLD ASSURANCE COMPANY, LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LIM FUI FONG
: AXA INSURANCE PTE LTD

Certificate No : P2044701

Accident Date : 22/08/2020

Vehicle No : SLU-6453-J

Make & Model : HYUNDAI ELANTRA AD 1.6 GLS AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
2	TAILLAMP PANEL RH/LH <i>bt</i> ✓	386.20	✓
1	BOOT LID <i>bt</i> ✓	1,782.40	✓
1	BOOT LID LOGO <i>ner</i> ✓	59.10	✓
1	EMBLEM - ELANTRA <i>ner</i> ✓	61.20	✓
1	EMBLEM - S <i>ner</i> ✓	38.20	✓
1	BOOT LID WEATHERSTRIP <i>ner</i> ✓	162.50	✓
2	BOOT LID HINGE <i>? bt</i> ✓	288.60	✓
1	BOOT LID LOCK <i>bt</i> ✓	161.20	✓
1	BOOT LID LOCK STRIKER <i>bt</i> ✓	55.30	✓
2	BOOT LID LAMP RH/LH <i>bro</i> ✓	779.80	✓

Date : 26/08/2020

To : ALLIED WORLD ASSURANCE COMPANY, LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LIM FUI FONG
: AXA INSURANCE PTE LTD

Certificate No : P2044701

Accident Date : 22/08/2020

Vehicle No : SLU-6453-J

Make & Model : HYUNDAI ELANTRA AD 1.6 GLS AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
2	REAR NUMBER PLATE LAMP ? Xsrc	128.40	X
1	REAR VIEW CAMERA ? Xsrc	525.50	X
1	REAR FENDER RH bue /	1,768.30	✓
1	REAR FENDER LH bue /	1,768.30	✓
1	REAR WINDSCREEN GLASS ? photo XAA	817.20	X
1	REAR WINDSCREEN MOULDING neu /	98.20	✓
1	REAR FENDER INNER TRIM RH de /	247.90	✓
1	REAR FENDER INNER TRIM LH de /	247.90	✓
1	SPARE TYRE PANEL RESTORE		

Date : 26/08/2020

To : ALLIED WORLD ASSURANCE COMPANY, LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LIM FUI FONG

: AXA INSURANCE PTE LTD

Certificate No : P2044701

Accident Date : 22/08/2020

Vehicle No : SLU-6453-J

Make & Model : HYUNDAI ELANTRA AD 1.6 GLS AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	10614.40	12381.90
	Discount 20% On Parts	20%	(2476.38)
	<u>Special Nett Item</u>	8491.52	
1	REVERSE SENSOR <i>rw</i>	220.00	<i>✓</i>
1	REAR NUMBER PLATE <i>bl</i>	35.00	<i>✓</i>
1	REAR WINDSCREEN SEALANT <i>rw</i>	50.00	<i>✓</i>
1	END PANEL SEALANT <i>rw</i>	50.00	<i>✓</i>
	Sub Total	355.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	1,980.00	<i>1500 1600</i>

Date : 26/08/2020

To : **ALLIED WORLD ASSURANCE COMPANY, LTD**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : LIM FUI FONG

: AXA INSURANCE PTE LTD

Certificate No : P2044701

Accident Date : 22/08/2020

Vehicle No : SLU-6453-J

Make & Model : HYUNDAI ELANTRA AD 1.6 GLS AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO RESPRAY AFFECTED AREAS	1,500.00	1200 ✓
	TO PULL AND STRAIGHTEN REAR CHASSIS PANEL	400.00	200 ✓
	TO REMOVE AND TRASFER BOOT LID COMPONENTS	200.00	80 ✓
	TO REMOVE AND REFIT REAR WINDCSREEN GLASS	120.00	✓
	TO REMOVE AND REFIT REAR SEATS AND FITTINGS TO ASSIST REPAIR	200.00	80 ✓
	RUST PROOFING	100.00	50 ✓
	TOWING CHARGES	50.00	✓
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	50.00	✓
			3430

Date : 26/08/2020

To : ALLIED WORLD ASSURANCE COMPANY, LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LIM FUI FONG

: AXA INSURANCE PTE LTD

Certificate No : P2044701

Accident Date : 22/08/2020

Vehicle No : SLU-6453-J

Make & Model : HYUNDAI ELANTRA AD 1.6 GLS AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	4600.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Remarks:

(12 days / p/p) (Resurvey before paint)

~~11,860.52~~ 15,145.32

SUB TOTAL

GST 7.0 %

1,040.24

TOTAL

15,900.76

Surveyor's name:

Rasul - Hp 90010068

Principal's name:

LIM FUI FONG

Survey Date & Time:

26/08/2020 @ 1635

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 06/10/2020

To : **ALLIED WORLD ASSURANCE COMPANY, LTD**
SUPPLEMENTARY

Attn : **Motor Claim Department**

FAX :

Owner : LIM FUI FONG

: AXA INSURANCE PTE LTD

Certificate No : P2044701

Accident Date : 22/08/2020

Vehicle No : SLU-6453-J

Make & Model : HYUNDAI ELANTRA AD 1.6 GLS AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	BOOT LID TRIM <i>de</i>	268.00	/
2	REAR BUMPER BEAM BRACKET <i>cm</i>	58.00	/
2	TAILLAMP CLIP <i>ne</i>	30.00	/
Sub Total		356.00	356
Discount 20% On Parts		(71.20)	20%
			284.80
		284.80	

Remarks:

SUB TOTAL

GST 7.0 % 19.94

TOTAL 304.74

Surveyor's name: _____

Principal's name: LIM FUI FONG

Survey Date & Time: _____

PAGE :