



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA20009031/R1sf3e2

(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Date : 03-09-2020



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 4883L	Veh. Inspected	SLU 6453J
Policy No.	BVFCB0007172013	Coverage (\$)	0.00
Claim No.	NSV2000240/PC	Excess (\$)	0.00
Assign From	STELLA GOH	Assign Date	26/08/2020

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI ELANTRA 1.6 GLS	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KMHD841CMJU591182	Colour	GREY
Odometer	41955	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45Z R17	FALKEN	6 mm
L/H Front Tyre	225/45Z R17	FALKEN	6 mm
R/H Rear Tyre	225/45Z R17	FALKEN	6 mm
L/H Rear Tyre	225/45Z R17	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/08/2020	Inspection Date	26/08/2020
Survey held at	ETHOZ GROUP LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075		

5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	------------------------