LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

From:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park

Singapore 408933

Attn:

Azlan, Syazairdina

Date:

27 Aug 2020

Preliminary Advice

Vehicle No

Make

: SLN1854E

: AUDI A6

Accident Date

: 20/08/2020

Assignment Date

: 26/08/2020

Policy No.

: 2100508434

Date of Inspection

Excess

:\$\$

: 26/08/2020

Est. Duration of Repair

: S\$0.00 : 3

Inspection At

: PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1

SINGAPORE 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Described and the		
Repairer's Estimate (Gross)	:S\$	13,145.00
Revised Amount	:S\$	4.973.00
Check Items (Estimated)	:S\$	520.00
Total	:S\$	
	.5\$	5,493.00

Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	68,701.00
Salvage Value	:S\$	50,701.00
Margin for Repair	:S\$	36,299.00

Remarks

(X))	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: