

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20009035/KES3Q2
Date: 19/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100431277	
Claimant Vehicle No :	SHC5624G	Insured Vehicle No :	SGA1466U	
Date of Loss:	22/08/2020	Nature of Claim:	TP	Claim No: 5090672868SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5624G		
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Engine No:	M9R8839C002180
Reg. Date:	19/11/2014 (Man. Year: 2014)	Chassis No:	VF1ABL15AUC280293
Colour:	Metallic White/Red	Odometer:	643779 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 8 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,394.39	4,419.65	14,974.74	77.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,740.00	1,520.00	5,220.00	77.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,134.39	5,939.65	20,194.74	77.27
Approved Total (Overridden) (S\$)		4,750.00		

(S\$)	26,134.39	4,750.00	21,384.39	81.82
+ GST 7.00/7.00% (S\$)	1,829.41	332.50	1,496.91	81.82
Nett Amount (S\$)	27,963.80	5,082.50	22,881.30	81.82
+ Car Rental (6.5 x S\$95.04/day) (S\$)		617.76		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,707.71		
Global Sum Settlement (S\$)		5,700.00		

INSPECTION

Date of Assignment: 25/08/2020

Date Inspected: 25/08/2020

Estimated Period of Repair: 5.0 days

Inspected At:

Trans-cab Auto Services Pte Ltd
 No 2 Ang Mo Kio Street 63
 Singapore 569111

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	16.60 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
9	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
10	1		*BUMPER BEAM BRACKET RH REAR	Bent	114.50 FL	*114.50 FL
11	1		*BOOT REAR	Bent	1,677.20 FL	*1,677.20 FL
12	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
13	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*- FL
14	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	*- FL
15	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*- FL
16	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
17	1		*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
18	1		*BOOT STRUT	Serviceable	145.10 FL	*- FL
19	1		*BOOT HINGE	Repair	254.20 FL	*- FL
20	1		*BOOT LOCK	Repair	246.60 FL	*- FL
21	2		*BOOT RUBBER PLUG	Serviceable	139.30 FL	*- FL
22	2		*LICENCE PLATE LAMP	Serviceable	26.30 FL	*- FL
23	1		*BOOT TRIM BOARD	Serviceable	611.00 FL	*- FL
24	1		*TAILLAMP RH	Mtg Cracked	401.40 FL	*401.40 FL
25	1		*TAILLAMP PANEL	Repair	401.40 FL	*- FL
26	1		*TAILLAMP LH	Serviceable	401.40 FL	*- FL
27	1		*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	*745.80 FL
28	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
29	1		*SPARE TYRE BOARD	Serviceable	680.90 FL	*- FL
30	1		*EXHAUST REAR	Repair	5,263.60 FL	*- FL
31	1		*EXHAUST CAP REAR	Repair	125.40 FL	*- FL
32	1		*FENDER PANEL REAR RH	Repair	1,933.20 FL	*- FL
33	1		*WHEELARCH REAR RH	Serviceable	275.40 FL	*- FL
34	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
35	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SET REAR BUMPER CLIP	Necessary	75.00 FS	*75.00 FS
37	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	65.00 FS	*- FS
38	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	65.00 FS	*- FS
39	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	60.00 FS	*- FS
40	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	65.00 FS	*- FS
41	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	60.00 FS	*- FS
42	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	70.00 FS	*- FS
43	1		*SET BUMPER LOWER REAR CLIP	Necessary	75.00 FS	*75.00 FS
44	2		*SEAM SEALANT	Not Necessary	180.00 FS	*- FS
45	1		*SET BOOT FINISHER CLIP	Not Necessary	55.00 FS	*- FS
46	1		*BOOT STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
47	1		*BOOT STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
48	1		*BOOT TRIM BOARD CLIP	Not Necessary	60.00 FS	*- FS
49	1		*RENAULT TYRE RIM (ROUE 7J 16H)	Serviceable	385.00 FS	*- FS
50	1		*RENAULT TYRE 215/60/16	Serviceable	330.00 FS	*- FS
51	1		*TAILLAMP CLIP RH	Necessary	40.00 FS	*5.00 FS
52	1		*TAILLAMP CLIP LH	Not Necessary	40.00 FS	*- FS
53	1		*REAR BUMPER PROTECTOR	Necessary	190.00 FS	*30.00 FS
54	1		*SET REAR LICENCE PLATE WITH HOLDER	Serviceable	140.00 FS	*- FS
55	1		*SET END PANEL TRIM CLIP	Not Necessary	55.00 FS	*- FS
56	1		*SET FENDER PANEL INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
57	1		*SET WHEELARCH RR CLIP	Not Necessary	65.00 FS	*- FS
58	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
59	2		*REAR WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
60	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	21,163.21	4,883.50
- List Item Discount on L Items 10.00/10.00% (\$)	1,768.82	463.85
Total Parts (\$)	19,394.39	4,419.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	60.00
2	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
3	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,800.00	600.00
5	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
6	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	60.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	660.00
9	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
10	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
12	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
13	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
14	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
15	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
16	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
Gross Labour Cost (\$\$)			6,740.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >