

Not Authored
1/Sing B

Trans-cab Auto Services Pte Ltd

AAD2008-103

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5624G

Vehicle No.:
Chassis No.: **25 AUG 2020**
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHC 5624G
VF1ABL15AUC280293
RENAULT
LATITUDE
22.8.2020
AIG
19/11/2014

	PART		LIST	
1	BUMPER COVER REAR	\$	Bu 561.70	✓
1	BUMPER LOWER REAR	\$	Bu 411.90	✓
1	BUMPER BRACKET CTR REAR	\$	SL 98.10	X
1	BUMPER BRACKET SIDE RH REAR	\$	SL 82.10	X
1	BUMPER RETAINER RH REAR	\$	SL 59.80	X
1	BUMPER REFLECTOR RH	\$	SL 16.60	X
1	BUMPER BRACKET SIDE LH REAR	\$	SL 80.80	X
1	BUMPER RETAINER LH REAR	\$	SL 54.20	X
1	BUMPER BEAM REAR	\$	Bu 547.80	✓
1	BUMPER BEAM BRACKET RH REAR	\$	Bu 114.50	✓
1	BOOT REAR	\$	Bu 1,677.20	✓
1	BOOT FINISHER	\$	SL 344.70	X
1	BOOT WHEATERSTRIP	\$	SL 178.20	X
1	BOOT REFLECTOR LAMP LH	\$	SL 277.70	X
1	BOOT REFLECTOR LAMP RH	\$	SL 277.70	X
1	BOOT BADGE 'RENAULT'	\$	SL 82.40	✓
1	BOOT BADGE	\$	SL 95.80	✓
1	BOOT STRUT	\$	SL 145.10	X
1	BOOT HINGE	\$	R 254.20	X
1	BOOT LOCK	\$	R 246.60	X
2	BOOT RUBBER PLUG	\$	SL 139.30	X
2	LICENCE PLATE LAMP	\$	SL 26.30	X
1	BOOT TRIM BOARD	\$	SL 611.00	X
1	TAILLAMP RH	\$	Mgmt 401.40	✓
1	TAILLAMP PANEL	\$	R 401.40	X
1	TAILLAMP LH	\$	SL 401.40	X

Trans-cab Auto Services Pte Ltd

AAD2008-103

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5624G

1	OUTER PANEL REAR (End Panel)	\$	Pr	745.80	✓
1	OUTER PANEL REAR (End Panel) TRIM	\$	Pr	404.56	} X
1	SPARE TYRE BOARD	\$	Sm	680.90	
1	EXHAUST REAR	\$	Pr	5,263.60	
1	EXHAUST CAP REAR	\$	Pr	125.40	
1	FENDER PANEL REAR RH	\$	Pr	1,933.20	
1	WHEELARCH REAR RH	\$	Sm	275.40	
1	FENDER PANEL INNER TRIM REAR RH	\$	Sm	671.45	
	TOTAL	\$		17,688.21	
	10%	\$		1,768.82	
		\$		15,919.39	

Special Nett

1SET	PARKING AID	\$	Pr	700.00	X
1SET	REAR BUMPER CLIP	\$	Pr	75.00	✓
1SET	BUMPER BRACKET CTR CLIP	\$	Nu	65.00	X
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	Nu	65.00	X
1SET	BUMPER RETAINER RH CLIP RR	\$	Nu	60.00	X
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	Nu	65.00	X
1SET	BUMPER RETAINER CLIP LH RR	\$	Nu	60.00	X
1SET	BUMPER LOWER REAR RIVET	\$	Nu	70.00	X
1SET	BUMPER LOWER REAR CLIP	\$	Nu	75.00	✓
2	SEAM SEALANT	\$	Nu	180.00	X
1SET	BOOT FINISHER CLIP	\$	Nu	55.00	X
1	BOOT STICKER "Trans-cab"	\$	Nu	80.00	305n
1	BOOT STICKER "6555-3333"	\$	Nu	80.00	305n
1	BOOT TRIM BOARD CLIP	\$	Nu	60.00	X
1	RENAULT TYRE RIM (ROUE 7J 16H)	\$	Pr	385.00	X
1	RENAULT TYRE 215/60/16	\$	Pr	330.00	X
1	TAILLAMP CLIP RH	\$	Nu	40.00	5.005n
1	TAILLAMP CLIP LH	\$	Nu	40.00	X
1	Rear Bumper Protector	\$	Nu	190.00	305n
1SET	Rear licence plate with holder	\$	Pr	140.00	X
1SET	END PANEL TRIM CLIP	\$	Nu	55.00	X

Trans-cab Auto Services Pte Ltd

AAD2008-103

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5624G

1SET FENDER PANEL INNER TRIM CLIP	\$	<i>nn</i>	60.00	} X
1SET WHEELARCH RR CLIP	\$	<i>nn</i>	65.00	
1 WINDSCREEN MOULDING	\$	<i>nn</i>	200.00	
2 REAR WINDSCREEN SEALANT	\$	<i>nn</i>	150.00	
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	130.00	
TOTAL	\$		3,475.00	
TOTAL PARTS			\$	19,394.39

LABOUR

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$		380.00	<i>bol</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$		170.00	<i>bol</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i>	170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,800.00	<i>bol</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i>	380.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$		250.00	<i>bol</i>
Putty And Spray Painting Of The Affected Portion.	\$		1,800.00	<i>bol</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO/GST Reg. No. 201019626G

SHC 5624G

AAD2008-103

To reinstall rear bumper parking sensor.	\$	170.00	601	
To Check Electrical Lighting Concerned.	\$	170.00	201	
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00		X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00		X
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	170.00		X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00		X
To check steering geometry and computer wheel alignment	\$	220.00		X
TOTAL	\$	6,740.00		
Over All Total	\$	26,134.39		

(LUMP SUM) Repair Days

~~20 DAYS~~
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: