



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2007333
INV Date 03/11/2020
Reference CC4/FCI20009040/R1ds3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SHB 3670R
Insured Veh. SHC 7689G
Claim No. D20003378MFSH/1
Policy No. D-20094921MFSH
Accident Date 23/08/2020
Inspection Date 26/08/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20009040/R1ds3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 03-11-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7689G	Veh. Inspected	SHB 3670R	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20003378MFSH/1	Excess (\$)	0.00	
Assign From	ERIC	Assign Date	26/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS HYBRID 1.8 CVT	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU503562781	Colour	YELLOW	
Odometer	386224	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	TAKSING	6 mm	
L/H Front Tyre	195/65 R15	TAKSING	6 mm	
R/H Rear Tyre	195/65 R15	TAKSING	6 mm	
L/H Rear Tyre	195/65 R15	TAKSING	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	23/08/2020	Inspection Date	26/08/2020	
Survey held at	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 3670R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	466.50	-
1	REAR BUMPER TOW CAP	CUT	23.49	23.49
1	REAR BUMPER DIFFUSER	DEFORMED	582.30	582.30
	LESS 25% DISCOUNT		-268.07	-151.45
			804.22	454.34
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIPS (SN)	NOT NECESSARY	45.00	-
1	REAR BUMPER PROTECTOR PAD (SN)	NOT NECESSARY	120.00	-
1	SET REVERSE SENSOR (SN)	SERVICEABLE	240.00	-
			405.00	-
	<u>LABOUR</u>			
	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		800.00	200.00
	RESPRAY REAR BUMPER.		250.00	200.00
	RESPRAY REAR BUMPER DIFFUSER.	NOT NECESSARY	250.00	-
	RESPRAY REVERSE SENSOR SET.	NOT NECESSARY	150.00	-
	R&R REVERSE SENSOR AND CHECK WIRING CONNECTION.	NOT NECESSARY	100.00	-
			1,550.00	400.00
	GRAND TOTAL		2,759.22	854.34
RECOMMENDED COST OF REPAIRS				854.34

Report Ref No. CC4/FCI20009040/R1ds3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 3670R

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 3670R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

